



Blk 503B Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7828 Website: www.esteemperf.com.sg

Repair Estimates

PC 1533 S

*Not Authorized*  
*61 Lapp Q?*  
*Ministry After Policy*

Parts (a) Cost / List Price Items \_\_\_\_\_  
Plus/Less \_\_\_\_\_  
Total of Cost / List \_\_\_\_\_  
(b) Nett Price Items \_\_\_\_\_  
Less \_\_\_\_\_  
Total of Nett Item \_\_\_\_\_  
(c) Special Nett Items \_\_\_\_\_  
Total Parts Cost \_\_\_\_\_  
Labour \$ 2,700.00  
Total \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

*Q 4086.80*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : *Ministry*  
Company : *LKK*  
Survey conducted on : *11/12/18* at \_\_\_\_\_  
Remarks By Surveyor  
(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.  
(b) Recommended Days of Repair : *06* day(s)  
(c) Resurvey : Required / ~~Not Required~~  
(d) Excess : \$ \_\_\_\_\_  
(e) Signature of surveyor : *Le* Date: *11/12/18*



**ESTEEM  
PERFORMANCE**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperi.com

**Spare Parts**

Vehicle No. : \_\_\_\_\_  
Make & Model : **PC 1533 S**  
Chassis No : **TOYOTA HIACE**  
**JTFST22P6000015776**

Submit By : \_\_\_\_\_  
Year Manufacture : \_\_\_\_\_  
Engine No. : \_\_\_\_\_  
**Cost / List**

| S/No. | Part Description                        | Qty | Unit Price | Price |
|-------|-----------------------------------------|-----|------------|-------|
| 1     | Front number plate <i>mit</i>           | 1   | \$45.00    | S.N ✓ |
| 2     | Front number plate garnish <i>NIP</i>   | 1   | N/A        | X     |
| 3     | Bonnet <i>Ry</i>                        | 1   | >10        | ✓     |
| 4     | Bonnet lock <i>R</i>                    | 1   | 35         | X     |
| 5     | Bonnet emblem <i>Nm</i>                 | 1   | 25         | ✓     |
| 6     | Bonnet heat insulator <i>NIP</i>        | 1   | N/A        | X     |
| 7     | Bonnet heat insulator clip <i>NV</i>    | 10  | N/A        | X     |
| 8     | Bonnet hinge LH <i>Di'l</i>             | 1   | 29         | ✓     |
| 9     | Bonnet hinge RH <i>Ry</i>               | 1   | 29         | ✓     |
| 10    | Headlamp LH <i>mit Ry</i>               | 1   | 200        | ✓     |
| 11    | Headlamp RH <i>Ry</i>                   | 1   | 200        | ✓     |
| 12    | Headlamp clip <i>NV Ry</i>              | 10  | 1.50       | X     |
| 13    | Headlamp LH Socket <i>PUK</i>           | 1   | TBA        | X     |
| 14    | Headlamp RH Socket <i>PUK</i>           | 1   | TBA        | X     |
| 15    | RH Corner panel <i>Ry</i>               | 1   | 60         | ✓     |
| 16    | Front support panel completed <i>R</i>  | 1   | 130        | X     |
| 17    | Front bumper <i>mit</i>                 | 1   | 185        | ✓     |
| 18    | Front bumper clip <i>NV Ry</i>          | 10  | 1.50       | X     |
| 19    | Front bumper reinforcement <i>Ry</i>    | 1   | 70         | ✓     |
| 20    | Front bumper beam <i>Ry</i>             | 1   | 80         | ✓     |
| 21    | Front bumper side retainer LH <i>CM</i> | 1   | 50         | ✓     |
| 22    | Front bumper side retainer RH <i>CM</i> | 1   | 50         | ✓     |
| 23    | Front bumper bracket LH <i>R</i>        | 1   | 38         | X     |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

**Spare Parts**

Vehicle No. : \_\_\_\_\_ **PC 1533 S**

Submit By : \_\_\_\_\_

Make &amp; Model :

TOYOTA HIACE

Year Manufacture :

Chassis No :

JTFST22P6000015776

Engine No. :

Cost / List

| S/No. | Part Description                       | Qty | Unit Price | Price |
|-------|----------------------------------------|-----|------------|-------|
| 24    | Front bumper bracket RH <i>R</i>       | 1   | 38         | X     |
| 25    | Front bumper upper grille <i>cm</i>    | 1   | 175        | ✓     |
| 26    | Front bumper lower grille <i>Arr 2</i> | 1   | 90         | ✓     |
| 27    | Air Filter Box <i>Br 2</i>             | 1   | 230        | ✓     |
| 28    | Condenser <i>Sm</i>                    | 1   | 480        | X     |
| 29    | Condenser fan motor <i>Sm</i>          | 1   | 360        | X     |
| 30    | Condenser fan blade <i>Sm</i>          | 1   | 50         | X     |
| 31    | Condenser fan cowling <i>Sm</i>        | 1   | 100        | X     |
| 32    | Radiator <i>Sm</i>                     | 1   | 620        | X     |
| 33    | Radiator fan motor <i>Sm</i>           | 1   | 360        | X     |
| 34    | Radiator fan blade <i>Sm</i>           | 1   | 40         | X     |
| 35    | Radiator fan cowling <i>Sm</i>         |     | 100        | X     |
| 36    | Coolant <i>nn</i>                      | 1   | \$20.00    | S.N X |
| 37    | "Green" Sticker <i>nn</i>              | 1   | \$20.00    | S.N   |
| 38    | RH front door <i>R R</i>               | 1   | 600        | X     |
| 39    |                                        |     |            |       |
| 40    |                                        |     |            |       |
| 41    |                                        |     |            |       |
| 42    |                                        |     |            |       |
| 43    |                                        |     |            |       |
| 44    |                                        |     |            |       |
| 45    |                                        |     |            |       |
| 46    |                                        |     |            |       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829  
Company Reg No. 200005485N / GST No. 20-0005485-N

**Spare Parts**

Vehicle No. :

PC 1533 S

Make &amp; Model :

TOYOTA HIACE

Chassis No :

JTFST22P6000015776

Submit By :

Year Manufacture :

Engine No. :

**Spare Parts**

Vehicle No. :

**PC 1533 S**

Submit By :

JENNY

Make &amp; Model :

T.HIACE

Year Manufacture :

2012

Chassis No. :

JTFST22P6000015776

Engine No. :

Cost / List

| S/No. | Part Description                 | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|----------------------------------|-----|------------|-------|-------------------------|
| 24    | Front windscreen                 | 1   | 450        |       | ✓                       |
| 25    | Front windscreen moulding        | 1   | 45         |       | ✓                       |
| 26    | Front windscreen sealant         | 1   | 50         |       | 4050 ✓                  |
| 27    | Front windscreen inner seal tape | 1   | N/A        |       | 3050 ✓                  |
| 28    | Front windscreen I.U. bracket    | 1   | N/A        |       | 2650 ✓                  |
| 29    |                                  |     |            |       |                         |
| 30    |                                  |     |            |       |                         |
| 31    |                                  |     |            |       |                         |
| 32    |                                  |     |            |       |                         |
| 33    |                                  |     |            |       |                         |
| 34    |                                  |     |            |       |                         |
| 35    |                                  |     |            |       |                         |
| 36    |                                  |     |            |       |                         |
| 37    |                                  |     |            |       |                         |
| 38    |                                  |     |            |       |                         |
| 39    |                                  |     |            |       |                         |
| 40    |                                  |     |            |       |                         |
| 41    |                                  |     |            |       |                         |
| 42    |                                  |     |            |       |                         |
| 43    |                                  |     |            |       |                         |
| 44    |                                  |     |            |       |                         |
| 45    |                                  |     |            |       |                         |
| 46    |                                  |     |            |       |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



BK 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 566535.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

# Labour

Vehicle No. : **PC 1533 S** Submit By : **Carmen Lim**  
Make & Model : **TOYOTA HIACE** Year of Manufacture : **2012**

| S/No | Labour Description                                                                                                               | Estimated Price | Adjusted Price |
|------|----------------------------------------------------------------------------------------------------------------------------------|-----------------|----------------|
| 1    | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, LHF CORNER PANEL,LHF DOOR,RHF DOOR) | \$1,000.00      | 600            |
| 2    | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (BONNET,FRONT BUMPER,SUPPORT PANEL, RHF CORNER PANEL,LHF DOOR,RHFDOR) | \$1,200.00      | 800            |
| 3    | To check wiring & focus headlamp                                                                                                 | \$50.00         | 20             |
| 4    | To remove & refit radiator, condenser to assist work load, to top up A/C gas. <i>nn</i>                                          | \$150.00        | X              |
| 5    | To do wheel alignment. <i>nn</i>                                                                                                 | \$120.00        | X              |
| 6    | To do art work. (RHF DOOR) <i>(Inferior)</i>                                                                                     | \$180.00        | X              |
|      |                                                                                                                                  |                 | 1420           |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

**ESTEEM PERFORMANCE PTE LTD**

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

**Spare Parts**

Vehicle No. :  
 Make & Model :  
 Chassis No. :

**PC 1533 S**

TOYOTA HIACE

JTFST22P6000015776

Submit By :  
 Year Manufacture :  
 Engine No. :  
**Cost / List**

**CARMEN LIM**  
 2012

**Supplementary**

| S/No. | Part Description           | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|----------------------------|-----|------------|-------|-------------------------|
| 1     | Fog lamp cover RH          | 1   | \$25.00    |       | ✓                       |
| 2     | Air Filter Box Top Ducting | 1   | \$55.00    |       | ✓                       |
| 3     | Tow cover LH               | 1   | \$10.00    |       | ✓                       |
| 4     | Tow cover RH               | 1   | \$10.00    |       | ✓                       |
| 5     |                            | 1   |            |       |                         |
| 6     |                            | 1   |            |       |                         |
| 7     |                            | 1   |            |       |                         |
| 8     |                            | 1   |            |       |                         |
| 9     |                            | 1   |            |       |                         |
| 10    |                            | 1   |            |       |                         |
| 11    |                            | 1   |            |       |                         |
| 12    |                            | 1   |            |       |                         |
| 13    |                            | 1   |            |       |                         |
| 14    |                            | 1   |            |       |                         |
| 15    |                            | 1   |            |       |                         |
| 16    |                            | 1   |            |       |                         |
| 17    |                            | 1   |            |       |                         |
| 18    |                            | 1   |            |       |                         |
| 19    |                            | 1   |            |       |                         |
| 20    |                            | 4   |            |       |                         |
| 21    |                            | 1   |            |       |                         |
| 22    |                            | 1   |            |       |                         |
| 23    |                            | 1   |            |       |                         |

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

100



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: [www.esteemperf.com.sg](http://www.esteemperf.com.sg)

Our Ref : CIV1302770

Your Ref : PC 1533 S

Date : 16 JAN 2020

AIG ASIA PACIFIC INSURANCE PTE.LTD  
AIG BUILDING  
78 Shenton Way  
#07-16 Singapore 079120

Attn : Motor Claims Department

Dear Sir/Mdm

**ACCIDENT INVOLVING ALONG CHANGI AIRPORT TERMINAL 1 E20**  
**POLICY NO : 999994313**

We refer to the above matter.

Attached, please find the following : -

1. Satisfaction Cum Discharge Voucher
2. Final Repair Bill
3. Singapore Accident Statement

Kindly forward us the cheque for **S\$1697.88** in favour of M/s Esteem Performance Pte Ltd as soon as possible.

Thank you.

Yours faithfully



# CERTIFICATE OF INSURANCE Pg. 1



HOTLINE TEL: (65) 6410-3000

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1989  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z. 400

|                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                      |                 |
|--------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|-----------------|
| Comprehensive Commercial Auto Plus                                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | (The below excess is subject to GST) |                 |
| CERTIFICATE NO.                                                                | 999994313                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            | POLICY EXCESS                        | S\$2,500.00 (i) |
|                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | WINDSCREEN EXCESS                    | S\$100.00       |
|                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | SUM INSURED                          | Market Value    |
|                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | INSURING WITH COE/PARF               | Yes             |
|                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | PC1533S                              |                 |
|                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | Goldball Car Rental Pte Ltd          |                 |
| 1) VEHICLE REGISTRATION NO.                                                    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                      |                 |
| 2) NAME OF POLICYHOLDER                                                        |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                      |                 |
| 3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 01 January 2019                      |                 |
| 4) DATE OF EXPIRY OF INSURANCE                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 31 March 2020                        |                 |
| 5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*                             | <p>Any person who is driving on the Insured's order or with their permission.<br/>Additional Excess of \$3,000 applies to drivers between below 23 years of age and/or with driving experience of less than 12 months.<br/>Additional excess of \$500 applies to all claims for accident outside Singapore.</p> <p>Provided that the person driving is permitted in accordance with the Licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> |                                      |                 |
| 6) LIMITATION AS TO USE*                                                       | <p>1) Use in connection with the Insured's business.<br/>2) Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.<br/>3) Use for social, domestic or pleasure purposes of any person to whom the vehicle is hired.</p> <p>The Policy does not cover</p> <p>a) Use for racing, pace-making, reliability trial or speed-testing.<br/>b) Use for the carriage of passengers for hire or reward<br/>c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.</p>                                                                    |                                      |                 |
| LOSS OF USE                                                                    | Not Included                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                      |                 |
| HIRE PURCHASE COMPANY                                                          | NA                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                      |                 |

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 28 Jan 2019

AIG Asia Pacific Insurance Pte. Ltd.

030123-000  
Acom International Network Pte Ltd  
48 Changi South St 1 Level 3  
SINGAPORE 488130

*M. Marib*

AUTHORISED REPRESENTATIVE

SSPTKY

ORIGINAL

AR 95285  
CA173939  
\$16000 (OP+TP)



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Date : 16.01.2020  
Our ref : CIV1302770

### Motor Vehicle Claim

### Owner's Satisfaction / Discharge Voucher

Name of vehicle's owner : GOLDBELL CAR RENTAL PTE LTD  
Motor policy no : 999994313  
Vehicle registration no : PC 1533 S  
Make & Model : TOYOTA HIACE  
Owner's Excess : S\$2500.00  
Accident Date : 03.12.2019  
Place : CHANGI AIRPORT TERMINAL 1 E20  
Repairer's Name : ESTEEM PERFORMANCE PTE LTD

I / We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner /Insured signature



*Henry*

Date & Time

: 26<sup>th</sup> February 2020, 9am



# ESTEEM PERFORMANCE PTE LTD

nt:1

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

M/S : AIG ASIA PACIFIC INSURANCE PTE.LTD  
AIG BUILDING  
78 SHENTON WAY  
#07-16 SINGAPORE 079120

ATTN: Motor Claim Department \ MR WONG

Your Ref No: PC1533S  
Claim Type: Own Damage  
Accident Date: 03/12/2019

Claim No: CER1302106  
Final No: CIV1302770  
Date: 16 Jan 2020  
Policy No: 999994313  
Veh Reg No: PC1533S  
Make/Model: TOYOTA HIACE  
H/ROOF 3.0 AT  
Chassis No: JTFST22P600015776  
Engine No: IKD2255216  
Reg. Date:

## Final Repair Cost to Vehicle No :PC1533S

| Description          | Quantity | List Price | Amount      |
|----------------------|----------|------------|-------------|
|                      |          | SS         | SS          |
| Others               |          |            |             |
| 1 COST OF REPAIR     | 1 PCS    | 4,086.80   |             |
|                      |          | 4,086.80   | 4,086.80    |
| Total                |          |            | SS 4,086.80 |
| Less Excess          |          |            | SS 2,500.00 |
| Amount Before GST    |          |            | SS 1,586.80 |
| Add GST @ 7%         |          |            | 111.08      |
| Total Amount Payable |          |            | SS 1,697.88 |

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SIX HUNDRED NINETY SEVEN AND CENTS EIGHTY EIGHT ONLY

The above vehicle was surveyed by KENNETH on 11/12/2019

For Esteem Performance Pte Ltd

E. &amp; O. E.

AUTHORISED SIGNATURE

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'ed | Status                                                          |
|------|-------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 10 Dec 2019 |               | 11 Dec 2019<br>15:24<br><a href="#">Edit Adj Rpt</a> | <b>S\$4,086.80</b><br><a href="#">Edit Estimates</a> | <b>S\$4,086.80</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                   |                                                                                                                    |                        |                                                                             |
|-------------------|--------------------------------------------------------------------------------------------------------------------|------------------------|-----------------------------------------------------------------------------|
| Insured:          | GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D                                                              |                        |                                                                             |
| Vehicle Reg. No.: | PC1533S                                                                                                            | Date of Loss:          | 03/12/2019 08:00 - :59<br>[82 Months and 3 Days From LTA Reg Date (Man Yr)] |
| Claim Type:       | OD / 0700173943SG                                                                                                  | Policy/Cover Note No.: | 0999994304 (Comprehensive)                                                  |
|                   |                                                                                                                    | Excess:                | S\$2,500.00                                                                 |
| Repairer:         | Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel: 64841221         |                        |                                                                             |
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com |                        |                                                                             |
| Adjuster:         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2019]    |                        |                                                                             |
| Driver/Custodian: | SAINODRDIN BIN ABDULLAH (54 / Male) , NRIC: S1731669I, Tel: +6598579975 Email: SAINODRDINABDULLAH@GMAIL.COM        |                        |                                                                             |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (12/12/2019): Alert - Adj Mandate Approved (S\$4676.00) - PC1533S - Claim Handler: Chan, Yoke S...
- AIG\_SG (12/12/2019): PC1533S / OD / 03/12/2019 / Coverage & Excess update

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |



## Claim Documents

**\*PC1533S (0700173943SG)**  
**OD**  
**Dec 3 2019 8:00AM**  
**[GOLDBELL CAR RENTAL PTE LTD]**  
**Esteem Performance Pte Ltd**

|                    |                 |  |                                   |  |  |                    |  |  |              |  |  |              |  |            |            |                                     |  |                                     |  |  |
|--------------------|-----------------|--|-----------------------------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|------------|------------|-------------------------------------|--|-------------------------------------|--|--|
| Upload Documents   |                 |  | Upload Photos                     |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |            | View       |                                     |  | View in Browser                     |  |  |
| Assessment Reports |                 |  |                                   |  |  |                    |  |  |              |  |  |              |  |            | 1 per page |                                     |  | <input checked="" type="checkbox"/> |  |  |
| No                 | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ) |  |  |                    |  |  |              |  |  |              |  | Thumbnail  |            | Print                               |  |                                     |  |  |
| 1                  | 12/12/19 14:35  |  | Adjuster Immediate Advice         |  |  |                    |  |  |              |  |  |              |  | 1 Load HTM |            |                                     |  |                                     |  |  |
| Photos/Images      |                 |  |                                   |  |  |                    |  |  |              |  |  |              |  |            | 3 per page |                                     |  | <input checked="" type="checkbox"/> |  |  |
| No                 | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ) |  |  |                    |  |  |              |  |  |              |  | Thumbnail  |            | Print                               |  |                                     |  |  |
| 1                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 2                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 3                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 4                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 5                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 6                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 7                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 8                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 9                  | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 10                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 11                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 12                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 13                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 14                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 15                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 16                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 17                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 18                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 19                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 20                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 21                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 22                 | 12/12/19 14:42  |  | General View                      |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 23                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 24                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 25                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 26                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 27                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 28                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 29                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| 30                 | 08/01/20 14:33  |  | Reinspection Photo                |  |  |                    |  |  |              |  |  |              |  | 1 Load JPG |            | <input checked="" type="checkbox"/> |  |                                     |  |  |
| Documentation      |                 |  |                                   |  |  |                    |  |  |              |  |  |              |  |            | 1 per page |                                     |  | <input checked="" type="checkbox"/> |  |  |
| No                 | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ) |  |  |                    |  |  |              |  |  |              |  | Thumbnail  |            | Print                               |  |                                     |  |  |
| 1                  | 12/12/19 14:37  |  | PC 1533S GIA.pdf                  |  |  |                    |  |  |              |  |  |              |  | 1 Load PDF |            |                                     |  |                                     |  |  |

| Assessment Reports |                |                                   | 1 per page ▾ | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|--------------|-------------------------------------|
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail    | Print                               |
| 2                  | 12/12/19 14:37 | CI.pdf                            | Load PDF     |                                     |
| 3                  | 12/12/19 14:37 | ESTIMATE.pdf                      | Load PDF     |                                     |
| 4                  | 12/12/19 14:37 | DRIVING.pdf                       | Load PDF     |                                     |
| 5                  | 08/01/20 14:33 | ESTIMATE & SUPP MARKED.pdf        | Load PDF     |                                     |
| 6                  | 10/03/20 16:58 | DISCHARGE VOUCHER                 | Load PDF     |                                     |
| 7                  | 10/03/20 16:58 | WORKSHOP INVOICE                  | Load PDF     |                                     |
| 8                  | 10/03/20 17:06 | SUPPLEMENTARY                     | Load PDF     |                                     |

## Linked Accident Report Documents

| Assessment Reports |                |                                              | 1 per page ▾ | <input checked="" type="checkbox"/> |
|--------------------|----------------|----------------------------------------------|--------------|-------------------------------------|
| No                 | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail    | Print                               |
| 1                  | 09/12/19 17:22 | Accident Statement                           | Load HTM     |                                     |
| 2                  | 10/12/19 12:47 | Addendum Sheet                               | Load TIF     |                                     |
| 3                  | 10/12/19 12:47 | Accident Statement                           | Load HTM     |                                     |
| Photos/Images      |                |                                              | 3 per page ▾ | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail    | Print                               |
| 1                  | 09/12/19 17:21 | Accident Photo                               | Load JPG     | <input checked="" type="checkbox"/> |
| 2                  | 09/12/19 17:21 | Accident Photo                               | Load JPG     | <input checked="" type="checkbox"/> |
| 3                  | 09/12/19 17:21 | Accident Photo                               | Load JPG     | <input checked="" type="checkbox"/> |
| Documentation      |                |                                              | 1 per page ▾ | <input checked="" type="checkbox"/> |
| No                 | Finalized On   | Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) | Thumbnail    | Print                               |
| 1                  | 09/12/19 17:21 | Sketch Plan                                  | Load TIF     |                                     |
| 2                  | 09/12/19 17:21 | CERTIFICATE OF INSURANCE                     | Load TIF     |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|----------------------------------------------|-------|------|-------|
| There are no document checklists configured. |       |      |       |

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
 Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG19021836/KSD3S2  
Date: 10/03/2020

## REFERENCE

Insured/Claimant: GOLDBELL CAR RENTAL PTE LTD  
Date of Loss: 03/12/2019

Policy No: 0999994304  
Nature of Claim: OD

Claim No: 0700173943SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: PC1533S  
Make & Model: TOYOTA HIACE, 3.0 D GL High-roof Commuter (A)  
Reg. Date: 31/01/2013 (Man. Year: 2012)  
Colour: White  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$35,000.00  
Sum Insured (S\$): Market Value/New Car Price

Engine No: 1KD2255216  
Chassis No: JTFST22P600015776  
Odometer: 0 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8  
Front Left Side: West Lake 8 mm Rear Left Side: Yokohama 3 mm  
Front Right Side: West Lake 8 mm Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                               | 5,951.70        | 2,666.80        | 3,284.90        | 55.19        |
| Miscellaneous Items                 | 0.00            | 0.00            | 0.00            |              |
| Labour                              | 2,700.00        | 1,420.00        | 1,280.00        | 47.41        |
| Paintwork Labour                    | 0.00            | 0.00            | 0.00            |              |
| Towing                              | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>8,651.70</b> | <b>4,086.80</b> | <b>4,564.90</b> | <b>52.76</b> |
| <b>- Excess (S\$)</b>               | <b>2,500.00</b> | <b>2,500.00</b> | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>6,151.70</b> | <b>1,586.80</b> | <b>4,564.90</b> | <b>74.21</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>430.62</b>   | <b>111.08</b>   | <b>319.54</b>   | <b>74.20</b> |
| <b>Nett Amount (S\$)</b>            | <b>6,582.32</b> | <b>1,697.88</b> | <b>4,884.44</b> | <b>74.21</b> |

## INSPECTION

Date of Assignment: 11/12/2019

Date Inspected: 11/12/2019 Inspected At:

Esteem Performance Pte Ltd (HQ)  
Blk 5033 Ang Mo Kio Ind Park 2, #01-259  
Singapore 569536

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's | Amount    |
|-----|-----|----------|--------------------------------------|---------------|------------|-----------|
| 1   | 1   |          | *FRONT NUMBER PLATE GARNISH (NPA)    | No such part  | 0.00 F     | *- F      |
| 2   | 1   |          | *BONNET (WCP)                        | Bent          | 210.00 F   | *210.00 F |
| 3   | 1   |          | *BONNET LOCK (WCP)                   | Repair        | 35.00 F    | *- F      |
| 4   | 1   |          | *BONNET EMBLEM (WCP)                 | Necessary     | 30.00 F    | *25.00 F  |
| 5   | 1   |          | *BONNET HEAT INSULATOR (NPA)         | No such part  | 0.00 F     | *- F      |
| 6   | 10  |          | *BONNET HEAT INSULATOR CLIP (NPA)    | Not Necessary | 0.00 F     | *- F      |
| 7   | 1   |          | *BONNET HINGE LH (WCP)               | Distorted     | 29.00 F    | *29.00 F  |
| 8   | 1   |          | *BONNET HINGE RH (WCP)               | Bent          | 29.00 F    | *29.00 F  |
| 9   | 1   |          | *HEADLAMP LH (WCP)                   | Mtg Broken    | 200.00 F   | *200.00 F |
| 10  | 1   |          | *HEADLAMP RH (WCP)                   | Broken        | 200.00 F   | *200.00 F |
| 11  | 10  |          | *HEADLAMP CLIP (WCP)                 | Not Necessary | 1.50 F     | *- F      |
| 12  | 1   |          | *HEADLAMP LH SOCKET (NPA)            | Serviceable   | 0.00 F     | *- F      |
| 13  | 1   |          | *HEADLAMP RH SOCKET (NPA)            | Serviceable   | 0.00 F     | *- F      |
| 14  | 1   |          | *RH CORNER PANEL (WCP)               | Bent          | 60.00 F    | *60.00 F  |
| 15  | 1   |          | *FRONT SUPPORT PANEL COMPLETED (WCP) | Repair        | 130.00 F   | *- F      |
| 16  | 1   |          | *FRONT BUMPER (WCP)                  | Missing       | 185.00 F   | *185.00 F |
| 17  | 10  |          | *FRONT BUMPER CLIP (WCP)             | Not Necessary | 1.50 F     | *- F      |
| 18  | 1   |          | *FRONT BUMPER REINFORCEMENT (WCP)    | Bent          | 70.00 F    | *70.00 F  |
| 19  | 1   |          | *FRONT BUMPER BEAM (WCP)             | Bent          | 80.00 F    | *80.00 F  |
| 20  | 1   |          | *FRONT BUMPER SIDE RETAINER LH (WCP) | Cracked       | 50.00 F    | *50.00 F  |
| 21  | 1   |          | *FRONT BUMPER SIDE RETAINER RH (WCP) | Cracked       | 50.00 F    | *50.00 F  |
| 22  | 1   |          | *FRONT BUMPER BRACKET LH (WCP)       | Repair        | 38.00 F    | *- F      |
| 23  | 1   |          | *FRONT BUMPER BRACKET RH (WCP)       | Repair        | 38.00 F    | *- F      |
| 24  | 1   |          | *FRONT BUMPER UPPER GRILLE (WCP)     | Cracked       | 175.00 F   | *175.00 F |
| 25  | 1   |          | *FRONT BUMPER LOWER GRILLE (WCP)     | Missing       | 90.00 F    | *90.00 F  |
| 26  | 1   |          | *AIR FILTER BOX (WCP)                | Broken        | 230.00 F   | *230.00 F |
| 27  | 1   |          | *CONDENSER (WCP)                     | Serviceable   | 480.00 F   | *- F      |
| 28  | 1   |          | *CONDENSER FAN MOTOR (WCP)           | Serviceable   | 360.00 F   | *- F      |
| 29  | 1   |          | *CONDENSER FAN BLADE (WCP)           | Serviceable   | 50.00 F    | *- F      |
| 30  | 1   |          | *CONDENSER FAN COWLING (WCP)         | Serviceable   | 100.00 F   | *- F      |
| 31  | 1   |          | *RADIATOR (WCP)                      | Serviceable   | 620.00 F   | *- F      |
| 32  | 1   |          | *RADIATOR FAN MOTOR (WCP)            | Serviceable   | 360.00 F   | *- F      |
| 33  | 1   |          | *RADIATOR FAN BLADE (WCP)            | Serviceable   | 40.00 F    | *- F      |
| 34  | 1   |          | *RADIATOR FAN COWLING (WCP)          | Serviceable   | 100.00 F   | *- F      |
| 35  | 1   |          | *RH FRONT DOOR (WCP)                 | Repair        | 600.00 F   | *- F      |
| 36  | 1   |          | *FRONT WINDSCREEN (WCP)              | Cracked       | 450.00 F   | *450.00 F |
| 37  | 1   |          | *FRONT WINDSCREEN MOULDING (WCP)     | Necessary     | 45.00 F    | *45.00 F  |
| 38  | 1   |          | *FRONT NUMBER PLATE                  | Missing       | 45.00 FS   | *45.00 FS |
| 39  | 1   |          | *COOLANT                             | Not Necessary | 20.00 FS   | *- FS     |
| 40  | 1   |          | *GREEN STICKER                       | Necessary     | 20.00 FS   | *20.00 FS |
| 41  | 1   |          | *FRONT WINDSCREEN SEALANT            | Necessary     | 50.00 FS   | *40.00 FS |
| 42  | 1   |          | *FRONT WINDSCREEN INNER SEAL TAPE    | Necessary     | 30.00 FS   | *30.00 FS |
| 43  | 1   |          | *FRONT WINDSCREEN I.U. BRACKET       | Necessary     | 26.00 FS   | *26.00 FS |
| 44  | 1   |          | *FOG LAMP COVER RH (WCP)             | Dented        | 25.00 F    | *25.00 F  |
| 45  | 1   |          | *AIR FILTER BOX TOP DUCTING (WCP)    | Cracked       | 55.00 F    | *55.00 F  |
| 46  | 1   |          | *TOW COVER LH (WCP)                  | Missing       | 10.00 F    | *10.00 F  |
| 47  | 1   |          | *TOW COVER RH (WCP)                  | Missing       | 10.00 F    | *10.00 F  |

F=Franchise part. S=SpcNett.

|                                                  |                 |                 |
|--------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                          | <b>5,428.00</b> | <b>2,439.00</b> |
| <b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b> | <b>523.70</b>   | <b>227.80</b>   |

Report was unsubmitted during this print-out.

| No.               | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|-------------------|-----|----------|-------------|-----------|------------|----------|
| Total Parts (S\$) |     |          |             |           | 5,951.70   | 2,666.80 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                              |          |                 |                 |
| 1                               | TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.<br>(BONNET, FRONT BUMPER, SUPPORT PANEL, LHF CORNER PANEL,<br>LHF DOOR, RHF DOOR)   | New      | 1,000.00        | 600.00          |
| 2                               | TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.<br>(BONNET, FRONT BUMPER, SUPPORT PANEL, RHF CORNER PANEL,<br>LHF DOOR, RHF DOOR) | New      | 1,200.00        | 800.00          |
| 3                               | TO CHECK WIRING & FOCUS HEADLAMP.                                                                                                            | New      | 50.00           | 20.00           |
| 4                               | TO REMOVE & REFIT RADIATOR, CONDENSER TO ASSIST WORK LOAD,<br>TO TOP UP A/C GAS.                                                             | New      | 150.00          | 0.00            |
| 5                               | TO DO WHEEL ALIGNMENT.                                                                                                                       | New      | 120.00          | 0.00            |
| 6                               | TO DO ART WORK. (RHF DOOR)                                                                                                                   | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                              |          | <b>2,700.00</b> | <b>1,420.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >