

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 12 Dec 2019

Preliminary Advice

Vehicle No	: PC1533S	Accident Date	: 03/12/2019
Make	: TOYOTA HIACE	Policy No.	: 0999994304
Assignment Date	: 11/12/2019	Excess	: S\$2,500.00
Date of Inspection	: 11/12/2019	Est. Duration of Repair	: 6 days
Inspection At	: Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,571.40
Revised Amount	:S\$	4,675.30
Check Items (Estimated)	:S\$	430.30
Total	:S\$	5,105.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	18,790.00
Salvage Value	:S\$	
Margin for Repair	:S\$	16,210.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :