

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 13 Dec 2019

Preliminary Advice

Insured Vehicle No : SJP4319C

TP Vehicle No : FBK5565Y

Make : HONDA CB400

Date of Inspection : 11/12/2019

Inspection At : SANFU MOTOR PL

Accident Date : 07/12/2019

Assignment Date : 11/12/2019

Est. Duration of Repair : 3/Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesRear O/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,626.50
Revised Amount	:S\$	5,971.50
Check Items (Estimated)	:S\$	416.25
Total	:S\$	6,387.75

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :We have not authorized repairs.