

L/S repair
without pre-finish
3 day
Resurvey before part
Hock ANN
LKLC
8531488
11/12/19
3.45pm

Resurvey taken
16/12/19
2-30pm
H-ANN
LKLC
after part most
infin taken after part



Hock ANN @ 11/12/19 Auto.com

ASSESSMENT FOR REPAIR : FBK5565Y

HONDA CB400

COE EXPIRY : 08 OCT 2025

Lump Sum / Part by Part

Qty	Description	Repairer's Estimate	Ist Survey	Repair Survey	Final Survey
1	METER COVER ASSY ✓ photo scr ✓	190.00	60.00	462.50	
1	BRAKE LEVER R ✓ BT	65		80.00	
1	HANDLE BAR ✓ BT	210.00		225.00	
1	FRONT FENDER ✓ scr	196.50		237.50	
1	FUEL TANK ✓ BT	1350.00		1,950.00	
1	RR BRAKE PEDAL ✓ CRU	140.20		162.50	
1	R/H ENGINE COVER ✓ scr	450.00		550.00	
1	YOSHIMURA STREET LEGAL LTA EXHAUST SYSTEM ✓ cut	3,125.00			
		1150.00			

6,792.50

less 10%

Special Nett Items

1	STEERING CONE & BEARING ✓	120.00			
1	ALIGNMENT ✓	220.00			
1	REAR NO. PLATE ✓ CRU	32.00			
1	ENGINE OIL 4L (\$28X4) ✓ m	112.00			

484.00

Total Parts

7,276.50

Labour Charges

- 1 Workmanship to renew damage parts & areas ✓

350.00

350.00

Total Parts & Labours Concluded

7,626.50

3751.70

Parts less 10%

3376.53

spe nett 297

1950 240

3913.53

4/5 less 20%

3130.82

Total 4/5 amt \$3100

LKK Auto Consultants is the Repairer of the following:

- To resurvey before/after repair
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and subject to final approval from the Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com