

ASS. REC. BY:

REF: CS/C11/9021856/ Guy f3

Special Instruction:

SURVIVOR: GA

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of C11 Date/Time: 11-12-19 16:12p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKL 6884H Insured: GBA 7530L

at Workshop m/s S Three Automotive Tel: 9766 2745

of BIC 8 sm my Ind Est #01-64/66

Policy No: DMCVSN 30433519000 Claim No: SIMM 19D205967C02

Sum Insured: Excess:

Make of Veh: D.O.A. 5-12-19

(Client's Record)

CA / REV / REP. / REV 24 HRS map 12.12.2019

Date/Time: 11.12.19 4.23p.m H.O.D. Endorsement:

Person Contacted: Michelle Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 6884H - x
	GBA 7530L - CS3/MSG/180178201/RICd302 DOA-28/04/2019

ASS. REC. BY: ad. REF: CTL

ASSIGNMENT

From: _____ Date: 12.12.2019
 Estimated Cost: _____
 OT / TP / VS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKL 6884H
 at Workshop m/s: S Three Automotive
 of Blt B sm ming Ind Est #01-64/66
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$53K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 7A days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKL6884H Yr Regn: 13 Dec 2013
 Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda CX-5 C.C. 1998
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 83048 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IM6KE1071E0223344

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R17
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>12-12-19</u>
Survey held at <u>w/s</u>	<u>12:15</u>

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Calc: 46944</u>
	<u>Net: 7000</u>
<u>20/12</u>	<u>unconfirm with w/s \$7000. lins (Red \$31,311-52, 81%)</u>
RECEIVED 23 DEC 2019	

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

2) 20/12/19 Typist

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Rep. Format: _____

Imp. Sum \$7000/=

Survey Fee: _____

Transportation: _____

_____ B + RS. \$1

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2019		11 Dec 2019 16:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: NATURAL CAR RENTALS PTE LTD									
Vehicle Reg. No.: SKL6884H		Date of Loss: 05/12/2019 07:00 - :59							
Claim Type: TP / SNM19D205867C02		Policy/Cover Note No.: DMCVSN30435519000							
Vehicle Reg. No. (Insured): GBA7530L		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ) BLK 8 SIN MING IND EST #01-64/66, 575643 Sin Ming - Tel: 9766 2745									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hul Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/12/2019]									
Adj Asg. Remarks: PLEASE SURVEY AND REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 11 December 2019 4:06 PM
To: Sim Teo Koon; alfred_ng@juseq.com.sg
Cc: assignments; Admin A
Subject: FW: ***SPAM*** FW: OUR REF : SNM19D205867/GBA7530L/IRENE - ACCIDENT INVOLVING SKL6884H & GBA7530L ON 5-12-2019. O REF: JEQ/191272/1219/S3

Dear Sir(LKK),

We refer to the above matter.

Please get your surveyor to liaise with S Three to conduct PRS.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F:(65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]
Sent: Wednesday, December 11, 2019 10:53 AM
To: Irene Tay <irene.tay@sg.cntaiping.com>; alfred_ng@juseq.com.sg
Cc: 'S Three Automotive' <admin@sthreeautomotive.com.sg>
Subject: RE: ***SPAM*** FW: OUR REF : SNM19D205867/GBA7530L/IRENE - ACCIDENT INVOLVING SKL6884H & GBA7530L ON 5-12-2019. O REF: JEQ/191272/1219/S3

Dear Sirs,

We refer to your email.

Our client is agreeable to appoint **KENNETH KONG (LKK Auto Consultants Pte Ltd)** as a single joint expert.

Please be informed that our client's motor vehicle is available for inspection at the under-stated workshop: -

S THREE AUTOMOTIVE RECOVERY PTE LTD
Blk 8 Sin Ming Industrial Estate #01-64/66,
Singapore 575643
Tel: 6284 1542; Fax: 6487 5315

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation.

Tel: 6506 6065, Fax: 6536 9339

E-mail: tk_sim@juseq.com.sg

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

Sent: 11 December 2019 09:18

To: Sim Teo Koon <tk_sim@juseq.com.sg>; alfred_ng@juseq.com.sg

Subject: ***SPAM*** FW: OUR REF : SNM19D205867/GBA7530L/IRENE - ACCIDENT INVOLVING SKL6884H & GBA7530L ON 5-12-2019. O REF: JEQ/191272/1219/S3

WITHOUT PREJUDICE

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING

Kelvin Ang

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

XING QUO QIANG

KENNETH KONG

SIMON HO

CHUA WEIJIE

MARCUS CHUA

HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Executive

Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 62247478/62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Tuesday, December 10, 2019 4:17 PM

To: Irene Tay <irene.tay@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
tk_sim@juseq.com.sg

Subject: OUR REF : SNM19D205867/GBA7530L/IRENE - ACCIDENT INVOLVING SKL6884H & GBA7530L ON 5-12-2019.
O REF: JEQ/191272/1219/S3

Dear Irene,

Please conduct PRS for SKL6884H.

Note : officer in charge – Irene Tay 63896192.

***** Kindly quote our reference number when replying.**

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sim Teo Koon [mailto:tk_sim@juseq.com.sg]

Sent: Tuesday, 10 December, 2019 2:27 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: ACCIDENT INVOLVING SKL6884H & GBA7530L ON 5-12-2019. O REF: JEQ/191272/1219/S3

Dear Sirs,

Please refer to our notice of accident.

Regards,

Sim Teo Koon (On behalf of Mr Michael Yap)

JusEquity Law Corporation

133 New Bridge Road #10-03, Chinatown Point,

Singapore 059413

Tel: 6506 6065 / 6536 9339

Fax: 6536 5368

E-mail: tk_sim@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

► Mazda CX-5 Used Vehicle List (13 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Mazda CX-5 2.0A	\$67,888	\$10,670 /yr	30-Jun-2015	1,998 cc	79,554 km	Autocar Pte Ltd	Availabl
1 Owner, Fully Maintained By Agent Since Day One. Low Mileage Done. Come With Original Agent Approve Certificate. Still In Original Condit And Paintwork Since Day One. 100% Accident Free! Call Us N... Office No. - - Keith - 97427882							
Mazda CX-5 2.0A	\$74,800	\$10,810 /yr	20-Oct-2015	1,998 cc	66,000 km	Hui Hua Credit Pte Ltd	Availabl
1 Owner! Agent Unit! Face Lifted Model! Popular Compact SUV! Low Mileage Done! Regularly Serviced By Previous Owner! Zero Mishap! In House Financing And High Trade In Given! Call Now To Enquire! Office No. - 64696611 / 64646611 Jian Rong - 91830337 Joey Ng - 88110091 Weisley - 84888000 Jevon - 88588388							
Mazda CX-5 2.0A	\$74,800	\$10,770 /yr	27-Oct-2015	1,998 cc	46,800 km	Vantage Pre-Owned	Availabl
Agent Unit. Extremely Popular And Reliable Premium Japanese SUV. Well Maintained 1 Owner Unit In Stunning Metallic Grey. Buy With Adde Peace Of Mind From Vantage Pre-Owned. A Member Of The Sime Darby... Office No. - 63762277 Valerie Tan - 98161147 Louis Chan - 96965133							
Mazda CX-5 2.0A Premium	\$76,988	\$10,630 /yr	24-Dec-2015	1,998 cc	56,000 km	Carz World Pte Ltd	Availabl
Premium Model! 1 Owner, Low Mileage! Full Servicing Records Available Upon Request. Fully Serviced By Agent. Accident Free! This Unit Com With Spare Tyre As Well. Red Hot Japanese SUV, Extremely Pop... Office No. - 65709482 Edwin Foo - 96437773 Joel Yew - 93874209							
Mazda CX-5 2.0A Premium	\$77,800	\$10,660 /yr	31-Dec-2015	1,998 cc	62,000 km	SG Car Choice Pte Ltd	Availabl
Low Monthly From \$7xx Only! High Specs Unit Maintained By 1 Previous Owner! Units Comes With BOSE Entertainment Sound System, In Br Navigation And Electric Memory Seats! The Most Affordable SUV In ... Office No. - 63974080 Roy - 81260077 Tommy - 81252285 Trev - 92727377							
Mazda CX-5 2.0A	\$81,800	\$11,040 /yr	22-Mar-2016	1,998 cc	62,488 km	Clarity Cars Pte Ltd	Availabl
100% Loan Available! Flexible Loan From Bank/In House Curated To Your Financing Needs, With Attractive Interest Rates! 1 Owner Unit, Fu Agent Serviced. 6 Months Gearbox&Engine Warranty. External Ch... Office No. - 62053313 / 62053133 Sherman Tan - 88165892 Brian Si - 88590725 Abigail Goh - 97876476 Trevor Ng - 91058969							
Mazda CX-5 2.0A	\$83,800	\$10,990 /yr	31-May-2016	1,998 cc	50,000 km	Thong Lee Trading Pte Ltd	Availabl
Full Loan Available, Well Maintained By Only 1 Owner. Paying Cheap For The Quality. Superb Condition. Full Agent Serviced Done. No Gimmi Always Sheltered Car. Original Paintwork.(No Dealers, Whata... Office No. - 68419655 Alvin Goh - 97993445 Kelvin Tan - 90618082							
Mazda CX-5 2.0A Premium	\$90,800	\$10,890 /yr	16-Dec-2016	1,998 cc	50,000 km	Unicars Automobile	Availabl
Tip Top Condition! Well Dressed Up With 19" Rims. 1 Owner. Full Serviced With Trans Eurokars Since Day 1. Spotless Bodywork. Engine And Gearbox In Excellent Condition. Perfect Under Carriage. Accident... Office No. - 62355035 Warren - 97636000							
Mazda CX-5 2.0A Premium	\$101,800	\$10,870 /yr	08-Dec-2017	1,998 cc	31,300 km	Motorist Pte Ltd	Availabl

Premium Model! 100% Accident Free. 1 Owner Unit. Fully Serviced And Maintained By Agent. Still Under Warranty! Workshop/STA Evaluatio

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	157E
Vehicle Details	
Vehicle No.:	SKL6884H
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2019
Vehicle Make:	MAZDA
Vehicle Model:	CX-5 5-DOOR WAGON 2.0L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	PE20339323
Chassis No.:	JM6KE1071E0223344
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$22,666.00 ✓
Original Registration Date:	13 Dec 2013
First Registration Date:	13 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$18,733.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Dec 2023
PARF Rebate Amount:	\$13,113.00
Intended COE Rebate Details	
COE Expiry Date:	12 Dec 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$84,578.00
COE Rebate Amount:	\$33,831.00
Total Rebate Amount:	\$46,944.00

The information contained herein is correct as at 12 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 17:04
Date Of Accident	05/12/2019 07:15
Exact Location Of Accident	PIONEER ROAD TURN TUAS CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL6884H
Insured/Policyholder	
Name Of Registered Owner	NATIONAL CAR RENTALS PTE LTD
Co Reg No	195100157E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94871051
Alternative Phone No	OFFICE-94871051

Vehicle Particulars

Manufacturer	MAZDA
Model	CX-5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	DUSTIN RYAN PHILIPS
Passport No/FIN	G3331333R
Date Of Birth	05/02/1991
Occupation	INDOOR
Date Of Driving Pass	19/02/2015
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94871051
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	390A HAVELOCK ROAD #01-07 SINGAPORE
Postcode	169664
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA7530L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims collectively the "Purposes".
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (f) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/PIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attach printed statement.

DECLARATION

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____

Date & Time:

Qualität zu erst. Anschließend ist

Driver's Signature
(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature: _____
Name: _____

NANCY/FOUO 7/20/02

Sketch Plan #3

Name: Dustin Phillips

FN: G3331333H

Vehicle: Blue Mazda CX-5

Plate Number: 58L6884H

Additional PAX: 1

Other Driver Name: Ramanathan Ayyappan

Work Permit Number: O 32723853

Vehicle: Grey Mitsubishi FUSO

Plate Number: G8A7530L

Additional PAX: 1 in the cab, two in the bed of the lorry

Date of Accident: 5/12/2019 at approx. 7:15AM

Injuries: None

Dustin Phillips Statement as Follows:

At approximately 7:15AM on 5/12/2019, I was stopped in the left hand turn lane on Pioneer Road waiting to turn left onto Tuas Crescent. I had a red light so I came to a stop in the left turn yield lane while waiting for a lorry to pass through the intersection and allow me to turn safely on to Tuas Crescent. While I was stopped, I was rear-ended by the Mitsubishi FUSO lorry at a high rate of speed pushing my vehicle into Tuas Crescent. My passenger and I were unharmed and it appeared the driver and three additional passengers were unharmed as all four were out and walking around. We exchanged information, took photos of the scene, and drove off in our own vehicles.

Dustin Phillips

 5/12/19



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO
ATTN

T/P VEHL NO: GBA7530L

ESTIMATE REPORT 1st QUOTATION

JOB NO:

OWNER'S PARTICULAR

NAME: NATIONAL CAR RENTALS PTE LTD

CONTACT:

ADDRESS:

LICENSE NO SKL6884H TRANS:

CHASSIS NO:

MAKE / MODEL: MAZDA CX5

ENGINE NO:

OWNER'S INSURER NTUC INCOME

JOB-CODE: TP S/A: MICHELLE

ACCIDENT DATE: 5-Dec-19

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR-DISC	REV. PRICE
1 REAR WINDSCREEN GLASS / SM	1.00	\$ 1,139.80	20.00	\$ 911.84	Y	1139 ✓
2 REAR WINDSCREEN GLASS MOULDING	1.00	\$ 60.00	20.00	\$ 48.00	Y	✓
3 REAR WINDSCREEN GLASS SIDE MOULDING LH	1.00	\$ 50.00	20.00	\$ 40.00	Y	30 ✓
4 REAR WINDSCREEN GLASS SIDE MOULDING RH	1.00	\$ 50.00	20.00	\$ 40.00	Y	✓
5 TAILGATE / Buc	1.00	\$ 1,637.40	20.00	\$ 1,309.92	Y	1321.4 ✓
6 TAILGATE SPOILER / De	1.00	\$ 1,107.70	20.00	\$ 886.16	Y	1107.7 ✓
7 TAILGATE LOGO / KC	1.00	\$ 54.30	20.00	\$ 43.44	Y	54.3 ✓
8 TAILGATE 1/4 GARNISH RH X for NN	1.00	\$ 38.00	20.00	\$ 30.40	Y	X
9 TAILGATE 1/4 GARNISH LH X	1.00	\$ 38.00	20.00	\$ 30.40	Y	X
10 TAILGATE EMBLEM - SKYACTIV / KC	1.00	\$ 75.20	20.00	\$ 60.16	Y	75.2 ✓
11 TAILGATE EMBLEM CX5	1.00	\$ 47.60	20.00	\$ 38.08	Y	47.6 ✓
12 TAILGATE OUTER CHROME MOULDING X for NN	1.00	\$ 450.20	20.00	\$ 360.16	Y	X
13 TAILGATE INNER LOCK / BT	1.00	\$ 269.30	20.00	\$ 215.44	Y	174.5 ✓
14 TAILGATE INNER LOCK CATCH X NN	1.00	\$ 45.60	20.00	\$ 36.48	Y	X
15 TAILGATE RUBBER BEADING / at	1.00	\$ 185.90	20.00	\$ 148.72	Y	185.9 ✓
16 TAILGATE INNER TRIM BOARD / at	1.00	\$ 313.40	20.00	\$ 250.72	Y	256.4 ✓
17 TAILGATE INNER TRIM LH / for De	1.00	\$ 413.50	20.00	\$ 330.80	Y	115 ✓
18 TAILGATE INNER TRIM RH / for De	1.00	\$ 413.50	20.00	\$ 330.80	Y	115 ✓
19 TAILGATE INNER TRIM TOP X NN	1.00	\$ 55.00	20.00	\$ 44.00	Y	X
20 TAILGATE INNER HANDLE / m/s	1.00	\$ 183.30	20.00	\$ 146.64	Y	183.3 ✓
21 TAILGATE OUTER HANDLE / CRA	1.00	\$ 330.00	20.00	\$ 264.00	Y	330 ✓
22 TAILGATE RUBBER X	1.00	\$ 183.30	20.00	\$ 146.64	Y	X
23 TAILGATE DAMPER LH X NN	1.00	\$ 244.00	20.00	\$ 195.20	Y	X
24 TAILGATE DAMPER RH X	1.00	\$ 244.00	20.00	\$ 195.20	Y	X
25 TAILGATE LAMP RH X NN	1.00	\$ 495.00	20.00	\$ 396.00	Y	X
26 TAILGATE LAMP LH / CRA	1.00	\$ 495.00	20.00	\$ 396.00	Y	466.6 ✓

8019

27	TAILGATE HINGE LH	X	1.00	\$	38.60	20.00	\$	30.88	Y	_____	X
28	TAILGATE HINGE RH	X	1.00	\$	38.60	20.00	\$	30.88	Y	_____	X
29	TAILGATE WIRE HARDNESS	X	1.00	\$	596.00	20.00	\$	476.80	Y	_____	X
30	REAR WIPER MOTOR	✓	1.00	\$	320.10	20.00	\$	256.08	Y	320.10	✓
31	REAR WIPER BLADE	✓	1.00	\$	58.00	20.00	\$	46.40	Y	58	✓
32	REAR WIPER ARM	✓	1.00	\$	68.10	20.00	\$	54.48	Y	68.10	✓
33	REAR TAILLAMP RH	✓	1.00	\$	588.00	20.00	\$	470.40	Y	588	✓
34	REAR TAILLAMP LH	✓	1.00	\$	588.00	20.00	\$	470.40	Y	588	✓
35	TAILGATE OPEN SWITCH	X	1.00	\$	99.60	20.00	\$	79.68	Y	_____	X
36	REAR TAILLAMP PANEL LH	X	1.00	\$	285.00	20.00	\$	228.00	Y	_____	X
37	REAR TAILLAMP PANEL RH	X	1.00	\$	285.00	20.00	\$	228.00	Y	_____	X
38	REAR BUMPER	✓	1.00	\$	1,278.90	20.00	\$	1,023.12	Y	1218	✓
39	REAR BUMPER REINFORCEMENT	✓	1.00	\$	614.10	20.00	\$	491.28	Y	584.8	✓
40	REAR BUMPER BRACKET RH	X	1.00	\$	116.00	20.00	\$	92.80	Y	_____	X
41	REAR BUMPER BRACKET LH	X	1.00	\$	116.00	20.00	\$	92.80	Y	_____	X
42	REAR BUMPER TOWING COVER 2PCS	ipc - cut	1.00	\$	192.00	20.00	\$	153.60	Y	8	✓
43	REAR BUMPER TOP RETAINER RH	X	1.00	\$	38.00	20.00	\$	30.40	Y	_____	X
44	REAR BUMPER TOP RETAINER LH	X	1.00	\$	38.00	20.00	\$	30.40	Y	_____	X
45	REAR BUMPER REFLECTOR LH	X	1.00	\$	186.00	20.00	\$	148.80	Y	_____	X
46	REAR BUMPER REFLECTOR RH	X	1.00	\$	186.00	20.00	\$	148.80	Y	_____	X
47	REAR BUMPER SIDE RETAINER LH	✓	1.00	\$	68.00	20.00	\$	54.40	Y	32.4	✓
48	REAR BUMPER SIDE RETAINER RH	✓	1.00	\$	68.00	20.00	\$	54.40	Y	32.4	✓
49	REAR NUMBER PLATE LAMP LH	X	1.00	\$	47.60	20.00	\$	38.08	Y	_____	X
50	REAR NUMBER PLATE LAMP RH	X	1.00	\$	47.60	20.00	\$	38.08	Y	_____	X
51	REAR END PANEL	X repair	1.00	\$	519.00	20.00	\$	415.20	Y	_____	X
52	REAR END PANEL INNER GARNISH	✓	1.00	\$	476.10	20.00	\$	380.88	Y	_____	✓
53	REAR END PANEL INNER CROSSMEMBER	X repair	1.00	\$	78.20	20.00	\$	62.56	Y	_____	X
54	REAR FENDER INNER TRIM BOARD LH	X	1.00	\$	413.50	20.00	\$	330.80	Y	_____	X
55	REAR FENDER INNER TRIM BOARD RH	X	1.00	\$	413.50	20.00	\$	330.80	Y	_____	X
56	REAR FENDER WHEEL PROTECTOR LH	✓	1.00	\$	375.00	20.00	\$	300.00	Y	375	✓
57	REAR FENDER WHEEL PROTECTOR RH	✓	1.00	\$	375.00	20.00	\$	300.00	Y	375	✓
58	REAR SPARE TYRE BOARD	X	1.00	\$	645.90	20.00	\$	516.72	Y	_____	X
59	REAR SPARE TYRE PANEL	X	1.00	\$	1,150.00	20.00	\$	920.00	Y	_____	X
60	REAR EXHAUST SILENCER	X repair	1.00	\$	1,754.00	20.00	\$	1,403.20	Y	_____	X
61	REAR EXHAUST MOUNTING	X	1.00	\$	38.00	20.00	\$	30.40	Y	_____	X
62	REAR EXHAUST HEAT SHIELD	X	1.00	\$	78.40	20.00	\$	62.72	Y	_____	X

12277.8

~~\$400.96~~

63	CENTRE EXHAUST PIPE	1.00	\$ 1,780.00	20.00	\$ 1,424.00	Y	_____	X
64	REAR KEYLESS CONTROL	1.00	\$ 227.60	20.00	\$ 190.08	Y	_____	X

TOTAL (PARTS) :

22914.40

18331.52

SPECIAL NETT ITEM

1	REAR WINDSCREEN GLASS SEALANT	1.00	50.00	0.00	50.00	Y	<u>20</u>	/
2	REAR WINDSCREEN GLASS INNER SEAL	1.00	50.00	0.00	50.00	Y	<u>20</u>	/
3	REAR WINDSCREEN GLASS CLEANER & PRIMER	1.00	50.00	0.00	50.00	Y	<u>20</u>	/
4	REAR NUMBER PLATE	1.00	50.00	0.00	50.00	Y	<u>40</u>	/
5	REAR FENDER INNER SHIELD CLIPS	1.00	100.00	0.00	100.00	Y	<u>30</u>	/
6	REAR END PANEL SEALANT	1.00	80.00	0.00	80.00	Y	_____	X
7	REAR END PANEL INNER GARNISH CLIPS 1SET	1.00	50.00	0.00	50.00	Y	<u>20</u>	/
8	REAR BUMPER CLIPS 1SET	1.00	50.00	0.00	50.00	Y	<u>40</u>	/
9	REAR SPARETYRE INSULATOR PAD	1.00	180.00	0.00	180.00	Y	_____	X
10	REAR REVERSE SENSOR	1.00	280.00	0.00	280.00	Y	<u>200</u>	/
11	REAR WINDSCREEN SOLAR FILM	1.00	280.00	0.00	280.00	Y	<u>150</u>	/
12	REAR CAMERA	1.00	680.00	0.00	680.00	Y	_____	X

TOTAL (PARTS) :

6740.00

6740.00

LABOUR

1	STRAIGHTEN & PANEL BEAT ON ACCIDENT AREA	1.00	1800.00	0.00	1800.00	Y	<u>600</u>	/
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1800.00	0.00	1800.00	Y	<u>600</u>	/
3	CHECK & REPAIR WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	<u>30</u>	/
4	R&R INNER TRIM, INNER GARNISH TO ASSIST REPAIR	1.00	120.00	0.00	120.00	Y	<u>60</u>	/
5	R&R AND RESET REAR BUMPER SENSOR	1.00	120.00	0.00	120.00	Y	<u>40</u>	/
6	R&R REAR WINDSCREEN GLASS	1.00	150.00	0.00	150.00	Y	<u>100</u>	/
7	R&R AND RE-ADJUST REAR EXHAUST SYSTEM	1.00	280.00	0.00	280.00	Y	<u>60</u>	/
8	RESPRAY TUFF KOTE ON ACCIDENT AREAS	1.00	280.00	0.00	280.00	Y	<u>20</u>	X
9	R&R TAILGATE COMPONENTS	1.00	120.00	0.00	120.00	Y	<u>60</u>	/
10	TOWING FEE - KING DOLLEY	1.00	180.00	0.00	180.00	Y	_____	X

TOTAL (LABOUR) :

13240.00

13240.00

Submit Invoice
to Insurance

4930

TOTAL PARTS & LABOUR

\$ 42,894.40

\$ 38,311.52

25161-52

EXCESS : \$

NO. OF DAY : 6.7

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$

DATE OF SURVEY 12/12/19

SURVEY BY Guo Qiang

CONTACT NO 82880282

FAX NO

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19021856/GYF3N2
Date: 30/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30435519000
 Claimant Vehicle No: SKL6884H Insured Vehicle No: GBA7530L
 Date of Loss: 05/12/2019 Nature of Claim: TP Claim No: SNM19D205867C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL6884H
 Make & Model: MAZDA CX-5, 2.0 (A) Engine No: PE20339323
 Reg. Date: 13/12/2013 (Man. Year: 2013) Chassis No: JM6KE1071E0223344
 Colour: Blue Odometer: 83048 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65R17 Rear Tyre Size: 225/65R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,231.52	8,888.64	11,342.88	56.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	1,550.00	3,380.00	68.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,161.52	10,438.64	14,722.88	58.51
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	25,161.52	7,000.00	18,161.52	72.18
+ GST 7.00/7.00% (S\$)	1,761.31	490.00	1,271.31	72.18
Nett Amount (S\$)	26,922.83	7,490.00	19,432.83	72.18

INSPECTION

Date of Assignment: 11/12/2019
 Date Inspected: 12/12/2019 Inspected At: S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ)
 BLK 8 SIN MING IND EST #01-64/66
 Singapore 575643
 Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)
Parts:	M1-SUV	MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL6884H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS	Smashed	1,139.80 FL	*1,139.00 FL
2	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	60.00 FL	*60.00 FL
3	1		*REAR WINDSCREEN GLASS SIDE MOULDING LH	Necessary	50.00 FL	*30.00 FL
4	1		*REAR WINDSCREEN GLASS SIDE MOULDING RH	Necessary	50.00 FL	*50.00 FL
5	1		*TAILGATE	Buckled	1,637.40 FL	*1,321.40 FL
6	1		*TAILGATE SPOILER	Deformed	1,107.70 FL	*1,107.70 FL
7	1		*TAILGATE LOGO	Necessary	54.30 FL	*54.30 FL
8	1		*TAILGATE 1/4 GARNISH RH	Not Necessary	38.00 FL	*- FL
9	1		*TAILGATE 1/4 GARNISH LH	Not Necessary	38.00 FL	*- FL
10	1		*TAILGATE EMBLEM-SKYACTIV	Necessary	75.20 FL	*75.20 FL
11	1		*TAILGATE EMBLEM-CX5	Necessary	47.60 FL	*47.60 FL
12	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	450.20 FL	*- FL
13	1		*TAILGATE INNER LOCK	Bent	269.30 FL	*174.50 FL
14	1		*TAILGATE INNER LOCK CATCH	Not Necessary	45.60 FL	*- FL
15	1		*TAILGATE RUBBER BEADING	Cut	185.90 FL	*185.90 FL
16	1		*TAILGATE INNER TRIM BOARD	Cut	313.40 FL	*256.40 FL
17	1		*TAILGATE INNER TRIM LH	Deformed	413.50 FL	*115.00 FL
18	1		*TAILGATE INNER TRIM RH	Deformed	413.50 FL	*115.00 FL
19	1		*TAILGATE INNER TRIM TOP	Not Necessary	55.00 FL	*- FL
20	1		*TAILGATE INNER HANDLE	Missing	183.30 FL	*183.30 FL
21	1		*TAILGATE OUTER HANDLE	Cracked	330.00 FL	*330.00 FL
22	1		*TAILGATE RUBBER	Not Necessary	183.30 FL	*- FL
23	1		*TAILGATE DAMPER LH	Not Necessary	244.00 FL	*- FL
24	1		*TAILGATE DAMPER RH	Not Necessary	244.00 FL	*- FL
25	1		*TAILGATE LAMP RH	Not Necessary	495.00 FL	*- FL
26	1		*TAILGATE LAMP LH	Cracked	495.00 FL	*466.60 FL
27	1		*TAILGATE HINGE LH	Not Necessary	38.60 FL	*- FL
28	1		*TAILGATE HINGE RH	Not Necessary	38.60 FL	*- FL
29	1		*TAILGATE WIRE HARDNESS	Not Necessary	596.00 FL	*- FL
30	1		*REAR WIPER MOTOR	Not Working	320.10 FL	*320.10 FL
31	1		*REAR WIPER BLADE	Cut	58.00 FL	*58.00 FL
32	1		*REAR WIPER ARM	Cut	68.10 FL	*68.10 FL
33	1		*REAR TAILLAMP RH	Cracked	588.00 FL	*588.00 FL
34	1		*REAR TAILLAMP LH	Cracked	588.00 FL	*588.00 FL
35	1		*TAILGATE OPEN SWITCH	Not Necessary	99.60 FL	*- FL
36	1		*REAR TAILLAMP PANEL LH	Not Necessary	285.00 FL	*- FL
37	1		*REAR TAILLAMP PANEL RH	Not Necessary	285.00 FL	*- FL
38	1		*REAR BUMPER	Deformed	1,278.90 FL	*1,218.00 FL
39	1		*REAR BUMPER REINFORCEMENT	Bent	614.10 FL	*584.80 FL
40	1		*REAR BUMPER BRACKET RH	Not Necessary	116.00 FL	*- FL
41	1		*REAR BUMPER BRACKET LH	Not Necessary	116.00 FL	*- FL
42	1		*REAR BUMPER TOWING COVERS (2 Pcs)	Cut (1 Pc only)	192.00 FL	*8.00 FL
43	1		*REAR BUMPER TOP RETAINER RH	Not Necessary	38.00 FL	*- FL
44	1		*REAR BUMPER TOP RETAINER LH	Not Necessary	38.00 FL	*- FL
45	1		*REAR BUMPER REFLECTOR LH	Not Necessary	186.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR BUMPER REFLECTOR RH	Not Necessary	186.00 FL	*- FL
47	1		*REAR BUMPER SIDE RETAINER LH	Deformed	68.00 FL	*32.40 FL
48	1		*REAR BUMPER SIDE RETAINER RH	Deformed	68.00 FL	*32.40 FL
49	1		*REAR NUMBER PLATE LAMP LH	Not Necessary	47.60 FL	*- FL
50	1		*REAR NUMBER PLATE LAMP RH	Not Necessary	47.60 FL	*- FL
51	1		*REAR END PANEL	Repair	519.00 FL	*- FL
52	1		*REAR END PANEL INNER GARNISH	Deformed	476.10 FL	*476.10 FL
53	1		*REAR END PANEL INNER CROSSMEMBER	Repair	78.20 FL	*- FL
54	1		*REAR FENDER INNER TRIM BOARD LH	Not Necessary	413.50 FL	*- FL
55	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	413.50 FL	*- FL
56	1		*REAR FENDER WHEEL PROTECTOR LH	Deformed	375.00 FL	*375.00 FL
57	1		*REAR FENDER WHEEL PROTECTOR RH	Deformed	375.00 FL	*375.00 FL
58	1		*REAR SPARE TYRE BOARD	Not Necessary	645.90 FL	*- FL
59	1		*REAR SPARE TYRE PANEL	Not Necessary	1,150.00 FL	*- FL
60	1		*REAR EXHAUST SILENCER	Repair	1,754.00 FL	*- FL
61	1		*REAR EXHAUST MOUNTING	Not Necessary	38.00 FL	*- FL
62	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	78.40 FL	*- FL
63	1		*CENTRE EXHAUST PIPE	Not Necessary	1,780.00 FL	*- FL
64	1		*REAR KEYLESS CONTROL	Not Necessary	237.60 FL	*- FL
65	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*20.00 FS
66	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	50.00 FS	*20.00 FS
67	1		*REAR WINDSCREEN GLASS CLEANER & PRIMER	Necessary	50.00 FS	*20.00 FS
68	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
69	1		*REAR FENDER INNER SHIELD CLIPS	Necessary	100.00 FS	*30.00 FS
70	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
71	1		*SET REAR END PANEL INNER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
72	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
73	1		*REAR SPARETYRE INSULATOR PAD	Not Necessary	180.00 FS	*- FS
74	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
75	1		*REAR WINDSCREEN SOLAR FILM	Necessary	280.00 FS	*150.00 FS
76	1		*REAR CAMERA	Not Necessary	680.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,814.40	10,975.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,582.88	2,087.16
Total Parts (\$\$)	20,231.52	8,888.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ON ACCIDENT AREA	New	1,800.00	600.00
2	SPRAY PAINTING ON ACCIDENT AREA	New	1,800.00	600.00
3	CHECK & REPAIR WIRING SYSTEM	New	80.00	30.00
4	R&R INNER TRIM, INNER GARNISH TO ASSIST REPAIR	New	120.00	60.00
5	R&R AND RESET REAR BUMPER SENSOR	New	120.00	40.00
6	R&R REAR WINDSCREEN GLASS	New	150.00	100.00
7	R&R AND RE-ADJUST REAR EXHAUST SYSTEM	New	280.00	60.00
8	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	280.00	0.00
9	R&R TAILGATE COMPONENTS	New	120.00	60.00
10	TOWING FEE-KING DOLLEY	New	180.00	0.00
Gross Labour Cost (\$\$)			4,930.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >