

ASS. REC. BY:

REF: CS/SM019021890/02d3

Special Instruction:

Assigner: SUN PH

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 12/12/19 @ 9:06am

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No.: SHB1226D Insured: SAS 2467Mat Workshop n/s: SMRT Tel: 6866 2672of Go woodlands Ind. park E4Policy No: _____ Claim No: CM1D1905757/GPL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 9/12/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 10:10am @ 12/12/19 Person Contacted: Alex Vehicle: IN / OUTDate/Time Action/Instruction Follow up ✓SHB1226D - CS3/A1917017731/Syb3012 DM: 10/19/19SAS 2467M - CS3/ASM19021791/Hyph DM: 01/12/201913/12/19 @ 1:44pm revised to Mr Guoh by email.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 12 December 2019 9:06 AM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) (BThaiyalN@smrt.com.sg); 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Gnoh, Pau Loong; Ye, Yong Kang Melvin; Henry, Irene James; Choo, Thelma
Subject: CMTD1905757/GPL - LKK/ SGJ2467M & SHB1226D ACC ON 09.12.19
Attachments: 2042 - 1226.pdf

Without Prejudice

Our Reference: CMTD1905757/GPL
Your Reference: SHB1226D

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that **Mr. Gnoh Pau Loong** is the handler of this case who can be contacted at 63295 327/
PauLoong.Gnoh@sompo.com.sg.

Please be informed that we have appointed **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make the arrangement to survey for **SHB1226D** on a without prejudice basis and revert your report upon completion of survey to my colleague, Mr. Pau Loong.

Thank you.

Our office will be closed on Christmas, New Year's Eve and New Year Day. Business will resume on 26th December 2019 and 2nd January 2020 respectively.

We wish you a Merry Christmas and a Happy New Year!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) <BThaiyalN@smrt.com.sg>

Sent: Wednesday, December 11, 2019 4:41 PM

To: 'motorsurvey@sompo.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/ARC/ARC)

<YewChung@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis)

<ngsiuching@smrt.com.sg>; Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis)

<kimming.chin@smrt.com.sg>; Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis)

<ANGBANGKIEN@smrtlan.com.sg>

Subject: RE: SHB1226D - Sompo Insurance

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB1226D** within 48 hours according to GIA guide line, involving your insured **SGJ2467M**

Vehicle in Woodlands

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 13 December 2019 1:44 PM
To: 'Teo, Grace'; assignments; Gnoh, Pau Loong
Cc: 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; 'Choo, Thelma'; SUR
Subject: RE: CMTD1905757/GPL - LKK/ SGJ2467M & SHB1226D ACC ON 09.12.19
Attachments: CSSMO19021890Qqd3.pdf

Dear Mr Gnoh,

Enclosed herewith preliminary advice of SHB 1226D.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 12 December 2019 10:11 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Choo, Thelma' <thelma.choo@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1905757/GPL - LKK/ SGJ2467M & SHB1226D ACC ON 09.12.19

Dear Sir/Mdm,

Thank you for the assignment.

Wishes you a Merry Christmas & Happy New Year 2020



Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 12 December 2019 9:06 AM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) (BThaiyalN@smrt.com.sg) <BThaiyalN@smrt.com.sg>; 'admin-d@lkkauto.com' <[admin-](mailto:admin-d@lkkauto.com)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905757/GPL

Date: 13th December 2019

Our Ref: CS/SMO19021890/Qqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHB 1226D


We thank you for the instruction on 12/12/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/12/2019 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ <u>23,139.29</u>
Revised Estimate Amount	: S\$ <u>3,766.50</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have not authorized repair.

Yours faithfully

Sun Pin
Automobile Assessor

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB1226D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	22R5929376
Chassis No.:	JTDKN36U705721165
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	05 Mar 2014
First Registration Date:	05 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Mar 2022
PARF Rebate Amount:	\$5,857.00
Intended COE Rebate Details	
COE Expiry Date:	04 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$16,338.00
Total Rebate Amount:	\$22,195.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Dec 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/12/2019 09:53
Date Of Accident	09/12/2019 15:50
Exact Location Of Accident	BEDOK NORTH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1226D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY

Vehicle Category	TAXI
------------------	------

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	NG SWEE PING
NRIC No	S0232549G
Date Of Birth	01/01/1952
Occupation	OUTDOOR
Date Of Driving Pass	26/10/1977
Driving Experience	42 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	538
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG BEDOK NORTH ROAD AT THE RIGHT LANE WHEN THE FRONT VEHICLE SKJ3506E BRAKE AND STOPPED. I APPLIED MY BRAKE AND ABLE TO STOP IN TIME. A FEW SECOND LATER, SUDDENLY THE VEHICLE SGJ2467M FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY TAXI. DUE TO THE GREAT IMPACT, IT PUSHED MY TAXI SURGED FORWARD AND HIT ONTO THE REAR OF THE VEHICLE SKJ3506E. WHEN I ALIGHTED AND CHECKED, I THEN REALISED THAT IT WAS A CHAIN COLLISION INVOLVED OF FIVE VEHICLES INCLUDING MINE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ2467M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EILEEN CHAN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKJ3506E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver DAVID
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLF2913D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SJP4983J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number : TAX/12/19/2042
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1226D

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-9693-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Sompo Insurance Singapore Pte. Ltd
 Accident Date and Time : 09/12/2019 07:50 AM
 Vehicle Age(in Months) : 69

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation					Surveyor Approval				Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	• / Nec
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	0	0.00	Check	• X SVC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	• / CR4
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	• / DD
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			WIRE, ENGINE ROOM, NO.3	1	242.00	242.00	10.00	217.80	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0.00	Check	• X SVC
One Time Key In	Main			RADIATOR ASSY	1	1,495.90	1,495.90	25.00	1,122.68	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			COOLANT	1	12.00	12.00	0.00	12.00	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			BUMPER CLIPS	1	1.61	1.61	25.00	1.21	Replace	1	1.21	Replace	• / Nec

3403.41

Total Spare Part Cost	14,092.59	Surveyor Total	2,304.32
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20.00
Final Spare Part Cost	11,274.07	Final Sur Total	1,843.46

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	• / NEC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	• / short
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0.00	Check	• X SVC
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0.00	Check	• X SVC
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0.00	Check	• X SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	579.60	579.60	25.00	509.70	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0.00	Check	• X SVC
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give	• X SVC
One Time Key In	Main			STICKER DECAL 8555 8888	1	21.80	21.80	0.00	21.80	Replace	0	0.00	Not Give	• X SVC
Standard	Main		6505517	BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	• / Dh
Standard	Main		6505515	BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0.00	Check	• X SVC
Standard	Main		6505516	BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0.00	Not Give	• X SVC
Standard	Main		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0.00	Not Give	• X SVC

2093.30

Total Spare Part Cost	14,092.58	Surveyor Total	2,304.32
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20.00
Final Spare Part Cost	11,274.07	Final Sur Total	1,843.48

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505539	BUMPER REINFORCEMENT FRT	1	488.40	488.40	25.00	373.80	Replace	0	0.00	Check	X SVC
Standard	Main		6505544	ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505543	ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505574	DEFLECTOR, RADIATOR RH	1	83.50	83.50	25.00	62.63	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505561	DEFLECTOR, RADIATOR LH	1	77.00	77.00	25.00	57.75	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0.00	Check	X SVC
Standard	Main		6505439	FOG LAMP RH	1	295.20	295.20	10.00	265.68	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505438	FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505458	LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505538	EMBLEM FRONT	1	66.50	66.50	25.00	64.88	Replace	1	64.88	Replace	/ Nec
Standard	Main		6505518	HOOD END PANEL SEAL	1	35.50	35.50	25.00	26.63	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505516	BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	/ SCH
Standard	Main		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0.00	Check	X SVC
Standard	Main		6505508	UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0.00	Not Give	X SVC
Standard	Main		8084300	A/C CONDENSER	1	1,181.90	1,181.90	25.00	886.43	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505786	RADIATOR ASSY, UPPER	1	679.60	679.60	25.00	509.70	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505548	BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	/ DN
Standard	Main		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505547	BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0.00	Check	X SVC
Standard	Main		6505546	ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check	X SVC
Standard	Main		6505545	ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check	X SVC
Standard	Main		6505617	BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0.00	Not Give	X SVC

6462.60

Total Spare Part Cost	14,092.59	Surveyor Total	2,304.32
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20.00
Final Spare Part Cost	11,274.07	Final Sur Total	1,843.46

SMRT Recommendation										Surveyor Approval				
BCM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		6505618	BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505619	BUMPER LIP REAR	1	228.00	228.90	25.00	171.68	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505522	END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0.00	Check	X SVC
Standard	Main		6505636	TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	/ PD
Standard	Main		6505497	TAILGATE DOOR HINGE L/RH	2	58.30	116.60	25.00	87.45	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505500	TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.08	Replace	/ Jumper
Standard	Main		6505637	TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0.00	Check	X SVC
Standard	Main		6505323	TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	0.00	Old Dam	X old change SVC
Standard	Main		6505639	EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505640	NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505642	NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505643	NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0.00	Not Give	X SVC
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	0.00	Old Dam	X old damage SVC
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Not Give	X SVC
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Not Give	X SVC
Standard	Main		6505462	TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0.00	Not Give	X SVC

Total Spare Part Cost 14,092.50

Surveyor Total 2,304.32

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 11,274.07

Final Sur Total 1,843.46

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	507.00	200.00	/
2	Main	TO REPAIR REAR PORTION	1,014.00	400.00	/
Total:			1,521.00	600.00	

1268.50

1921 800

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	/
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00	
4	Main	TO RESPRAY REAR BUMPER	378.00	200.00	/
5	Main	TO RESPRAY BUMPER BEAM	180.00	0.00	
6	Main	TO RESPRAY REAR PANEL	180.00	0.00	
7	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00	
8	Main	TO RESPRAY TAIL GATE	378.00	200.00	/
9	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00	
Total:			2,214.00 2,374	600.00	

Other Cost Detail


S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	/
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	/
3	Main	TO CONDUCT RADIATOR PRESSURE CHECK	120.00	0.00	
4	Main	TO TOP UP A/C GAS	120.00	0.00	
5	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0.00	
6	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00	0.8725
7	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00	
8	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00	/
9	Main	TO REPLACE SUNDRY PARTS	120.00	20.00	/
10	Main	TO WASH AND VACUUM	80.00	0.00	
Total:			1,276.88	366.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	11,274.07	1,843.46
Total Labour Cost	1,521.00	600.00
Total Spray Painting	2,214.50	600.00
Other	1,276.88	366.88
Overall Total	16,285.95	3,871.20
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	16,300.00	3,850.00
Surveyor Approved Amount		3,850.00
No of Repair Days*	11	4

Remarks: - Lump Sum Repair. Take after spray photo.

Surveyor Name: Sun Pin (LKK)

Signature:  

Survey Date: 12/12/2019

Repair day - 4 days.
L/S

5047.94

23,139.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section A - Accident Details

Registration Number	SHB1226D
Case Reference Number	TAX/12/19/2042
Registration Date	5/3/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	NG SWEE PING
Type of Accident	Head to Rear
Accident Date and Time	8/12/2019 3:50 PM
Accident Reported Date and Time	10/12/2019 9:53 AM
is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24104768
Special Instruction to ARC, if any	DROVE IN
Prepared Date and Time	11/12/2019 4:25 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,971.00	\$800.00
Total Spray Cost	\$2,574.00	\$700.00
Total Spare Part Cost	\$11,930.28	\$2,200.65
Total Other Cost	\$1,276.88	\$366.88
TOTAL COST	\$17,752.17	\$4,067.53
Lump Sum Total	\$17,750.00	\$4,050.00 (L/S)
Number of Repair Days	11.0	6.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / Sompo
ARC / Surveyor Sign Off Date	17/12/2019 8:56 AM	16/12/2019 9:07 PM
Signature		
Remarks	Initial estimate = 11 days SUP = 2 days	Lump Sum Repair, Take after spray photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1912-0460	Invoice Number	
Quotation Date	30.12.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$250.00	\$200.00
TO REPAIR FRONT SUPPORT PANEL	\$200.00	\$0.00
TO REPAIR FRONT PORTION	\$507.00	\$200.00
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
Total Labour	\$1,971.00	\$800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,574.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO CONDUCT RADIATOR PRESSURE CHECK	\$120.00	\$0.00
TO TOP UP A/C GAS	\$120.00	\$0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$120.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,276.88	\$366.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52114-47140	BRACKET, FR BUMPER	0.00	\$110.40	0.00	\$0.00	Replace	Check X
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace
		52125-47903	COVER, FR BUMPER HOLE LH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given X
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given X
		62113-47160	WIRE, ENGINE ROOM, NO 3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given X
		53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check X
		16400-37230	RADIATOR ASSY	0.00	\$1,496.90	0.00	\$0.00	Replace	Not Given X
			COOLANT	0.00	\$12.00	0.00	\$0.00	Replace	Not Given X
		52161-16010	BUMPER CLIPS	1.00	\$1.61	25.00	\$1.21	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		89997-30070	ANTENNA ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X
		54716-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Check X
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	0.00	\$0.00	Replace	Check X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
		64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given X
		58416-47030B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given X
		58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check X
		69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given X
		69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given X
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL SMRT	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Check X
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given X
		52511-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
		53293-47040	DEFLECTOR, RADIATOR RH	0.00	\$83.50	0.00	\$0.00	Replace	Not Given X
		53294-47030	DEFLECTOR, RADIATOR LH	0.00	\$77.00	0.00	\$0.00	Replace	Not Given X
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check X
		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given X
		81220-12230	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given X
		81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 81 Woodlands Industrial Park EA, Singapore 757105
 FAX Number: 63655522
 Estimator Telephone Number: 68922023
 Accident Reporting Number: 5662972

Date Generated : 27/12/2019

User ID : PehJoon

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
75310-47010			EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace ✓
53395-47020			HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given ✗
76851-47020			BUMPER LIP FRT	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
52618-47050			BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check ✓
51410-12105			UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given ✗
85460-47150			A/C CONDENSER	0.00	\$1,181.90	0.00	\$0.00	Replace	Not Given ✗
G9010-47031			RADIATOR ASSY, UPPER	0.00	\$679.60	0.00	\$0.00	Replace	Not Given ✗
52159-47905			BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
52576-47020			BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given ✗
52575-47020			BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given ✗
52023-12240			BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check ✗
52016-47030			ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check ✗
52015-47050			ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check ✗
76089-47020			BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given ✗
76087-47020			BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given ✗
76891-47020			BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given ✗
58307-47080			END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check ✗
87005-47241			TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace ✓
85810-47010			TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given ✗
69350-47030			TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace ✓
87881-47022			TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check ✗
76801-47070-80			TAILGATE OUTSIDE GARNISH	1.00	\$504.90	100.00	\$0.00	Replace	Old Damage ✗
75310-47020			EMBLEM REAR	0.00	\$60.30	0.00	\$0.00	Replace	Not Given ✗
75374-47051			NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given ✗
75442-47030			NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given ✗
75443-47030			NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given ✗
81581-47170			TAIL LAMP LH	1.00	\$548.40	100.00	\$0.00	Replace	Old Damage ✗
52562-47010			TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given ✗
52563-47010			TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given ✗
81551-47180			TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given ✗
Total					\$17,994.62		\$2,304.33		

2750.81/
 - 207

 2200.65/
 + 800.00/
 + 1066.88/

 4067.53/
 L/S \$4050/
 6 days

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
52114-47140			BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace ✓
52021-47023			BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given ✗
52023-12240			BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
Total					1,093.70		448.48		

CRA
 old damage & SVC
 PD
 BT
 BT

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	7AX/12/19/2042	Date of Collection	13/12/19
Vehicle No	SHB 1226 D	Date of Request	16/12/19
Vehicle Model	70307A PRIUS	Number of Days to Extend (If any)	4 DAYS 2 days

S/N	Part Number	Part Description	Quantity	Unit Price	
	5209,10,11	Bracket Frt Bumper		\$110.40	/ CRA
	5112,13,14,15 5116	Bumper Reinforcement Frt		\$495.40	X old damage
	5104,105,08	Bumper Reinforcement Rear		\$205.70	/ DD
	510,11	Arm Sub Assy RR Bumper LH		\$139.60	/ BT
	5109,11	Arm Sub Assy RR Bumper RH		\$139.60	/ BT
	5106,07	To Repair End Panel		\$250.00	200
	5212,13,14,15	To Repair Support Panel		\$200.00	X old damage
		To Respray End panel		\$180.00	100
		To Respray Support panel		\$180.00	X old damage

I, (Name) CHAI

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....


Signature of person making this declaration
 [To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO19021890/Qqd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 30-01-2020	
Code : SMO			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGJ 2467M	Veh. Inspected	SHB 1226D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905757/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	12/12/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U705721165	Colour	MAROON
Odometer	899209	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	5 mm
L/H Front Tyre	195/65 R15	FIRENZA	5 mm
R/H Rear Tyre	195/65 R15	FIRENZA	5 mm
L/H Rear Tyre	195/65 R15	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/12/2019	Inspection Date	12/12/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1226D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER CLIPS (DISC 25%)	NECESSARY	1.61	1.21
1	BUMPER FRT (DISC 25%)	DENTED	482.00	361.50
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.88
1	BUMPER LIP FRT (DISC 25%)	SCRATCHED	139.60	104.70
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	TAILGATE DOOR LOCK (DISC 25%)	JAMMED	444.10	333.08
1	BRACKET, FR BUMPER (DISC 25%)	CRACKED	110.40	82.80
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	NUMBER PLATE FRAME (SN)	CRUMPLED	12.00	12.00
1	NUMBER PLATE (SN)	DENTED	15.00	15.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	SHORTED	180.00	180.00
1	BRACKET, FR BUMPER	SERVICEABLE	110.40	-
1	COVER, FR BUMPER HOLE LH	SERVICEABLE	18.50	-
1	COVER, FR BUMPER HOLE RH	SERVICEABLE	18.50	-
1	WIRE, ENGINE ROOM, NO.3	SERVICEABLE	242.00	-
1	SUPPORT SUB-ASSY	SERVICEABLE	1,460.40	-
1	RADIATOR ASSY	SERVICEABLE	1,496.90	-
1	COOLANT	SERVICEABLE	12.00	-
1	ANTENNA. ELECTRICAL LOWER REAR	SERVICEABLE	157.40	-
1	END PANEL COVER, DECK TRIM HOLE	SERVICEABLE	46.10	-
1	END PANEL COVER, DECK TRIM, RR	SERVICEABLE	121.10	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	BOX, DECK FLOOR, RR	SERVICEABLE	649.70	-
1	BOX, RR FLOOR, BOARD	SERVICEABLE	679.60	-
1	SPARE TYRE PANEL	SERVICEABLE	667.70	-
1	TAILGATE LOCK, COVER	SERVICEABLE	15.70	-

Report Ref No. CS/SMO19021890/Qqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STRIKER, BACK DOOR	SERVICEABLE	48.90	-
1	NUMBER PLATE	SERVICEABLE	15.00	-
1	NUMBER PLATE FRANE	SERVICEABLE	12.00	-
1	STICKER DECAL SMRT	SERVICEABLE	7.80	-
1	STICKER DECAL 6555 8888	SERVICEABLE	21.60	-
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	BUMPER ENERGY ABSORBER FRT	SERVICEABLE	78.80	-
1	BUMPER REINFORCEMENT FRT	SERVICEABLE	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	SERVICEABLE	250.40	-
1	DEFLECTOR, RADIATOR RH	SERVICEABLE	83.50	-
1	DEFLECTOR, RADIATOR LH	SERVICEABLE	77.00	-
1	BUMPER GRILLE SUB-ASSY, LOWER	SERVICEABLE	311.10	-
1	FOG LAMP RH	SERVICEABLE	295.20	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	LENS & BODY, FR TURN LH	SERVICEABLE	511.80	-
1	HOOD END PANEL SEAL	SERVICEABLE	35.50	-
1	BUMPER FRT ABSORBER LOWER	SERVICEABLE	127.70	-
1	UNDER COVER CENTER	SERVICEABLE	448.30	-
1	A/C CONDENSER	SERVICEABLE	1,181.90	-
1	RADIATOR ASSY, UPPER	SERVICEABLE	679.60	-
1	BUMPER SIDE RETAINER RR/LH	SERVICEABLE	94.80	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	BUMPER REINFORCEMENT REAR	SERVICEABLE	205.70	-
1	ARM SUB-ASSY, RR BUMPER LH	SERVICEABLE	139.60	-
1	ARM SUB-ASSY, RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER LIP COVER RR/LH	SERVICEABLE	72.20	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER LIP REAR	SERVICEABLE	228.90	-
1	END PANEL	SERVICEABLE	602.10	-
2	TAILGATE DOOR HINGE LH / RH @\$58.30	SERVICEABLE	116.60	-
1	TAILGATE DOOR WEATHER STRIP	SERVICEABLE	353.40	-

Report Ref No. CS/SMO19021890/Qqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EMBLEM REAR	SERVICEABLE	60.30	-
1	NAME PLATE (HYBRID)	SERVICEABLE	51.90	-
1	NAME PLATE (PRIUS)	SERVICEABLE	60.80	-
1	NAME PLATE (TOYOTA)	SERVICEABLE	51.90	-
1	TAIL LAMP BRACKET, RH	SERVICEABLE	30.70	-
1	TAIL LAMP BRACKET, LH	SERVICEABLE	30.70	-
1	TAIL LAMP RH	SERVICEABLE	557.80	-
1	TAILGATE OUTSIDE GARNISH (SERVICEABLE)	OLD DAMAGED	504.90	-
1	TAIL LAMP LH (SERVICEABLE)	OLD DAMAGED	548.40	-
1	BUMPER REINFORCEMENT FRT (SERVICEABLE)	OLD DAMAGED	498.40	-
			19,221.11	2,750.81
	LABOUR			
	PANEL BEATING & BODY WORK.		1,971.00	800.00
	SPRAY PAINT.		2,574.00	700.00
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		296.88	296.88
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO CONDUCT RADIATOR PRESSURE CHECK.	NOT NECESSARY	120.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REPLACE SUNDRY PARTS.		120.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			-	-
			-	-
			5,821.88	1,866.88
	GRAND TOTAL		25,042.99	4,617.69

Report Ref No. CS/SMO19021890/Qqd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,050.00
---	--	--	----------

Report Ref No. CS/SMO19021890/Qqd3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng_AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.