

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 22173

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1455/2019/NS
Date : 10-Dec-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Peh Chai Peng
Address : Blk 642A Punggol Drive
#11-345
Singapore 821642
Telephone : HP +65 81332230
Type of Claim : Own Damage Claim
Policy No. : 2100445230-03
Vehicle No : **SGY 1128 U**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Dec-15
Engine No : CZC 504868
Chassis No : WAUZZZ8V5G1052582
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Dec-19
Place of Accident : Suntec Exit Parking To Main Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGY 1128 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1000 ✓	
3	To respray front bumper and bonnet.	\$ 2,000.00 1100 ✓	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGY 1128 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>rehd</i>	\$ 1,830.00	✓ 1464
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$ 170.00	+
3	FRONT BUMPER COVER TRIM - LH <i>neu</i>	\$ 148.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>neu</i>	\$ 148.00	+
5	FRONT BUMPER PULL STRAP - LOWER <i>neu</i>	4 \$ 187.00	+
6	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>neu</i>	\$ 99.00	+
8	RADIATOR GRILLE <i>cracked</i>	\$ 637.00	✓ 509.20
9	RADIATOR GRILLE - COVER <i>not new</i>	\$ 89.00	7 X
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>neu</i>	\$ 660.00	7 X
11	FRONT BUMPER FOAM FILLER PIECE <i>neu</i>	\$ 125.00	7 X
12	FOAM FILLER PIECE COVER <i>cracked</i>	\$ 51.00	7 40.40
13	SIGNAL HORN - LH HIGH TONE <i>neu</i>	\$ 182.00	X
14	BONNET <i>Repis</i>	\$ 2,898.00	+
15	BONNET ATTACHMENT PARTS	\$ 149.00	+
16	BONNET CATCH HOOK <i>neu</i>	\$ 81.00	+
17	BONNET STRIKER - LH / RH	2 \$ 200.00	+
✓ 18	BONNET EDGE PROTECTION - FRONT <i>neu</i>	\$ 25.00	✓ 19.92
19	BONNET LID LOCK <i>neu</i>	2 \$ 367.00	+
20	BONNET BOWDEN CABLE <i>neu</i>	\$ 53.00	+
SUB TOTAL SPARE PARTS		: \$	<u><u>8,134.00</u></u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGY 1128 U

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	WATER BOX ADAPTER SEAL - LH	\$	12.00 +
22	BONNET CATCH HOOK	\$	58.00 +
23	CAUTION SIGN STICKER	NEC \$	12.00 ✓ 9.76
24	AIRCON STICKER	NEC \$	7.00 ✓ 5.12
25	HEADLIGHT - LH	\$	1,825.00 ✓ 1460
26	LIFT CYLINDER - LH	\$	181.00 + 144.80
27	RADIATOR AIR GUIDE - LH / RH	2 \$	22.00 +
28	RADIATOR AIR GUIDE - UPPER CENTRE	\$	11.00 +
29	SUNDRIES	\$	300.00 ? 23.36
TOTAL SPARE PARTS		: \$	10,562.00
TOTAL LABOUR CHARGES		: \$	5,002.00
GRAND TOTAL		: \$	15,564.00 20,311

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 12/12/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Steve 3/1/20

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/1455/2019/NS
Date 3-Jan-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SGY 1128 U
Model No Audi A3 Sedan 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Front lock carrier / DR	\$ 663.00	547.60
2	Mix coolant / MC X nn	\$ 84.00	
		\$ 747.00	

Labours

- | | | | |
|---|--|-----------------|---------|
| 1 | To remove and reinstall aircond condenser, radiator and additional radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. | S/N \$ 1,200.00 | ✓ ✓ |
| 2 | To remove and renew front lock carrier and align to position. | \$ 2,800.00 | 1250. ✓ |

Labours total	\$ 4,000.00
Parts total	\$ 747.00
TOTAL	\$ 4,747.00

Adrian Ling
Sigs.

For Premium Automobiles Pte Ltd

Authorised Signature