



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA19021905/Kvf3e2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 08-07-2020



Code : AWA

### 1. Policy Particulars :- OWN DAMAGE

<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SCL 89X
<b>Policy No.</b>	BVPCSB0321411901	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	SCL 89X/HLF	<b>Excess (\$)</b>	2,500.00
<b>Assign From</b>	HEW LEE FONG	<b>Assign Date</b>	12/12/2019

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	PORSCHE PANAMERA 4S (A)	<b>c.c</b>	2894
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	WP0ZZZ97ZHL123971	<b>Colour</b>	METALLIC GREY
<b>Odometer</b>	55194	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	275/35Z R21	PIRELLI	8 mm
<b>L/H Front Tyre</b>	275/35Z R21	PIRELLI	8 mm
<b>R/H Rear Tyre</b>	315/30Z R21	PIRELLI	8 mm
<b>L/H Rear Tyre</b>	315/30Z R21	PIRELLI	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE UNDERCARRIAGE COMPONENTS.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/12/2019	<b>Inspection Date</b>	12/12/2019
<b>Survey held at</b>	160 SIN MING DRIVE #06-02		
<b>Repairer</b>	MBM WHEELPOWER PTE LTD		

### 5a. Remarks

A)THE MARKET VALUE IS S\$386,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**