

# MG SOLUTION

23 Kaki Bukit Avenue 4 (South Wing)

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1374

Reg. No: 2014

0.0

1,258. +  
 240.3 +  
 320. +  
 180.3 +  
 211.3 +  
 850. +  
 580. +  
 124.8 +  
 398. +  
 66.5 +  
 90. +  
 182.3 +  
 103. +  
 520. +  
 422. +  
 725. +  
 189.2 =  
 6,460.7 \*  
 6,460.7 x  
 75. %  
 4,845.525 \*  
 30. +  
 30. +  
 20. +  
 20. +  
 60. +  
 10. +  
 200. =  
 370. \*  
 800. +  
 800. +  
 60. +  
 30. +  
 60. +  
 50. +  
 50. +  
 80. +  
 120. =  
 2,050. \*  
 4,845.53 +  
 370. +  
 2,050. =  
 7,265.53 \*  
 7,265.53 x  
 80. %  
 5,812.424 \*  
 0.0

notify  
 ting  
 resurvey  
 ation  
 ; Prejudice" basis  
 id  
 ; surveyed and  
 Insurance Company

LIST  
 E  
 16.90  
 10.00 +  
 2.00 +  
 15.30 +  
 0.30 -  
 0.00 -  
 0.30 -  
 1.30 -  
 0.00 -  
 0.00 -  
 4.80 -  
 5.00 ✓ 398  
 6.50 -  
 0.00 90.  
 4.60 182.30  
 3.00 ✓  
 0.00 520  
 2.00 422

TO : AIG  
 ATTENTION : MOTOR CLAIMS DEPT  
 ESTIMATE REPORT :  
 Jia Le  
VEHICLE DETAILS  
 VEHICLE NO : SLT2897T  
 MODEL : TOYOTA CHR HYBRID  
 CHASSIS NO  
ACCIDENT DETAILS DATE : 11/12/2019  
 TIME : 08:45HRS  
 THIRD PARTY REQUESTOR / CONTACT : JA

CLAIM DETAIL : PARTS

S/N	DESCRIPTION
1	BOOT LID <i>Repair Dent</i>
2	BOOT LID LOGO <i>3 new</i>
3	BOOT LID EMBLEM 'CH-R'
4	BOOT LID EMBLEM 'HYBRID SYNERGY DRIVE' <i>new</i>
5	BOOTLID WEATHERSTRIP <i>cut</i>
6	BOOTLID LOCK <i>changed</i>
7	BOOTLID DETECTOR <i>changed</i>
8	BOOTLID WINDSCREEN MOULDING <i>new</i>
9	REAR BUMPER <i>changed</i>
10	REAR BUMPER LOWER LID <i>changed</i>
11	REAR BUMPER SIDE RETAINER <i>new</i>
12	REAR BUMPER REINFORCEMENT <i>But.</i>
13	REAR BUMPER TOWING COVER <i>Missing</i>
14	REAR BUMPER REFLECTOR <i>LH changed</i>
15	REAR BUMPER REFLECTOR HOUSING <i>cut</i>
16	REAR BUMPER BRAKE LIGHT COVER <i>changed</i>
17	REAR TAILLAMP <i>LH changed</i>
18	REAR FENDER INNER TRIM <i>LH changed</i>

L/S - \$5800

1258

398

90.

182.30

520

422