

19	REAR END PANEL <i>Damaged</i>	1	\$ 860.30	\$ 860.30	✓ 225
20	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 189.20	\$ 189.20	✓

6460.70

4845.52

TOTAL PRICE \$ 8,719.50
 LESS 25% \$ 2,179.88
 SUB TOTAL PRICE \$ 6,539.63

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	BOOTLID WINDSCRREN SEALANT <i>2 per</i>	1	\$ 100.00	\$ 100.00	30
2	BOOTLID WINDSCREEN INNER SEAL	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER CLIP(SET) <i>New</i>	1	\$ 20.00	\$ 20.00	✓
4	REAR FENDER INNER TRIM CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
5	REAR END PANEL SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	60
6	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	10
7	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

370

TOTAL \$ 560.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	80	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	800	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 160.00	30	
5	UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 120.00	50	
8	TRANSFER BOOT LID MECHANISM	\$ 80.00	✓	
9	TO REMOVE AND REFIX REAR WINDSCREEN	\$ 160.00	120	

2050

TOTAL \$ 3,540.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,099.63
 TOTAL LABOUR COST : \$ 3,540.00
 TOTAL REPAIR COST : \$ 10,639.63

APPROVED DETAILS

EXCESS :
 NO. OF DAYS :

Adrian H
 4/5 11/12/19.

06 Days.
 total: 7265.52
 4/5: 58K

RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :