

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

M/s: AIG Asia Pacific Insurance Pte Ltd

Date: 11/12/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLB4487A
 CHASSIS NO : NRE1610011710
 MAKE / MODEL : Toyota Corolla Axio 1.5 G
 DATE OF ACCIDENT : 11/12/2019
 YOUR INSURED VEHICLE NUMBER : SDU40B
 MILEAGE: 592401 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	<u>PARTS DIScription</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear boot ✓ <i>bn</i>	1PC	\$ 1,059.84	\$ 1,059.84	<i>900</i>
2	Rear boot Corolla emblem ✓ <i>NEC</i>	1PC	\$ 40.00	\$ 40.00	
3	Rear boot Axio emblem ✓ <i>NEC</i>	1PC	\$ 30.00	\$ 30.00	
4	Rear boot weatherstrip ✓ <i>cup</i>	1PC	\$ 226.00	\$ 226.00	<i>187</i>
5	Rear boot lock ✓ <i>Janed</i>	1PC	\$ 418.00	\$ 418.00	<i>174</i>
6	Rear boot lock catch ✓ <i>BT</i>	1PC	\$ 60.00	\$ 60.00	
7	R/L taillamp ? ✓ <i>CRA</i>	1PC	\$ 850.00	\$ 850.00	<i>548</i>
8	R/R taillamp ? ✓ <i>X SVC</i>	1PC	\$ 850.00	\$ 850.00	<i>X</i>
9	Rear end panel ✓ <i>bn</i>	1PC	\$ 850.00	\$ 850.00	<i>602.40</i>
10	Rear end panel top cover ✓ <i>EB pb</i>	1PC	\$ 320.00	\$ 320.00	<i>218.2</i>
11	Rear bumper ✓ <i>pb</i>	1PC	\$ 780.00	\$ 780.00	<i>598.5</i>
12	Rear bumper RH retainer ✓ <i>BN</i>	1PC	\$ 180.00	\$ 180.00	<i>96</i>
13	Rear bumper LH retainer ✓ <i>BN</i>	1PC	\$ 180.00	\$ 180.00	<i>96</i>
LIST TOTAL S\$:				\$ 5,843.84	<i>3,550.1</i>
25%DISCOUNT S\$:				\$ 1,460.96	<i>-25%</i>
				\$ 4,382.88	<i>2,662.58</i>

<u>SPECIAL NETT</u>				
2	Rear bumper clips ✓ <i>NEC</i>	1 SET	\$	100.00 <i>30</i>

<u>LABOUR CHARGES</u>				
1	To labour charge for removing out rear boot, rear end panel, and rear bumper out to facilitate replacement of damaged parts. Also to straighten rear spare tyre panel	\$	1,200.00	<i>900</i>
2	To respray rear bumper, R/L fender, rear boot, end panel and spare tyre panel (Pearl Paint)	\$	1,000.00	<i>600</i>
LABOUR TOTAL S\$:				\$ 2,200.00 <i>1,500</i>
TOTAL S\$:				\$ 6,582.88
7% GST				\$ 460.80
GRAND TOTAL S\$:				\$ 7,043.68

Repair day - 5 days.

Sun Pm (Ucle)
11/12/2019.
TP without prejudice.

Lump Sum
After panel photo
4/5
\$3,350
5 days.

P = 2,662.58
N = 30
L = 1,500

4,192.58

- 20%

3,354.06