

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G



Not Authorised
LKK
12/12/19

Take ph. After rep.:-
3 day.

8800

ESTIMATED COST: HQQ000193

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE	:	11-DEC-2019
MAKE	:	TOYOTA
MODEL	:	SIENTA 1.5 DICE 2WD
CHASSIS NO	:	NCP815216230
ENGINE NO	:	1NZE712819
SERVICE ADVISOR	:	GERINE
PAGE	:	1 OF 1

SLF9893G**LI PING**

BLK 418C FERNVALE LINK

#19-168

SINGAPORE 793418

CONTACT NO : 93628556

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT LH FENDER	<i>n</i> 622.74	<i>X</i>
1	FRONT BUMPER	<i>n</i> 1,337.80	<i>X</i>
1	SPORTS RIM	<i>n</i> 1,201.11	<i>X</i>
1	HEAD LAMP LH	<i>n</i> 1,339.70	<i>X</i>
1	FRONT LH SIDE RETAINER	<i>n</i> 67.30	<i>X</i>
1	FRONT FENDER INNER SHIELD LH	<i>n</i> 291.80	<i>X</i>
Sub Total		4,860.45	0.00

SPECIAL NETT

10	BUMPER CLIPS	<i>n</i> 50.00	<i>X</i>
Sub Total		50.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	<i>200</i>
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	<i>600</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR SPORTS RIM AND TYRE COMPONENTS & BALANCING	<i>n</i> 200.00	<i>X</i>
1	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	<i>n</i> 180.00	<i>X</i>
1	TO APPLY TUFF COAT ON AFFECTED AREAS	<i>n</i> 150.00	<i>X</i>
1	TO CHECK WIRING	<i>n</i> 100.00	<i>X</i>
Sub Total		2,230.00	0.00

SUB-TOTAL	7,140.45	0.00
GST - 7 %	499.83	0.00
TOTAL	7,640.28	0.00

ABWIN SERVICE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Acknowledged by Repairer

Prepared By

Signature:

Date: