

REPAIR ESTIMATE*

AIG

11-12-19; 09:10

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,000.00 600
	Spray Painting Charge			\$ 500.00 400
	Wiring Charge			\$ 50.00 30
	Towing Charge			\$ 90.00 receipt 7.60
	Remove/Refix Undercarriage (FRT)			\$ 400.00 X
	Front Wheel Alignment			\$ 120.00 60
	Remove/Refix Aircon & Refill Gas			\$ 150.00 100
	Re-set Frt ABS System			\$ 200.00 X
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 200
	TOTAL LABOUR			\$ 2,990.00
	ESTIMATE TOTAL			\$ 17,021.92
<i>Resul</i> <i>4p 9001w68</i> <i>6 days</i> <i>48</i> <i>12/12/19 P1450</i> <i>Return</i> <i>after</i> <i>repair</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				