

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

11-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1291 D

1 pc	n/s mirror Assy Br Br	\$ 590.00
		\$ 590.00
	Less 10%	\$ 59.00
		\$ 531.00
S/NETT		
1 set	n/s door stickers rec	\$ 100.00
	Sundry	\$ 50.00 x 1111
	To dismantle and replace the n/s wing mirror assy	\$ 150.00 \$80
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the front n/s door, etc	\$ 200.00 \$180
	To putty and spray painting on front n/s door, n/s mirror	\$ 400.00 \$280
	To apply rustproofing on the repaired and replaced panels.	\$ 80.00 \$30
		<u>\$ 1,511.00</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)
12/12/19 11:00 AM
Ramasuran@lkkauto.com
88622778 hp
(3 repair days)
LIS
aft repair photo