

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5545X**AAD1912-068***Not Authorized
Reserve B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

11 DEC 2019

SHD 5545X

JTDKB3FU103076808

TOYOTA

PRIUS

10.12.19

FCIL

15/11/2018

		PART	LIST	
1	1	REAR BUMPER	\$ <i>Per 1 m/m</i> 442.60	✓
2	1	REAR BUMPER RE-INFORCEMENT	\$ 332.70	✓ X NN
3	1	REAR BUMPER TOWING COVER	\$ <i>Per</i> 15.40	X
4	1	GUARD, REAR BUMPER, CENTER	\$ <i>Per</i> 576.30	✓
5	1	REAR BUMPER SIDE RETAINER LH	\$ <i>Per</i> 116.50	X
6	1	REAR BUMPER SIDE RETAINER RH	\$ <i>Per</i> 117.70	X
7	1	REAR TAILGATE	\$ <i>Per</i> 1,147.80	} X
8	1	REAR TAILGATE OUTER GARNISH	\$ <i>Per</i> 925.60	
9	1	COVER, REAR COMBINATION LAMP, RH	\$ <i>Per</i> 64.50	
10	1	COVER, REAR COMBINATION LAMP, LH	\$ <i>Per</i> 64.50	
11	1	BOARD ASSY, BACK DOOR TRIM	\$ <i>Per</i> 259.20	
12	1	REAR TAILGATE WEATHERSTRIP	\$ <i>Per</i> 372.30	
13	1	PANEL SUB-ASSY, BODY LOWER BACK	\$ <i>Per</i> 650.30	
14	1	TAILLAMP LOWER RH	\$ <i>Per</i> 502.00	
15	1	TAILLAMP UPPER RH	\$ <i>Per</i> 451.80	
16	1	REAR BUMPER SIDE RH	\$ <i>Per</i> 123.70	
17	1	REAR BUMPER SIDE LH	\$ <i>Per 1 m/m</i> 123.70	✓
18	1	TAILLAMP LOWER LH	\$ <i>Per</i> 502.00	} X
19	1	TAILLAMP UPPER LH	\$ <i>Per</i> 443.30	
20	1	BOARD, BACK DOOR TRIM	\$ <i>Per</i> 225.20	
21	1	COVER, DECK TRIM, REAR	\$ <i>Per</i> 126.70	
22	1	COVER, FLOOR UNDER, NO 1	\$ <i>Per</i> 175.10	
23	1	COVER, FLOOR UNDER, NO 2	\$ <i>Per</i> 241.90	
24	1	COVER, REAR FLOOR	\$ <i>Per</i> 229.90	
25	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ <i>Per</i> 56.50	
26	1	REAR FENDER LINER	\$ <i>Per</i> 139.80	
27	1	SEAL, REAR BUMPER SIDE, LH	\$ <i>Per</i> 88.50	

Trans-cab Auto Services Pte Ltd**AAD1912-068**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5545X

28	1	DUCT ASSY, QUARTER VENT, LH	\$	Sn	67.00	X
29	1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	Sn	467.00	X
30	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	Sn	355.90	X
31	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	Sn	355.90	X
TOTAL			\$		9,761.30	
25%			\$		2,440.33	
			\$		7,320.98	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	X
4	1	WINDSCREEN MOULDING	\$	nn	100.00	} X
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
6	1	REAR TAILGATE TOYOTA LOGO	\$	nn	47.00	
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	nn	52.90	
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	nn	53.50	
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	nn	80.00	} X
10	1	REAR TAILGATE STICKER '6555-3333'	\$	nn	80.00	
11	1	REAR BUMPER PROTECTOR	\$	nn	100.00	
12	1	REAR WHEEL RIM	\$	Sn	1,570.55	} X
13	1	REAR TYRE 195/65/15	\$	Sn	350.00	
14	1	REAR WHEEL RIM COVER	\$	Sn	175.80	
15	1	REAR RH BUMPER RETAINER CLIP	\$	nn	25.00	
16	1	REAR LH BUMPER RETAINER CLIP	\$	nn	25.00	
17	1SET	REAR FENDER LINER CLIP	\$	nn	35.00	
18	1	REAR BUMPER CENTER GUARD CLIP	\$	nn	35.00	
TOTAL			\$		3,675.75	
TOTAL PARTS			\$		10,996.73	

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5545X**AAD1912-068**

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 *2200*

To reinstall rear bumper parking sensor.

\$ 170.00 *500*

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 *X*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *100*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *2000***TOTAL \$ 14,340.00****Over All Total \$ 25,336.73**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(PART-BY-PART) Repair Days*20 Days**2 day,*