

# Revol Carz Garage Pte Ltd

Blk 10 Ang Mo Kio Industrial Park 2a, Ang Mo Kio Autopoint #02-18

Singapore 568047

Tel: 65551171

Fax: 62679317

## Estimated Repair of SLS49T

Name : Revol Carz Garage Pte Ltd  
Address : c/o 10 Ang Mo Kio Industrial Park 2A  
#02-18, Ang Mo Kio AutoPoint Singapore 568047

Date : 13-Dec-19

Model : AUDI A3

QTY	ITEM	AMT (\$)
-----	------	----------

List Items		Per Unit	
1 pc	Driver side front door / DD		\$ 1,500.75
1 pc	Driver side front door lock ?		\$ 600.54
1 pc	Driver side front door window regulator ?		\$ 433.21
1 pc	Driver side front door window motor ?		\$ 600.75
1 pc	Driver side front door outer handle ?		\$ 300.21
1 pc	Driver side front door outer handle cover ?		\$ 130.21
2 pc	Driver side front door hinge X		\$ 147.20
1 pc	Driver side rear door / DD		\$ 1,500.75
1 pc	Driver side rear door window regulator X		\$ 455.60
1 pc	Driver side rear door window motor X		\$ 400.21
2 pc	Driver side front door hinge -upper X DD		\$ 100.21
1 pc	Driver side front door hinge -lower X		\$ 100.21
1 pc	Driver side front door inner rubber / MC		\$ 188.86
1 pc	Driver side rear door inner rubber / MC		\$ 188.86
1 pc	Driver side front door inner board ?		\$ 1,670.21
1 pc	Driver side rear door inner board X		\$ 1,600.54
			\$ 9,918.32

### Special Nett Items

1 pc	Paint Protection (Ze Tough Protection) (Certificate) ?	\$ 1,200.00
	\$500 x 3	\$ 1,200.00

### S/N

### Labour Charge

1	To remove and refit rear electrical wiring and test for proper functioning	\$ 40.00 30
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs	\$ 80.00 50
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 2,800.00 900
4	To spray paint on the replaced and repaired parts prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available	\$ 2,500.00 900
5	To apply undercoating on the repaired and replaced panels for rust protection	\$ 60.00 50
6	Computerised 4 wheel alignment	\$ 120.00 60
7	To reset computerize fault code	\$ 60.00 30
		\$ 5,740.00

Total : \$ 16,858.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Dollars : Sixteen Thousand Eight Hundred Fifty-Eight and Cents Thirty-two Only