

INDIA INTERNATIONAL INSURANCE

Vehicle number	SJQ4940C
Make / Model	TOYOTA PICNIC
Chassis number	JTEGH23B700026543 / 2009
Accident date	10/12/19
Reference	1912-16

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	REAR BUMPER <i>de</i>	673.00	586
1	REAR BUMPER RETAINER <i>new / RH (1pc) @ 55</i>	150.00	55
1	REAR BUMPER REFLECTOR <i>new / RH (1pc) @ 87</i>	183.30	87
1	REAR BUMPER TOW COVER <i>cut</i>	83.20	55
1	REAR BUMPER SIDE BRACKET <i>RH? (1pc) X SVC</i>	144.50	X
1	REAR END PANEL <i>bt</i>	691.56	571
1	REAR END PANEL TOP GARNISH <i>X nn</i>	327.55	X
1	TAILGATE <i>X nn</i>	1507.00	X
1	TAILGATE EMBLEM LOGO <i>X nn</i>	75.00	X
1	TAILGATE EMBLEM - TOYOTA <i>X nn</i>	52.80	X
1	TAILGATE EMBLEM - PICNIC <i>X nn</i>	66.70	X
1	TAILGATE GLASS MOULDING <i>X nn</i>	172.30	X
1	TAILGATE LAMP <i>X nn</i>	599.60	X
1	TAILGATE LOCK <i>X nn</i>	428.90	X
1	TAILGATE LOCK STRIKER <i>X nn</i>	43.50	X
1	TAILGATE WEATHERSTRIP <i>X nn</i>	316.80	X
1	TAILGATE ABSORBER <i>X nn</i>	563.00	X
1	REAR COMPARTMENT TRIM <i>X nn</i>	561.55	X
		6640.26	
Less 25%		1660.06	
		4980.20	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
1 SET	REAR REVERSE SENSOR <i>new</i>	400.00	200 <i>new</i>
1	REAR NUMBER PLATE <i>X nn</i>	80.00	X
1 SET	REAR BUMPER CLIP <i>new</i>	60.00	30
1 SET	END PANEL TOP GARNISH CLIP <i>X nn</i>	60.00	X
1	WINDSCREEN SEALANT <i>X nn</i>	150.00	X
Subtotal		750.00	
Balance C/F		5730.20	

1354

256

1015.50

230

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	5730.20
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 Xnn
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 60
3	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 Xnn
4	REMOVE AND REFIT REAR WINDSCREEN	150.00 Xnn
5	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 Xnn
6	PANEL BEATING ON AFFECTED AREAS	1200.00 500
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 600
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 Xnn
	Subtotal	3310.00
	Grand total	9040.20

1160 1410
600 750

Asul

Hp 90010068

4 days

L/S

12/12/19 @ 1025

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

INDIA INTERNATIONAL INSURANCE

Vehicle number	SJQ4940C
Make / Model	TOYOTA PICNIC
Chassis number	JTEGH23B700026543
Accident date	10/12/19
Reference	1912-16

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR EXHAUST <i>bf</i>	879.60 833
2	REAR EXHAUST MOUNTING <i>new</i>	161.50 122
1	Floor Panel compartment - repair	1201.30 <i>X R</i>
		2242.40
	Less 25%	560.60
		1681.80
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR BUMPER STICKER	100.00 30
	Subtotal	100.00
	Balance C/F	1781.80
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	1781.80
1	REMOVE AND REFIT REAR EXHAUST	150.00 80
	Subtotal	150.00
	Grand total	1931.80

955
 258
 716.25

30

80

P - 10,15.50
 S/N - 230.00
 L - 1410.00
 716.25
 Suppl P - 30.00
 Suppl S/N - 80.00
 Suppl L - 3481.75
 T. - 2020
 2785.40
 415-21800