

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

First

Owner : Haridass S/O Muniandy

Accident Date : 3-Dec-19

Vehicle No : FBE 4950 G

Vehicle Model : Honda Wave

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Fork inner tubes	\$ set/tw 240.00 ✓
2	Fork outer tubes	\$ set/tw 250.00 ✓
1	Fork under bracket	\$ set 185.00 ✓
1	Front sport rim	\$ 320.00 x
1	Front rim shaft	\$ su 42.00 x
1	Front rim bearing	\$ 38.00 x
1	Front brake disc	\$ su 155.00 ✓
1	Headlamp	\$ su 95.00 x
1	Side mirror -L/H	\$ set 48.00 —
1	Front signal -L/H	\$ set 50.00 —
1	Handle-bar	\$ set 105.00 —
1	Hand grip (1 set)	\$ 50.00 —
1	Front footrest bracket	\$ set 55.00 —
1	Front footrest rubber R/H L/H	\$ 28.00 —
1	Brake pedal	\$ 42.00 x
1	Rear footrest - R/H L/H	\$ cur 38.00 —
1	Rear footrest bracket	\$ set 65.00 —
1	Rear taillamp	\$ cur 88.00 —
1	Rear fender n13	\$ cur 68.00 ✓
1	Main stand	\$ 90.00 x
1	Side stand	\$ 75.00 x
1	Fairing assy (1 set)	\$ cur 485.00 ✓
		\$ 2,612.00
	Less 10%	\$ 261.20
		\$ 2,350.80

c/f: \$ 2,350.80

Special Nett Items

- | | |
|---|---------------------------------|
| 1 | Number plate (1 set) |
| 2 | Fork oils |
| 2 | Fork oil seals |
| 1 | Steering cone bearing (1 set) |
| 1 | Rear box |
| 1 | Rear box bracket |
| 1 | ERP IU |
| 1 | Helmet |

Rear	\$	3rd	28.00	10
	\$	11	30.00	Q
	\$	11	56.00	Q
	\$	ner	85.00	
	\$	cur	250.00	200
	\$	cm	100.00	✓
	\$	cur	175.00	✓
	\$	n	95.00	X
	\$		819.00	

S/No. **Labour**

- | | |
|---|---|
| 1 | To provide towing service. |
| 2 | To check wiring and reset headlamp focusing |
| 3 | To provide labour. |
| 4 | To repair body frame. |

\$	50.00	35
\$	80.00	X
\$	380.00	280
\$	400.00	X
\$	910.00	

Grand Total

\$ 4,079.80

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

Date: _____

Signature: _____

Acknowledged by Repairer:

Date: _____

Signature: _____

the Repairer of the following:

Date: _____

Signature: _____

LKK Auto Consultants hence notify

• To resurvey before/after spray painting

• To display damaged parts for confirmation

• Parts prices are subject to confirmation

• Supplementary items must be resurveyed and signed for approval from Insurance Company

• No illegal modifications are allowed

• Supplementary items must be resurveyed and signed for approval from Insurance Company

• Parts prices are subject to confirmation

• To display damaged parts for confirmation

• To resurvey before/after spray painting