

not Admnd
rhr

FASTECH AUTO PTE LTD

BLK1 KAKI BUKIT AVE 6

#01-46,48,50 AUTOBAY

SINGAPORE 417883

Repair sum \$2400
357.
2/2/18

VEHICLE NO :SKB 7799S

QTY	PARTICULAR	AMOUNT
1 PCS	TAILGATE	11 \$2,953.00 X
1 PCS	TAILGATE REAR LOGO	11 \$66.50 X
1 PCS	TAILGATE WEATHERSTRIP	11 \$211.20 X
1 PCS	REAR BUMPER 767.40	20/12 \$881.30 /
2 PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11 \$130.00 X
1 PCS	REAR BUMPER BEAM 619.20	321 \$791.00 /
1 PCS	REAR BUMPER SPONGE 126.40	101 \$298.50 /
1 PCS	REAR BUMPER TOW COVER 39.20	CU1 \$65.00 /
1 SET	REAR BUMPER CLIPS	102 m \$38.00 /
1 PCS	REAR END PANEL	11 \$720.00 X
1SET	REAR BUMPER REVERSE SENSOR	CU1 \$280.00 2005.2
		\$6,434.50
	TO CHECK WIRING	\$50.00 20
	TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00 50
	TO DISMANTLE & REFIX CUSHION UPHOLSTREY	\$120.00 60
	TO SPRAY RUST PROOFING	11 \$50.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$680.00 400
	TO PUTTY & SPRAY PAINTING	\$880.00 550
	TOTAL	\$8,294.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 1590.20
102
p- 1431.18
S.V- 200.00
L- 1080.00
2711.18