

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 11/12/2019

Date / Time: 11/12/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: GBG 9324X

Claim No.: SNM19D205932

Name of Insured: MANCON ENGINEERING & TRADING PTE LTD

Policy No.: DMCVSN1768701902

Insured Tel No.: HP: 10/12/2019 14:50

Make / Model: KIA K2500-2.5 D 6M/T (M)

Excess Sec II :SS

D.O.A: 10/12/2019 14:50

Place of Accident: T/JUNCTION OF ADMIRALTY ST & SENOKO AVE

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SHEIKH MD SHARIF

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: +65-90564035

(V/L: YES / NO)

Insured Liability: % Final ? Yes / No

SLH 7020L

INSRS:
WSP: NHT
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	SLH 7020L - X	GBG 9324X - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
03/02/2020 @ 5:30pm	spoke to OL @ 90564035. Old rear-ended TP. Informed TP claim, agree to settle & even RPD will proceed.		Call OE:	7/03/2020 JL
			After call ltr to OE:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup):	☐
			After call ltr to OE:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☐
			Towing Invoice:	☐
			LTA / CHA:	☒
			Medical Bill:	☐
			PIR:	☐
			Mandate/Reject Instruction:	☒
			LOD:	☒
			Payment Breakdown Form:	☐
			Post-Repair Photos:	☐
			Others:	☐

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: 45	SS 9,800.00 (8 days) Reduction: 53	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 13/03/2020	Confirm with: 20K41	Email ☒ Call ☐
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 27		If NO or B 28, Ass. Lia:
Repair Cost: (w/loss)	SS 10,486.00		(OLD RATE - ENDED TP)
Loss of Rental (LOR):	SS — (days)		
Loss of Use (LOU):	SS 600.00 (S 60 x 10 days)		
Loss of Income (LOI):	SS — (S x days)		
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS —		
Disbursement:	SS — (e.g. Tow/Independent)		
Legal Cost	SS —		
Total:	SS 11,088.00	Global Sum SS: —	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS 11,088.00	Name 1: NEW HOCK TECK MOTOR PTE LTD	
Payee 2: (Strike if N.A.)	SS —	Name 2: —	
Payee 3: (Strike if N.A.)	SS —	Name 3: —	

ASSIGNMENT

SLT 7020L

2016 Nov

Insurance Co.

OD / TP / WS / TP RES / OD RES / EVA / RV / MV

Transport Vehicle /

at Workshop /

Insured /

Policy No.

Claim No.

Sum Insured

Excess

(Client's Receipt)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	OIS

Est. or Market Value

IDAC Accident Report Consistent? Yes or No

GIA / PR Seen Consistent? Yes or No

Est. Repairs days Res: Yes or No

Lim Sum % 3 Val Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted

Vehicle IN / OUT

Type ☒ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Private Motor /

Truck / Trailer

Make Honda Vezel Hybrid 1456

Color Grey Insured / Std / NI / NA

Sp Reading 48660 3 Reading Insured / Std / NI / NA

Engine

City 2431212702

Gen. Cond. ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Brake ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Moti Nil / ☒ R/R / ☐ STD A/Rim or

Tyre Size F: 225/50R18

R: 225/50R18

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front

Rear

R/Bal 06 mm R/Bal 06 mm

L/Bal 06 mm L/Bal 06 mm

D.O.A. 0 O.I. 11/12/19

Survey held at NHT

Des. of Damages Frt / ☒ Res / ☐ OIS / ☐ NIS / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim

Li \$9,800.00

CRB: \$10,688.80 (83%)

MV: 66K

PV: 42.6K

Nett: 23.4K

Down/Up File Task

☐ : Preli. Report

Days Of Repair

☐ : Final Report

Restorey No. of Trip

Survey Fee

Copy/Rev. File Download

Compensation

SVMT Fee ☐ See Reg 15

20-25

☐ 10-15

☐ 15-20

☐ 20-25

☐ 25-30

☐ 30-35

☐ 35-40

Report Summary

Report Summary

Report Summary

Report Summary

Report Summary



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM19D205932/GBG9324X/TKL
Our ref: CC6/CTI19021949/Aha3

Date: 05.02.2020

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLH 7020L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.12.2019 at the premises of M/s NEW HOCK TECK MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	20,638.80
Revised Estimate Amount	: S\$	12,277.84
"Check" Items Amount	: S\$	-
Market Value	: S\$	66,000.00
LTA Reimbursement Value	: S\$	42,600.00
Nett Value	: S\$	23,400.00

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 8 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser



Posted: 26-Nov-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$65,800 \$9,530 /yr 02-Aug-2016 1,496 cc 65,223 km SUV Available

Fuel Type: Petrol-Electric

Special Offer Till 31 December Only. Vehicle Viewing At AML Building. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! DVD/Bluetooth, Reverse Camera, Keyless Entry/Start, Paddle Shift, Auto LEDs...

Posted: 11-Nov-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X Honda Sensing \$65,800 \$9,490 /yr 12-Aug-2016 1,496 cc 36,598 km SUV Available

Fuel Type: Petrol-Electric

1 Owner Unit! Very Low Mileage Done. Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! DVD/Bluetooth, Reverse Camera, Keyless Entry/Start, Paddle Shift, Auto LED Headlights, Electric Park Brake, Auto Brake Hold, Low Fuel Consumption, M...

Posted: 06-Dec-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$78,888 \$11,330 /yr 07-Sep-2016 1,496 cc - SUV Available

Fuel Type: Petrol-Electric

100% Loan Available. High Trade In. Premium Warranty With \$500 Service Credits. Call For Viewing Now.

Posted: 21-Oct-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



Save on petrol with DBS Esso card!

Enjoy huge petrol savings of up to 21%, interest-free 0% Instalment Payment Plan for Motor Insurance and Road Tax, and 1-year annual fee waiver.

Find out more!



☐ Honda Vezel Hybrid 1.5A X \$78,888 \$11,330 /yr 07-Sep-2016 1,496 cc - SUV Available

Fuel Type: Petrol-Electric

100% Loan Available. High Trade In. Lowest Interest In Town. Premium Warranty With \$500 Credit. Call For Viewing Now.

Posted: 27-Oct-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$72,000 \$10,250 /yr 22-Sep-2016 1,496 cc 45,145 km SUV Available

Fuel Type: Petrol-Electric

Japan PI Honda Unit. Silver Exterior With Black Interior. Minimum 1 Year Warranty. One Owner With Low Mileage. Low Fuel Consumption. Most Popular SUV In The Market. Attractive Interest Rate From 2.48%. Please Call Our Sales Consultant For More Enquiries Now.

Inchcape Pre-Owned

Posted: 17-Dec-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$73,800 \$10,510 /yr 22-Sep-2016 1,496 cc 47,378 km SUV Available

Fuel Type: Petrol-Electric

Award-Winning SUV! Sporty, Infinite Design! Responsive iVTEC Engine Performance With 150Hp That Outshone Many Others In Its Class! 100% Fuel Efficiency With Hybrid Power! Owned By Successful Entrepreneur Who Had Upgraded To A New Merc GLC From Us. Top Con...

Car House Pte Ltd

Posted: 10-Nov-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X Honda Sensing \$70,800 \$10,050 /yr 26-Sep-2016 1,496 cc - SUV Available

Fuel Type: Petrol-Electric

Beautiful Red Vezel Hybrid, Low Mileage, Reliable Built, 1 Owner, Excellent Fuel Efficiency, Easy Maintenance, Car Available In Showroom For Viewing, Call For More Information.

Posted: 13-Dec-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$66,800 \$9,460 /yr 28-Sep-2016 1,496 cc 58,937 km SUV Available

Fuel Type: Petrol-Electric

Special Offer Till 31 December Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme Available, No Gimmicks! DVD/Bluetooth, Reverse Camera, Keyless Entry/Start, Paddle Shift, Auto LEDs Headlights, Electric Park Brake, A...

Posted: 16-Nov-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$66,388 \$9,370 /yr 06-Oct-2016 1,496 cc 53,000 km SUV Available

Fuel Type: Petrol-Electric

Looking To Be Different?? This Fierce Looking Vezel Comes With Bodykit And Cosmetic Modifications! 1 Meticulous Owner. Has Paddle Shifters And Sports Mode. Most Importantly, Very Well Maintained! Most Popular And Reliable Japanese SUV. Flexible Bank/In House Lo...

Posted: 27-Dec-2019 Tags: 2016 Honda Vezel, 2016 Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel, Honda Vezel



☐ Honda Vezel Hybrid 1.5A X \$67,800 \$9,520 /yr 19-Oct-2016 1,496 cc 56,183 km SUV Available

Fuel Type: Petrol-Electric

Special Offer Till 31 December Only. Come With 2 Years Third Party Warranty, Easy And Flexible In House Loan And Balloon Scheme

SHORTLISTED HISTORY

Compare



Fuel Type: Petrol-Electric

Sporty White Honda Vezel Hybrid, Come With Paddle Shift And Sport Mode.Best Selling SUV Model In The Market, Excellent Fuel Economy.Very Well Maintain By Careful Owner.Low Mileage Of 45,000km Done.Do Not Miss This Beautiful Unit.Trade-In Welcome! Easy



Honda Sensing

Fuel Type: Petrol-Electric
1 Owner Honda Sensing Hybrid Model. New Road Tax. Upgraded Rims And Sound System. Immaculate Condition. Low Mileage Done. Bank Loan Low Interest Rate Offer. In House Financing! Attractive Trade In Price. STA Welcome. Call Us Now For Viewing.



Fuel Type: Petrol-Electric

1 Owner! Low Mileage! Free 1 Servicing Upon Purchase! Up To 2 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! No Gimmicks! Trade-In Welcome! Not The Cheapest But Definitely The Best Value For Money Drive! Well Maintain

JDM Care

Save this search criteria, to get email alerts whenever a match is found



Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

[For old advertisements, view Expired ads.](#)


[= Back \(1 2 3 4 \) Next =](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

All prices and other information displayed on [sgCarMart.com](#) are gathered from sources and based on algorithms that are believed by [sgCarMart.com](#) to be reliable, but no assurance can be given that this information is accurate, complete or current. [sgCarMart.com](#) does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 soCarMart. All rights reserved.

Downloaded by [209.229.248.110]

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 393F

Vehicle Details

Vehicle No.: SLH7020L
Vehicle to be Exported: No
Intended Deregistration Date: 10 Dec 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X HYBRID CVT ABS
D/AIRBAG 2WD

Primary Colour: Black
Manufacturing Year: 2016
Engine No.: LEB5912712
Chassis No.: RU31212702
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$30,293.00
Original Registration Date: 15 Nov 2016
First Registration Date: 15 Nov 2016
Transfer Count: 2
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Nov 2026
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 14 Nov 2026
COE Category: B - Car above 1600cc or 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$56,089.00
COE Rebate Amount: \$38,857.00
Total Rebate Amount: \$42,607.00

The information contained herein is correct as at 10 Dec 2019

OK



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

LIM THIAN CHAI

10/12/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China

Vic

Accident date: 10/12/2019

Estimated repair cost for vehicle no: SLH7020L HONDA VEZEL 1.5 X A HYBRID '16

CHASSIS: RU31212702

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Distorted		\$1,100.90
2	2	Rear Boot Lid Hinges Bent	\$68.10	\$136.20
3	2	Rear Boot Lid Shock Absorbers Damaged	\$180.90	\$361.80
4	1	Rear Boot Lid Emblem Logo New		\$45.10
5	1	Rear Boot Lid Vezel Logo New		\$56.30
6	1	Rear Boot Lid Center Garnish Cracked		\$250.10
7	1	Rear Boot Lid Camera (Special Nett) Damaged		\$550.00
8	1	Rear Boot Lid Number Plate Not new		\$50.00
9	2	Rear Boot Lid Number Plate Lamp Not new	\$38.50	\$77.00
10	2	Rear Boot Lid Side Reflector Lt	\$284.60	\$569.20
11	1	Rear Boot Lid Inner Lock Damaged		\$185.60
12	1	Rear Boot Lid Inner Rubber Lt		\$135.25
13	1	Rear Boot Lid Top Center Trim Cover Deformed		\$105.40
14	2	Rear Boot Lid Top Side Trim Cover Deformed	\$68.30	\$136.60
15	1	Rear Boot Lid Inner Trim Board Cracked		\$283.40
16	1	Rear Boot Lid Inner Trim Board Side Handle Cover Not new		\$55.80
17	1	Rear Boot Lid Wiper Motor Damaged		\$205.00
18	1	Rear Boot Lid Wiper Arm Lt		\$122.00
19	1	Rear Boot Lid Windscreen Shattered		\$1,150.70
20	1	Rear Boot Lid Windscreen Seal NoC		\$151.70
21	2	Rear Boot Lid Windscreen Side Moulding	\$75.00	\$150.00
22	1	Rear Boot Lid Top Spoiler Cracked		\$480.20
23	1	Rear Boot Lid Top Spoiler Brake Lamp Lt		\$280.50
24	2	Rear Tail Lamp Lt	\$474.60	\$949.20
25	2	Rear Tail Lamp Panel Right	\$135.70	\$271.40
26	4	Rear Tail Lamp Clips New	\$8.00	\$32.00
27	2	Rear Tail Lamp Lower Bracket Not new	\$18.10	\$36.20

28	2	Rear Tail Lamp Lower Cover	Deformed	\$198.70	\$397.40	✓
29	1	Rear Bumper	Deformed		\$801.70	✓
30	2	Rear Bumper Side Retainer	New	\$29.20	\$58.40	✓
31	2	Rear Bumper Side Reflector	Cracked	\$148.40	\$296.80	✓
32	1	Rear Bumper Reverse Sensor (Special Nett)	Damaged		\$350.00 200/cw	✓
33	1	Rear End Panel	Dented		\$595.60	✓
34	1	Rear End Panel Top Garnish	Deformed		\$122.30	✓
35	1	Rear End Panel Lock Sensor	Not New		\$98.10	X
36	1	Rear End Panel Buzzer	Cracked		\$85.50	✓
37	2	Rear Fender Inner Trim Board	Cracked	\$325.25	\$650.50	✓
38	16	Rear Fender Inner Trim Board Clip	New	\$6.50	\$104.00 60	✓
39	1	Rear Spare Tyre Panel	Repair		\$662.20	X
40	1	Rear Spare Tyre Panel Top Cover	Deformed		\$306.65	✓
41	1	Rear Spare Tyre Panel Lower Cover	Repaired		\$190.90	X
42	1	Rear Spare Tyre Panel Storage Box	Deformed		\$226.90	✓
43	1	Rear Spare Tyre Under Cover	Deformed		\$190.90	✓
44	8	Rear Spare Tyre Under Cover Clips	New	\$6.50	\$52.00 30	✓
45	1	Rear Exhaust	Repair		\$868.00	X
46	1	Rear Center Exhaust	Repair		\$986.00	X
47	4	Rear Exhaust Mounting	New	\$25.60	\$102.40	X
48	1	Rear Exhaust Aluminum Cover	New		\$105.00	X
49	1	Rear Solar Film	New		350 250(SN)	
				Subtotal :-	\$15,178.80	

1070980 SN 830
856784

Labour charges

To remove & refit cushion & trim board	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 50
To remove & refit rear & center exhaust	\$380.00 80
To remove & refit rear windscreen	\$120.00 ✓
Gum net	\$50.00 ✓
To check wiring	2880 \$100.00 30
Tuff kote	\$150.00 60
Towing fee	\$150.00 60
Panel beating	\$2,000.00 1200
Spray painting	\$1,800.00 1100
To remove and refit tailgate fittings.	80 150
Subtotal :- <u>\$5,310.00</u>	
Total:- <u>\$20,488.80</u>	

20988.80

total 1227784

4/5 9.8k.

08 Days

9.8k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Friday, 13 December, 2019 12:00 PM
To: Mei Kwan (LKKAUTO); Vic (LKKAUTO)
Subject: RE: OUR REF: SNM19D205932/GBG9324X/TKL - Accident Involving GBG9324X (OI : CTI - TBA) AND SLH7020L (TP : LKK REF - CC6/CTI19021949/Aha3) on 10/12/2019
Attachments: GBG9324X.PDF
Categories: HMK

Without Prejudice

Der Mei Kwan,

We refer to your email below.

Attached is our insured's GIA report for your necessary action.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Friday, December 13, 2019 11:46 AM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: OUR REF: SNM19D205932/GBG9324X/TKL - Accident Involving GBG9324X (OI : CTI - TBA) AND SLH7020L (TP : LKK REF - CC6/CTI19021949/Aha3) on 10/12/2019

Dear Kah Leong,

Please revert LKK.

Note : officer in charge – Kah Leong

***** Kindly quote our reference number when replying.**

Thank You.

Regards,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19021949/Aha3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 19-03-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 9324X	Veh. Inspected	SLH 7020L	
Policy No.	DMCVSN1768701902	Coverage (\$)	0.00	
Claim No.	SNM19D205932	Excess (\$)	0.00	
Assign From		Assign Date	11/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU31212702	Colour	GREY	
Odometer	48660	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2019	Inspection Date	11/12/2019	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 7020L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DISTORTED	1,100.90	1,100.90
2	REAR BOOT LID HINGES @\$68.10	BENT	136.20	136.20
2	REAR BOOT LID SHOCK ABSORBERS @\$180.90	DAMAGED	361.80	361.80
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	45.10	45.10
1	REAR BOOT LID VEZEL LOGO	NECESSARY	56.30	56.30
1	REAR BOOT LID CENTER GARNISH	CRACKED	250.10	250.10
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$38.50	NOT NECESSARY	77.00	-
2	REAR BOOT LID SIDE REFLECTOR @\$284.60	CUT	569.20	569.20
1	REAR BOOT LID INNER LOCK	DAMAGED	185.60	185.60
1	REAR BOOT LID INNER RUBBER	CUT	135.25	135.25
1	REAR BOOT LID TOP CENTER TRIM COVER	DEFORMED	105.40	105.40
2	REAR BOOT LID TOP SIDE TRIM COVER @\$68.30	DEFORMED	136.60	136.60
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	283.40	283.40
1	REAR BOOT LID INNER TRIM BOARD SIDE HANDLE COVER	NOT NECESSARY	55.80	-
1	REAR BOOT LID WIPER MOTOR	DAMAGED	205.00	205.00
1	REAR BOOT LID WIPER ARM	CUT	122.00	122.00
1	REAR BOOT LID WINDSCREEN	SHATTERED	1,150.70	1,150.70
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	151.70	151.70
2	REAR BOOT LID WINDSCREEN SIDE MOULDING @\$75.00	NECESSARY	150.00	150.00
1	REAR BOOT LID TOP SPOILER	CRACKED	480.20	480.20
1	REAR BOOT LID TOP SPOILER BRAKE LAMP	CUT	280.50	280.50
2	REAR TAIL LAMP @\$474.60	CUT	949.20	949.20
2	REAR TAIL LAMP PANEL @\$135.70	TO REPAIR SEE LABOUR	271.40	-
4	REAR TAIL LAMP CLIPS @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$18.10	NOT NECESSARY	36.20	-
2	REAR TAIL LAMP LOWER COVER @\$198.70	DEFORMED	397.40	397.40
1	REAR BUMPER	DEFORMED	801.70	801.70
2	REAR BUMPER SIDE RETAINER @\$29.20	NECESSARY	58.40	58.40

Report Ref No. CC6/CTI19021949/Aha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER DIDE REFLECTOR @\$148.40	CRACKED	296.80	296.80
1	REAR END PANEL	DENTED	595.60	595.60
1	REAR END PANEL TOP GARNISH	DEFORMED	122.30	122.30
1	REAR END PANEL LOCK SENSOR	NOT NECESSARY	98.10	-
1	REAR END PANEL BUZZER	CRACKED	85.50	85.50
2	REAR FENDER INNER TRIM BOARD @\$325.25	CRACKED	650.50	650.50
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NECESSARY	104.00	60.00
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	662.20	-
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	306.65	306.65
1	REAR SPARE TYRE PANEL LOWER COVER	REPEATED	190.90	-
1	REAR SPARE TYRE PANEL STORAGE BOX	DEFORMED	226.90	226.90
1	REAR SPARE TYRE UNDER COVER	DEFORMED	190.90	190.90
8	REAR SPARE TYRE UNDER COVER CLIPS @\$6.50	NECESSARY	52.00	30.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	868.00	-
1	REAR CENTER EXHAUST	TO REPAIR SEE LABOUR	986.00	-
4	REAR EXHAUST MOUNTING @\$25.60	NOT NECESSARY	102.40	-
1	REAR EXHAUST ALUMINUM COVER	NOT NECESSARY	105.00	-
	LESS 20% DISCOUNT		-	-2,141.96
			14,278.80	8,567.84
	SPECIAL NETT ITEMS			
1	REAR SOLAR FILM (SN)	NECESSARY	350.00	250.00
1	REAR BOOT LID CAMERA (SN)	DAMAGED	550.00	380.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	GUM (SN)	NECESSARY	50.00	50.00
			1,300.00	880.00
	LABOUR			
	TO REMOVE & REFIT CUSHION & TRIM BOARD.		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIT REVERSE CAMERA.		180.00	50.00
	TO REMOVE & REFIT REAR & CENTER EXHAUST.		380.00	80.00

Report Ref No. CC6/CT119021949/Aha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	60.00
	TOWING FEE.		150.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL,REAR SPARE TYRE PANEL,REAR EXHAUST AND REAR CENTER EXHAUST.		2,000.00	1,200.00
	SPRAY PAINTING.		1,800.00	1,100.00
	TO REMOVE AND REFIT TAILGATE FITTINGS.		150.00	80.00
			5,410.00	2,910.00
GRAND TOTAL			20,988.80	12,357.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,800.00

Report Ref No. CC6/CTI19021949/Aha3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.