



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

10/12/2019

LIM THIAN CHAI

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China.

Vic

Accident date: 10/12/2019

Estimated repair cost for vehicle no: SLH7020L HONDA VEZEL 1.5 X A HYBRID '16

CHASSIS: RU31212702

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Distorted</i>		\$1,100.90 ✓
2	2	Rear Boot Lid Hinges <i>Best</i>	\$68.10	\$136.20 ✓
3	2	Rear Boot Lid Shock Absorbers <i>Damaged</i>	\$180.90	\$361.80 ✓
4	1	Rear Boot Lid Emblem Logo <i>New</i>		\$45.10 ✓
5	1	Rear Boot Lid Vezel Logo <i>New</i>		\$56.30 ✓
6	1	Rear Boot Lid Center Garnish <i>Cracked</i>		\$250.10 ✓
7	1	Rear Boot Lid Camera (Special Nett) <i>Damaged</i>		\$550.00 <i>389(SN)</i> ✓
8	1	Rear Boot Lid Number Plate <i>Not new</i>		\$50.00 X
9	2	Rear Boot Lid Number Plate Lamp <i>Not new</i>	\$38.50	\$77.00 X
10	2	Rear Boot Lid Side Reflector <i>lit</i>	\$284.60	\$569.20 ✓
11	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$185.60 ✓
12	1	Rear Boot Lid Inner Rubber <i>lit</i>		\$135.25 ✓
13	1	Rear Boot Lid Top Center Trim Cover <i>Delam</i>		\$105.40 ✓
14	2	Rear Boot Lid Top Side Trim Cover <i>Delam</i>	\$68.30	\$136.60 ✓
15	1	Rear Boot Lid Inner Trim Board <i>Cracked</i>		\$283.40 ✓
16	1	Rear Boot Lid Inner Trim Board Side Handle Cover <i>Not new</i>		\$55.80 X
17	1	Rear Boot Lid Wiper Motor <i>Damaged</i>		\$205.00 ✓
18	1	Rear Boot Lid Wiper Arm <i>lit</i>		\$122.00 ✓
19	1	Rear Boot Lid Windscreen <i>Shattered</i>		\$1,150.70 ✓
20	1	Rear Boot Lid Windscreen Seal <i>3 Noc</i>		\$151.70 ✓
21	2	Rear Boot Lid Windscreen Side Moulding	\$75.00	\$150.00 ✓
22	1	Rear Boot Lid Top Spoiler <i>Cracked</i>		\$480.20 ✓
23	1	Rear Boot Lid Top Spoiler Brake Lamp <i>lit</i>		\$280.50 ✓
24	2	Rear Tail Lamp <i>lit</i>	\$474.60	\$949.20 ✓
25	2	Rear Tail Lamp Panel <i>Bye</i>	\$135.70	\$271.40 ✓
26	4	Rear Tail Lamp Clips <i>New</i>	\$8.00	\$32.00 ✓
27	2	Rear Tail Lamp Lower Bracket <i>Not new</i>	\$18.10	\$36.20 X

28	2	Rear Tail Lamp Lower Cover	Deformed	\$198.70	\$397.40	✓
29	1	Rear Bumper	Deformed		\$801.70	✓
30	2	Rear Bumper Side Retainer	nee	\$29.20	\$58.40	✓
31	2	Rear Bumper Side Reflector	cracked	\$148.40	\$296.80	✓
32	1	Rear Bumper Reverse Sensor (Special Nett)	Damaged		\$350.00	200(SN) ✓
33	1	Rear End Panel	Dented		\$595.60	✓
34	1	Rear End Panel Top Garnish	Deformed		\$122.30	✓
35	1	Rear End Panel Lock Sensor	Nor Nee		\$98.10	X
36	1	Rear End Panel Buzzer	cracked		\$85.50	✓
37	2	Rear Fender Inner Trim Board	cracked	\$325.25	\$650.50	✓
38	16	Rear Fender Inner Trim Board Clip	nee	\$6.50	\$104.00	60 ✓
39	1	Rear Spare Tyre Panel	Repair		\$662.20	X
40	1	Rear Spare Tyre Panel Top Cover	Deformed		\$306.65	✓
41	1	Rear Spare Tyre Panel Lower Cover	Repaired		\$190.90	X
42	1	Rear Spare Tyre Panel Storage Box	Deformed		\$226.90	✓
43	1	Rear Spare Tyre Under Cover	Deformed		\$190.90	✓
44	8	Rear Spare Tyre Under Cover Clips	nee	\$6.50	\$52.00	30 ✓
45	1	Rear Exhaust	Repair		\$868.00	+
46	1	Rear Center Exhaust	Repair		\$986.00	+
47	4	Rear Exhaust Mounting	Nee	\$25.60	\$102.40	+
48	1	Rear Exhaust Aluminum Cover	Nee		\$105.00	+
49	1	Rear Solar Film	nee			
				350 250(SN)		
				Subtotal :-	\$15,178.80	

1070980 SN 830
856784

Labour charges

To remove & refit cushion & trim board		\$280.00 80
To remove & refit reverse sensor		\$100.00 50
To remove & refit reverse camera		\$180.00 50
To remove & refit rear & center exhaust		\$380.00 80
To remove & refit rear windscreen		\$120.00 ✓
Gum		\$50.00 ✓
To check wiring	2880	\$100.00 30
Tuff kote		\$150.00 60
Towing fee		\$150.00 60
Panel beating		\$2,000.00 1200
Spray painting		\$1,800.00 1100
To remove and refit tailgate fittings.	80 150	

Subtotal :- \$5,310.00

Total:- \$20,488.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 11227784

4/5 9.8K.

08 Days

98K.