

ASS. REC. BY:

REF:

CS/AG119021980/Ay f3

Special Instruction:

Surveyor Adrian

ASSIGNMENT (Office)

From (Person): Imy Raklia

of

AG1

Date/Time: 12.12.19 1:30p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMA 624R

Insured:

SLT 7761T

at Workshop m/s N/51 Automarve

Tel:

68420051

of 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit

Policy No:

Claim No:

C1004881

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12.12.19 1:48p.m

Person Contacted:

Qian Yu

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMA 624R - X
	SLT 7761T - X

Adrian

INSURANCE

SMA 6242.

2018 May

TO / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle (V)

at Workshop (W)

at

Insured

Policy No.

Claims Type

Survey Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Est. or Market Value:

IGAC Accident Report Consistent? Yes or No

GIA / FR Seen Consistent? Yes or No

Est. Repair: days Res: Yes or No

Loss Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted

Vehicle: IN / OUT

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Private Motor / Truck / Trailer

Make: Toyota Sienta Hybrid 1486

Color: Green AX: Insured / Std / NI / NA

Op. Reading: 147551 T/Scale: Insured / Std / NI / NA

Eng. No.

C/Nr.

NHP1707126407.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt

Brake: In order / Jammed / Leaked / Burnt

Mod: Nil / STD A/Rim

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or Habiled.

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I: 16/12/19

Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

9/3 TP Budget Direct
L/S \$6300/- (Red \$5354-65, 45%)

MV:

PV:

Nett.

RECEIVED 10 MAR 2020

Survey Type: Pre-Fault or

☐

Post-Fault Report

or

☐

Final Report

Date/Time: The Date of

9/3/20 Typist

Days Of Repair: 7

Resurvey No. of Trip: 3

Survey Fee:

Insurance:

or

or

or

or

or

or

or

Arbit. Fee:

Site Insp: 15

Survey Fee: 15

Survey Fee: 15

Survey Fee: 15

Survey Fee: 15

Survey Fee: 15

Survey Fee: 15

350

\$6300/-

Summer Lee (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Friday, 13 December, 2019 1:34 PM
To: Nivitha (LKK Auto)
Cc: SUR; Julie Mangubat
Subject: FW: SMA624R & SLT7761T - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS || C10004881
Attachments: 624.pdf

Hi Team,

We would like to arrange TP PRS for SMA624R. They have chosen Mr. Adrian Ling to survey the vehicle.

Please see attached file for the workshop information.

Kindly confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Ziting <ziting@n51.com.sg>

Sent: Friday, 13 December 2019 12:22 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Subject: Re: SMA624R & SLT7761T - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS || C10004881

Dear Sir / Madam,

We appoint your surveyor Adrian Ling LKK Auto Consultants Pte Ltd

Please see attached.

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



From: Ziting <ziting@n51.com.sg>

Sent: Friday, 13 December 2019 10:27 AM

To: Claims <claims@budgetdirect.com.sg>

Subject: SMA624R & SLT7761T - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer to attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,


Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2019 18:58
Date Of Accident	12/12/2019 16:00
Exact Location Of Accident	SLIP RD ALONG JALAN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMA624R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31388644
Vehicle Particulars	
Manufacturer	TOYOTA
Model	SIENTA-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	
Driver	
Name of Driver	ONG SWEE HUAT
NRIC No	S0417951Z
Date Of Birth	27/01/1948
Occupation	OUTDOOR
Date Of Driving Pass	30/09/1967
Driving Experience	52 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92968649
Fax Number	
Contact Number	OTHERS-98550048
Email Address	NOEMAIL

Address	BLK 171 BUKIT BATOK WEST AVE 8 #14-359
Postcode	650171
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOT APPLICABLE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 12/12/19 AT AROUND 4PM, I WAS DRIVING MY CAR ON THE SLIP RD FROM JALAN BUKIT MERAH INTO CTE. AS I STOP MY CAR TO A STATIONARY POSITION, VEHICLE B DROVE UP FROM BEHIND AND COLLIDED INTO THE BACK OF MY CAR. MY CAR SUSTAINED REAR DAMAGES. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT7761T
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	KOR SU YEE
NRIC/Passport Number	S7641904C
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

FRONT PORTION

No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

12/12/2019
5.50 p.m.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

(A) SMA 624 R

(B) SLT 7761 T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/12/2019 at around 4.00p.m., I was driving my car (Uch. A SMA 624 R) on the slip road from Jalan Bukit Merah into C.T.E. As I stop my car to a stationary position, Uch. B (SLT 7761 T) drove up from behind and collided into the back of my car. My car sustained rear damages. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP Budget Direct
Yvonne

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

ESTIMATE

Repair Code : CLM15855

Date in : 12/12/2019

Vehicle Num. : SMA624R

Model : TOYOTA SIENTA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707126407/1NZ8545424

Contact : 66550005-GRAB 92968649, 98550048

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
* REAR BUMPER <i>Dehd</i>	1	950.00	✓ 950.00
REAR BUMPER CENTER GARNISH <i>Dehd</i>	1	209.00	✓ 209.00
REAR BUMPER REFLECTOR L/R <i>crushed</i>	2	85.00	✓ 170.00
REAR BUMPER SIDE GARNISH L/R <i>Not Nec</i>	2	155.00	X 310.00
REAR BUMPER SIDE RETAINER L/R <i>Na</i>	2	90.00	✓ 180.00
REAR BUMPER TOW HOOK COVER <i>Not nec</i>	1	25.00	X 25.00
REAR DASH BOX COVER <i>crushed</i>	1	686.00	✓ 686.00
REAR END PANEL 'INNER' <i>Repair</i>	1	607.00	X 607.00
REAR END PANEL 'OUTER' <i>Distorted</i>	1	599.00	✓ 599.00
REAR END PANEL INNER TOP GARNISH <i>Dehd</i>	1	207.00	✓ 207.00
REAR FENDER INNER TRIM GARNISH L/R <i>Dehd</i>	2	709.00	✓ 1,418.00
REAR TAILGATE <i>Dented</i>	1	1785.00	1785.00
REAR TAILGATE 'HYBRID' EMBLEM <i>Given</i>	1	78.00	✓ 78.00
REAR TAILGATE 'LOGO' EMBLEM	1	110.00	✓ 110.00
REAR TAILGATE INNER PULL HANDLE <i>Not nec</i>	1	48.00	X 48.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>Not nec</i>	2	19.00	X 38.00
REAR TAILGATE INNER TRIM GARNISH <i>Not nec</i>	1	455.00	X 455.00
REAR TAILGATE LOCK STRIKER <i>Not nec</i>	1	40.00	X 40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 92968649, 98550048

ESTIMATE

Repair Code : CLM15855

Date in : 12/12/2019

Vehicle Num. : SMA624R

Model : TOYOTA SIENTA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707126407/1NZ8545424

REAR TAILGATE MECHANISM LOCK <i>2pc</i>	1	265.00	✓	265.00
REAR TAILGATE WEATHER STRIP <i>1pc</i>	1	385.00	✓	385.00
REAR TAILGATE WINDSCREEN MOULDING <i>3pc</i>	2	45.00	70	90.00
REAR TAILGATE WINDSCREEN SEAL	2	45.00	70	90.00
REAR TAILLAMP LOWER BRACKET L/R <i>new</i>	2	83.10	x	166.20
REAR TOOL BOX TOP BOARD COVER L/R <i>2pc</i>	2	378.00	1	756.00
REAR TOOL BOX TRAY <i>2pc</i>	1	519.00	✓	519.00
Subtotal before discount				10,186.20
Percentage discount 25%				2,546.55
Sub-total 1				7,639.65
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	200	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	10	20.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	50.00	60	100.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>new</i>	1	50.00	x	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	x	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>3pc</i>	1	50.00	x	50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	✓	60.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 92968649 , 98550048

ESTIMATE

Repair Code : CLM15855
Date in : 12/12/2019
Vehicle Num. : SMA624R
Model : TOYOTA SIENTA HYBRID 1.5X CVT
Chassis/Eng# : NHP1707126407/1NZ8545424

Subtotal before discount	605.00
Percentage discount 0%	0.00
Sub-total 2	605.00
Parts-total	8,244.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓ 60.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 120.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	800 1,400.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	800 1,500.00
To apply anti-rust chemical on repaired and replaced panel.	60 100.00
To remove, reinstall tailgate mechanism and check for function	80.00
Labour Total	3,410.00
Parts & Labour Total	11,654.65

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 7350
4/5: 6.3K.
07Days
6.3K




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19021980/Ayf3n2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 10-03-2020		
		Code : AGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 7761T	Veh. Inspected	SMA 624R	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10004881	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	13/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	NHP1707126407	Colour	GREEN	
Odometer	147551	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HABILEAD	6 mm	
L/H Front Tyre	185/60 R15	HABILEAD	6 mm	
R/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
L/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/12/2019	Inspection Date	16/12/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 624R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	950.00	950.00
1	REAR BUMPER CENTER GARNISH	DEFORMED	209.00	209.00
2	REAR BUMPER REFLECTOR L/R @\$85.00	CRACKED	170.00	170.00
2	REAR BUMPER SIDE GARNISH L/R @\$155.00	NOT NECESSARY	310.00	-
2	REAR BUMPER SIDE RETAINER L/R @\$90.00	NECESSARY	180.00	180.00
1	REAR BUMPER TOW HOOK COVER	NOT NECESSARY	25.00	-
1	REAR DASH BOX COVER	CRACKED	686.00	686.00
1	REAR END PANEL "INNER"	TO REPAIR SEE LABOUR	607.00	-
1	REAR END PANEL "OUTER"	DISTORTED	599.00	599.00
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	207.00	207.00
2	REAR FENDER INNER TRIM GARNISH L/R @\$709.00	DEFORMED	1,418.00	1,418.00
1	REAR TAILGATE	DENTED	1,785.00	1,186.00
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	78.00	78.00
1	REAR TAILGATE "LOGO" EMBLEM	NECESSARY	110.00	110.00
1	REAR TAILGATE INNER PULL HANDLE	NOT NECESSARY	48.00	-
2	REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R @\$19.00	NOT NECESSARY	38.00	-
1	REAR TAILGATE INNER TRIM GARNISH	NOT NECESSARY	455.00	-
1	REAR TAILGATE LOCK STRIKER	NOT NECESSARY	40.00	-
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	265.00	265.00
1	REAR TAILGATE WEATHER STRIP	CUT	385.00	385.00
2	REAR TAILGATE WINDSCREEN MOULDING @\$45.00	NECESSARY	90.00	70.00
2	REAR TAILGATE WINDSCREEN SEAL @\$45.00	NECESSARY	90.00	70.00
2	REAR TAILLAMP LOWER BRACKET L/R @\$83.10	NOT NECESSARY	166.20	-
2	REAR TOOL BOX TOP BOARD COVER L/R @\$378.00	DEFORMED	756.00	378.00
1	REAR TOOL BOX TRAY	DEFORMED	519.00	519.00
	LESS 25% DISCOUNT		-2,546.55	-1,870.00
			7,639.65	5,610.00
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	SET REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/AGI19021980/Ayf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR FENDER INNER TRIM GARNISH CLIPS L/R @\$50.00 (SN)	NECESSARY	100.00	60.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
			605.00	360.00
	LABOUR			
	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.		80.00	80.00
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		60.00	60.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		120.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,400.00	800.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR END PANEL "INNER".		1,500.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			3,410.00	1,980.00
GRAND TOTAL			11,654.65	7,950.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,300.00

Report Ref No. CS/AGI19021980/Ayf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.