4/12/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19021982/QRA3Q2

12/04/2021 Date:

Odometer:

143119 km

**REFERENCE** 

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle** SLM8718A

Insured Vehicle No: SMM4554U

20/09/2019 Nature of Claim: TP Claim No: 1332732668SG Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLM8718A** 

Make & Model: **KIA FORTE K3, 1.6 (A)** Engine No: G4FGGH647508 Reg. Date: 17/04/2017 (Man. Year: 2017) Chassis No: KNAFJ411MH5714383

Colour: White

**Engine Capacity:** 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Firenza 5 mm Firenza 5 mm Front Right Side: Rear Right Side: Firenza 5 mm Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,645.90	1,332.00	1,313.90	49.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,270.00	830.00	39.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,745.90	2,602.00	2,143.90	45.17
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	4,745.90	2,000.00	2,745.90	57.86
+ GST 7.00/7.00% (S\$)	332.21	140.00	192.21	57.86
Nett Amount (S\$)	5,078.11	2,140.00	2,938.11	57.86
+ Loss of Use (6.0 x S	\$60.00/day) (S\$)	360.00		
	(S\$)	2,500.00		
Liable Amou	nt (50.00%) (S\$)	1,250.00		
+ Doc/	Search Fee (S\$)	2.00		
N	ett Liability (S\$)	1,252.00		

**INSPECTION** 

Date of Assignment: 13/12/2019

Date Inspected: 13/12/2019 Inspected At: 60 Jalan Lam Huat, #04-35/36 Carros Centre

Singapore 737569

Lion City Rentals Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/R DOOR	Dented	1,542.00 FL	*1,480.00 FL
2	1		*R/R DOOR	Repair	1,309.00 FL	*- FL
3	1		*SET BUMPER CLIPS	Serviceable	80.00 FS	*-FS
F=Fra	ınchise	part. S=SpcNett.	L=ListItemDisc.			
				Sub Total (S\$)	2,931.00	1,480.00
			- List Item Discoun	t on L Items 10.00/10.00% (S\$)	285.10	148.00
				Total Parts (S\$)	2,645.90	1,332.00
			Report was u	nsubmitted during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO LABOUR CHARGE FOR REMOVING F/R DOOR AND R/R DOOR OF TO FACILITATE REPLACEMENT OF DAMAGED PARTS	<b>DUT</b> New	900.00	600.00
2	TO RESPRAY F/R DOOR ,R/R DOOR AND F/R FENDER	New	900.00	600.00
3	REMOVE AND TRANSFER DOOR MECHANISMS	New	300.00	70.00
	Gross L	abour Cost (S\$)	2,100.00	1,270.00
	Report was unsubmitted during	his print-out		

< END OF ESTIMATES >