

Our Job Ref No . 305366574

Date : 19. Dec. 2019

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA 469G

Date of Accident: 11. Dec. 2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG GBF4448K
2. The finalized amount shall be:
 - (a) Spare Parts after List discount To: Khandun
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c) Lumpsum Repair (if applicable)
 - Total for Lumpsum repair cost after Less:
 - Final Lumpsum Repair cost** \$5,900.00 *Recuplaid*

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Ram

Name : Ram

Date : 20/12/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO : SHA 469G

DATE 12/12/2019 10:09

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet BUC			\$ 2,265.90
	Bonnet Lock xnn			\$ 36.90
	Radiator Grille Cva			\$ 1,110.10
	Radiator Grille H Emblem ncc			\$ 39.50
	Front Bumper Cover Cva			\$ 1,052.20
	Front Bumper Sponge Br			\$ 99.20
	Front Bumper Reinforcement ?X NN			\$ 402.10
	Front Bumper Grille (LH/RH) xnn		\$ 93.60	\$ 187.20
	Front Bumper Grille Airduct (LH/RH) xnn		\$ 26.20	\$ 52.40
	Front Bumper Bracket Top (LH/RH) xnn		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) xnn		\$ 24.60	\$ 49.20
	Headlamp (LH/RH) Br (LH) xnn		\$ 1,388.00	\$ 2,776.00
	Front Fender (LH/RH) RH BUC LH x(R)		\$ 663.00	\$ 1,326.00
	Front Fender Shield (LH/RH) xnn		\$ 174.90	\$ 349.80
	Front Fender Retainer xnn			\$ 24.60
	SUB TOTAL			\$ 9,815.90
	LESS 20%			\$ 1,963.18
	DISCOUNTED TOTAL			\$ 7,852.72
	Front Number Plate Cva			\$ 25.00
	Front No Plate Trim Cover Br			\$ 30.00
	Front Fender Advertisement Logo (LH/RH) xnn		\$ 100.00	\$ 200.00
	Labour Charge			
	Panel Beating			\$ 1,800.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 2,900.00
	ESTIMATE TOTAL			\$ 11,007.72

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ram (LKR)
12/12/19 1530hrs
Paragwan (LKR) 1530hrs
88622778 hp
Aft repair - flat
L/S
3 repair days

L/S: \$5900/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.