

Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore
415933
Email: automim.claim@gmail.com Tel: 9119 8371

Estimate

Our Ref: AC2019048/TP/GBG2689R-09.12.2019

GBB2689R TOYOTA HIACE

Items Qty	List Items /			AMOUNT S\$
1 1	TAIL GATE L			2,062.00
2 1	TAIL GATE LOGO NEL			135.00
3 1	TAIL LAMP ASSY LH WO			786.00
4 1	REAR FENDER PANEL LH			1,988.00
5 1	REAR BUMPER de			982.00
61102	REAR BUMPER SIDE RETAINER NO (LH)		121.50	243.00
7 1	REAR END PANEL OUTER CARMY			1,288.00
	,		\$	7,484.00
		LESS 25%	\$	1,871.00
			\$	5,613.00

<u>Items</u>	Qty	Special Nett		AMOUNT S\$
8	1	REAR WINDSCREEN GLASS SEALANT 1/4		90.00 60
9	1	REAR WINDSCREEN GLASS INNER SEAL M		135.00100
10	1	REAR SIDE PANEL GLASS SEALANT /		90.00 60
11	1	70 KM/H STICKER AM		25.00 10
12	8	TAIL GATE TRIM BOARD CLIP NO.	6.00	48.00
13	1	REVERSE SENSOR 🗡		250.00
			Ś	638.00

	LABOUR & MISCELLANEOUS:	
14	To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,890.00
15	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	1,200.00 750
16	To transfer tail gate components with all necessary attachments	250.00 80
17	To remove, refix rear windscreen glass and water test	250.00 120
18	To remove, refix side panel glass and water test LH	250.00 (20
19	To remove, refix rear interior garnishes upholstery	250:00 (20 200:00 (00
20	To install reverse sensor and test funtion	100.00 × \$ 4,050.00

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pasul Hp 90010068 6 days 13/12/19 @ 1520 Roswuy after repair