

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.SOH CHAN WAH
12 DERBYSHIRE ROAD #04-01
SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM14793

Date in : 17/12/2019

Vehicle Num. : SKB6841J /2011

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104117512/1ZRX097811

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>bt</i> ✓	1	1240.00	1050 1,240.00
FRONT BONNET <i>bt</i> ✓	1	1140.40	862 1,140.40
FRONT BONNET MECHANISM LOCK <i>X su</i>	1	182.10	182.10 X
FRONT BONNET RUBBER GUIDE STOPPER L/R <i>nee</i> ✓	2	43.90	87.80 ✓
FRONT BONNET WEATHER STRIP <i>nee</i> ✓	1	181.25	52 181.25
FRONT BRACE PANEL <i>bt</i> ✓	1	182.10	100 182.10
FRONT BUMPER <i>de</i> ✓	1	456.00	456.00 ✓
FRONT BUMPER 'LOGO' EMBLEM <i>nee</i> ✓	1	71.60	71.60 ✓
FRONT BUMPER LOWER GRILLE <i>ca</i> ✓	1	265.00	120 265.00
FRONT BUMPER REINFORCEMENT <i>bt</i> ✓	1	379.00	325 379.00
FRONT BUMPER SIDE RETAINER L/R <i>LH-X/RH-nee @65</i>	<i>2 lpc</i>	(65.00)	130.00 X
FRONT BUMPER UPPER WEATHER STRIP <i>X su</i>	1	185.00	185.00 X
FRONT FENDER 'VVTI' EMBLEM L/R <i>X su</i>	2	43.10	86.20 X
FRONT GRILLE <i>ca</i> ✓ (ASSY)	1	404.00	290 404.00
FRONT GRILLE CHROME MOULDING L/R <i>X su</i>	2	135.80	271.60 X
FRONT GRILLE LOWER CHROME MOULDING <i>X su</i>	<i>2</i>	156.70	313.40 X
FRONT HEADLAMP L/R <i>ca</i> ✓	2	445.00	890.00 ✓
FRONT SUPPORT PANEL <i>repair</i>	1	2135.30	2,135.30 X

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510 .

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR.SOH CHAN WAH

12 DERBYSHIRE ROAD #04-01

SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM14793

Date in : 17/12/2019

Vehicle Num. : SKB6841J

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104117512/1ZRX097811

RADIATOR (AUTO) <i>bt</i>	1	2142.30	<i>1680</i> 2,142.30
RADIATOR FAN COWLING <i>Xsu</i>	1	292.10	292.10 X
RADIATOR TOP BRACKET GARNISH <i>Xsu</i>	1	65.90	65.90 X
REAR BOOTLID <i>bt</i>	1	982.00	<i>855</i> 982.00
REAR BOOTLID '1.6' EMBLEM <i>ne</i>	1	48.00	48.00
REAR BOOTLID 'ALTIS' EMBLEM <i>ne</i>	1	43.20	43.20
REAR BOOTLID 'COROLLA' EMBLEM <i>ne</i>	1	45.10	45.10
REAR BOOTLID 'DUAL' EMBLEM <i>ne</i>	1	39.20	39.20
REAR BOOTLID 'LOGO' EMBLEM <i>ne</i>	1	58.30	58.30
REAR BOOTLID 'VVTI' EMBLEM <i>ne</i>	1	43.10	43.10
REAR BOOTLID CHROME MOULDING <i>sc</i>	1	274.45	274.45
REAR BOOTLID INNER UPHOLSTERY TRIM COVER <i>Xsu</i>	1	245.30	245.30 X
REAR BOOTLID MECHANISM LOCK <i>bt</i>	1	509.00	<i>110</i> 509.00
REAR BOOTLID REFLECTOR LAMP BACK RUBBER GASKET L/R <i>ne Xsu</i>	2	19.10	38.20 X
REAR BOOTLID REFLECTOR LAMP L/R <i>RH-CR / LH-Xsu</i>	<i>2/1pc</i>	331.90 <i>140</i>	663.80
REAR BOOTLID RUBBER GUIDE STOPPER <i>ne @10</i>	<i>4</i>	45.90 <i>40</i>	183.60
REAR BOOTLID WEATHER STRIP <i>ne</i>	1	169.00	169.00
REAR BUMPER <i>de</i>	1	682.00	<i>545</i> 682.00

*** This is a computer-generated document which requires no signature.***

page 2

4090.35

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.SOH CHAN WAH
12 DERBYSHIRE ROAD #04-01
SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM14793

Date in : 17/12/2019

Vehicle Num. : SKB6841J

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104117512/1ZRX097811

2060.30

REAR BUMPER BRACKET L/R ^{su} LH-X/RH-St-@87	2/pc	132.25	87	264.50
REAR BUMPER CORNER RETAINER L/R ^{su} LH-X/RH-ne	2/pc	(66.00)		132.00
REAR BUMPER REFLECTOR L/R ^{su} LH-X/RH-ca-@38	2/pc	66.30	38	132.60
REAR BUMPER SIDE RETAINER L/R ^{su} LH-X/RH-ne	2/pc	103.50	27	207.00
REAR BUMPER SPONGE ^{ca}	1	108.00		108.00
REAR END PANEL ^{bt}	1	581.20		581.20
REAR END PANEL INNER TOP GARNISH ^{de}	1	229.60	192	229.60
REAR FENDER INNER UPHOLSTERY TRIM L/R ^{su} LH-X/RH-cut	2/pc	274.00		548.00 X
REAR SPARE TYRE INNER TOP UPHOLSTERY BOARD ^{Xsu}	1	285.00		285.00 X
REAR TAILLAMP L/R ^{ca} @318	2	407.00	630	814.00
REAR TAILLAMP LOWER BRACKET L/R ^{su} LH-X/RH-ca	2/pc	(57.10)		114.20
Subtotal before discount		10520.05		18,541.40
Percentage discount 25%		25%		4,635.35
Sub-total 1		7890.03		13,906.05
FRONT BUMPER CLIPS - SET ^{su}	1	50.00	30	50.00
FRONT GRILLE CLIPS - SET ^{su}	1	40.00	20	40.00
FRONT NUMBER PLATE	1	25.00		25.00
FROTNT NUMBER PLATE HOLDER ^{bt}	1	50.00	35	50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR.SOH CHAN WAH
12 DERBYSHIRE ROAD #04-01
SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM14793
Date in : 17/12/2019
Vehicle Num. : SKB6841J
Model : TOYOTA COROLLA ALTIS 1.6 AUTO
Chassis/Eng# : MR053REE104117512/1ZRX097811

REAR BOOTLID CHROME MOULDING CLIPS - SET <i>nw</i>	1	30.00	15	30.00
REAR BUMPER CLIPS - SET <i>nw</i>	1	50.00	30	50.00
REAR BUMPER END COVER CLIPS L/R - SET <i>xnw</i>	2	30.00	X	60.00
REAR BUMPER REVERSE SENSOR <i>nw</i>	1	250.00	200	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>nw</i>	1	30.00		30.00
REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET <i>nw</i>	<i>71pc</i>	30.00		60.00 X
REAR NUMBER PLATE	1	25.00		25.00
REAR NUMBER PLATE HOLDER	1	50.00	35	50.00
REAR TAILLAMP CLIPS L/R - SET <i>nw</i>	2	20.00	20	40.00
Subtotal before discount			<i>445</i>	760.00
Percentage discount 0%				0.00
Sub-total 2				760.00
Parts-total				14,666.05

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	120.00	80
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	60.00	30
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	100.00	60
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1000	1,200.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	600	1,000.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

MR. SOH CHAN WAH
12 DERBYSHIRE ROAD #04-01
SINGAPORE 309466

Contact : 91790770

ESTIMATE

Repair Code : CLM14793

Date in : 17/12/2019

Vehicle Num. : SKB6841J

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053REE104117512/1ZR097811

To remove and reinstall exhaust pipe.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	3030	4,240.00
Parts & Labour Total		18,906.05

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram

Hp 90010068

12 days

4/5

17/12/19 @ 1710

Resurvey after repair

7890.03

445.00

3030.00

11,365.03

20%

9092.02

4/5 - 9,150

12 days

Repair limit

\$9000