

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: **Vehicle No: SLK77077**Model: **Mercedes Benz E200 AVG**Chassis No: **WDD2130422A399375**Year of manufacture: **2017****Bifrost Auto Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Rear bumper ✓ <i>CRA</i>	1		
2	Rear bumper retainer RH <i>X (SVC)</i>	1		
3	Rear bumper retainer LH <i>X (SVC)</i>	1		
4	Rear bumper center bracket <i>X (SVC)</i>	1		
5	Rear bumper bracket RH <i>X (SVC)</i>	1		
6	Rear bumper bracket LH ✓ <i>CRA</i>	1		
7	Rear bumper lower garnish ✓ <i>SCR</i>	1		
8	Rear bumper chrome piece ✓ <i>SCR</i>	1		
9	Rear bumper chrome diffuser LH ✓ <i>SCR</i>	1		
10	Reverse sensor <i>4H ✓ short</i>	3		
11	Reverse sensor wire harness set <i>X SVC</i>	1		
12	Rear bumper reverse sensor bracket ✓ <i>none</i>	6		
13	Rear bumper reflector LH <i>Holder CRA</i>	1		
14	Rear bumper reinforcement <i>X (R)</i>	1		
15	Tail lamp LH ✓ <i>SCR</i>	1		

0.00

Special Nett Items

16	Rear bumper clip set ✓ <i>none</i>	1		60.00 <i>25</i>
17	Tail lamp clip set ✓ <i>none</i>	1		30.00 <i>10</i>

90.00

Labour & Miscellaneous Charge

60	To R&R rear bumper reverse sensor	1		100.00 <i>20</i>
61	To check wiring and lighting system	1		80.00 <i>20</i>
62	To supply under-coating / putty on parts replaced	1		80.00 <i>20</i>
63	To perform anti rust treatment on affected areas	1		60.00
64	To diagnostic erase fault code memories	1		180.00 <i>150</i>
65	To repair, replace and realign damaged areas	1		600.00 <i>250</i>
66	To spray painting on affected areas	1		600.00 <i>250</i>
67	Sundries	1		50.00 <i>X</i>

1750.00

List Items Subtotal

Special Nett Items Subtotal

*L/S repair
without preparation.
2 day
13/12/19
1.50pm
no spray after part
Hoch ANN
85314873
Hoch ANN@KikiAuto.com*

*Rear bumper taken on
4.45pm
13/12/19
H. ANN*