

LKK Auto Consultants hence notify**the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: SLK7707Z
 Model: Mercedes Benz E200 AVG
 Chassis No: WDD2130422A399375
 Year of manufacture: 2017

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Items			
1	Rear bumper ✓ CRA	1	1576.80	1500.80 ✓
2	Rear bumper retainer RH X (svc)	1	147.60	
3	Rear bumper retainer LH X (svc)	1	147.60	
4	Rear bumper center bracket X (svc)	1	248.90	
5	Rear bumper bracket RH X (svc)	1	195.80	
6	Rear bumper bracket LH ✓ CRA	1	195.80	98.80 ✓
7	Rear bumper lower garnish ✓ SCN	1	485.60	280.70 ✓
8	Rear bumper chrome piece ✓ SCN LH	1	245.70	220.80 ✓
9	Rear bumper chrome diffuser LH ✓ SCN	1	382.50	
10	Reverse sensor LH ✓ short	2	1420.00	192 ✓
11	Reverse sensor wire harness set X svc	1	685.00	
12	Rear bumper reverse sensor bracket X svc ✓ msc	6	45 X 4 = 180.00	✓
13	Rear bumper reflector LH ✓ cn X SVC	1	128.60	
14	Rear bumper reinforcement X (R)	1	698.70	
15	Tail lamp LH ✓ SCN	1	1150.80	827.20 ✓

0.00

Special Nett Items

16	Rear bumper clip set ✓ msc	1	60.00	25 ✓
17	Tail lamp clip set ✓ msc	1	30.00	10 ✓
				<u>90.00</u>

Labour & Miscellaneous Charge

60	To R&R rear bumper reverse sensor	1	100.00	22 ✓
61	To check wiring and lighting system	1	80.00	20 ✓
62	To supply under-coating / putty on parts replaced	1	80.00	70 ✓
63	To perform anti-rust treatment on affected areas	1	60.00	
64	To diagnostic erase fault code memories	1	180.00	100 ✓
65	To repair, replace and realign damaged areas	1	600.00	250 ✓
66	To spray painting on affected areas	1	600.00	250 ✓
67	Sundries	1	nn	50.00 X

1750.00

List Items Subtotal

Special Nett Items Subtotal

Paints	3682.80
Paints less	10%
	3314.52
Sp nett	35
labour	660
	4009.52
45 less	20%
Total	3207.61
45 less	→ \$ 1220.00

L/S repair
 without pre-approval
 2 day
 13/12/19
 1.10pm
 resurvey rear part
 Hock ANN
 85314883
 Hock ANN @ KKK Auto. com

Resurvey taken on
 4.45pm
 13/12/19
 H. ANN