

NAZ CTI

ASSIGNMENT

From: NAZ Date: 13/12/19

Estimated Cost:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 1859S
at Workshop m/s Premier Automotive
of 23 chengi south Ave 2 # 01-02

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

X	X	✓
N/S	O/S	

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD 1859S Yt Regn: 16 DE 2014
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA OPTIMA

Colour: SILVER

Sp.Reading: 475,503

Eng/No:

C/No: KNAGM414MF556-1706

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65-R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HANKOOK

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 12/12/19

D.O.I. 13/12/19

Survey held at PREMIER CHANKI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L&D /

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Insp (\$)

☐ : Wheel end (\$)

Survey Fee:

Transportation:

☐ : S + PS, ☐ : ST

☐ : Photos

☐ : Other:

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

12-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	Bonnet
1 pc	Bonnet lock
1 pc	Bonnet lifter
1 pc	Bonnet lock base
1 pc	Bonnet hinge o/s & n/s @ \$23.00
1 pc	Bonnet grille
1 pc	Support panel
1 pc	Front bumper
1 pc	Front bumper emblem
1 pc	Front bumper centre grille
1 pc	Front bumper lower stiffer
1 pc	Front bumper tow hook cover
1 pc	Front bumper lip
1 pc	Front bumper inner sponge
1 pc	Front bumper reinforcement
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00
2 pcs	n/s & o/s headlamp @ \$1028.00
2 pcs	Front bumper o/s & n/s protector @ \$51.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00
1 pc	Air con condenser
1 pc	Radiator
1 pc	Air duct
1 pc	Intercooler
1 pc	Blower assy
1 pc	Boot lid
1 pc	Boot lid lock
1 pc	Bootlid lock cable
1 pc	Bootlid striker
1 pc	Bootlid emblem
1 pc	Bootlid CRDi
1 pc	Boot lid rubber weatherstrip
1 pc	Boot lid lower garnish
2 pcs	Bootlid hinges @ \$66.00
2 pcs	Rear license plate lamp @ \$30.00
2 pcs	Bootlid hinge torsion bar @ \$33.00
1 pc	Handle trunk lid hook
1 pc	Bootlid inner trim
1 pc	End panel
1 pc	End panel inner garnish

Kanchana

Finalized

18/3/2020

\$	979.00	/DD
\$	36.00	? / DEF
\$	70.00	? XSVL
\$	13.00	? XSVL
\$	46.00	XSVL
\$	385.00	/CRK
\$	645.00	? / DEF
\$	531.00	/CRK
\$	44.00	/NEC
\$	174.00	XSVL
\$	134.00	? XSVL
\$	14.00	/CRK
\$	52.00	? XSVL
\$	110.00	? / DEF
\$	328.00	? / BT
\$	32.00	} ? XSVL
\$	32.00	
\$	32.00	
\$	2,056.00	/SSR CRK
\$	102.00	? XSVL
\$	132.00	? XSVL
\$	805.00	/DEF
\$	669.00	} ? XSVL
\$	210.00	
\$	800.00	
\$	596.00	/DEF
\$	1,119.00	
\$	99.00	/JAM
\$	35.00	? XSVL
\$	21.00	/DEF
\$	27.00	/NEC
\$	29.00	/NEC
\$	96.00	/IN
\$	290.00	? / DEF
\$	132.00	? / DEF
\$	60.00	? / Blown
\$	66.00	? XSVL
\$	5.00	? XSVL
\$	190.00	? / DEF
\$	250.00	? / DEF
\$	74.00	? / DEF

8,320

12-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	Rear n/s fender
1 pc	Rear n/s fender inner shield
1 pc	Rear windscreen moulding
1 pc	Rear bumper
1 pc	Rear o/s fender top chrome moulding
1 pc	Rear n/s fender top chrome moulding
1 pc	Rear bumper lower cover
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00
1 pc	Rear bumper inner sponge
1 pc	Rear bumper reinforcement
2 pcs	Rear bumper stay o/s & n/s @ \$53.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00
2 pcs	n/s & o/s tail lamp @\$421.00
2 pcs	n/s & o/s reflector @\$350.00
1 pc	n/s tail lamp panel
1 pc	o/s tail lamp panel
1 pc	Spare tyre clamp
1 pc	Exhaust pipe
1 pc	Exhaust pipe hanger
1 pc	Floorboard panel
1 pc	Floorboard panel trim

Less 10%

\$	1,205.00	/BT
\$	120.00	? /TN
\$	87.00	/NEC
\$	696.00	/CRK
\$	97.00	? XSVL
\$	97.00	? XSVL
\$	206.00	/CRK
\$	58.00	? /DEF
\$	114.00	? /CRK
\$	607.00	? /BR
\$	108.00	? /BT
\$	36.00	? /DEF
\$	36.00	? /XSVL
\$	92.00	/CRK
\$	842.00	/CRK
\$	700.00	/CRK
\$	215.00	? /DEF
\$	215.00	? /DEF
\$	6.00	? /BR
\$	1,009.00	? /BT
\$	40.00	? /ZD /MIS
\$	625.00	? /DEF
\$	205.00	? /XSVL
\$	18,936.00	
\$	1,893.60	
\$	17,042.40	

6,981

S/NETT

1 set	Rear bumper clips
1 set	End panel inner garnish clips
1 set	Bootlid inner trim clips
1 set	Bootlid lower garnish clips
1 set	Bootlid stickers
1 set	Reverse sensor
1 pc	Rear bumper top protector
1 set	Floorboard compartment insulating paddings
1 pc	Rear no. plate with casing
1 pc	Coolant 6L

\$	48.00	/NEC
\$	30.00	? /NEC
\$	52.00	? /NEC
\$	60.00	? /NEC
\$	100.00	/NEC
\$	280.00	/MIS
\$	80.00	/NEC
\$	120.00	? XNN
\$	50.00	XSVL
\$	40.00	? XNN
	650	

12-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

- 1 pc Front no. plate with casing
 1 pc Front bumper clips
 2 pcs Front n/s & o/s head lamp lower clip @ \$6.00
 2 pcs Front n/s & o/s head lamp side clip @ \$3.00
 2 pcs front n/s & o/s fender sticker @\$60.00
 2 pcs Rear n/s & o/s fender sticker @\$60.00
 Sundry
 Towing Fee
 To check for wiring and to focus head lamps
 To top up aircon gas
 To dismantle / replace reverse sensor to new bumper and reset to the same
 To dismantle and refit the rear windscreen
 To dismantle / replace exhaust pipe
 To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.
 To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis
 To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear n/s taillamp panel, front bumper, bonnet, rear n/s & o/s chassis member, front o/s fender, front n/s fender, rear o/s fender, rear o/s taillamp panel
 To apply rustproofing on the repaired and replaced panels.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK
 13/12/19 1745
 LLS

8 DAYS.
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS.
 REQUEST book value to calculate repair (in)

PARTS \$15,301
 LESS 10% \$1,370.90
 NET \$ 956

LABOUR \$3,020

\$17,746.90

LESS GST 10% \$1,774.69

LESS TOTAL \$14,200.00

(10 DAYS)

\$ 50.00 X SVL
 \$ 48.00 / N/C
 \$ 12.00 / N/C
 \$ 6.00 / N/C
 \$ 120.00 / N/C
 \$ 120.00 / N/C
 \$ 50.00 X NV
 \$ X 50.00 show receipt / claim separate
 \$ 80.00 30
 \$ 120.00 ? / 60
 \$ 120.00 30
 \$ 120.00 100
 \$ 120.00 ? / 50
 \$ 180.00 80

\$ 3,000.00 1,260

\$ 3,000.00 1,260

3,020

\$ 300.00 150.
 \$ 25,398.40

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: