

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	Bonnet	\$	979.00	DD
1 pc	Bonnet lock	\$	36.00	?
1 pc	Bonnet lifter	\$	70.00	?
1 pc	Bonnet lock base	\$	13.00	?
1 pc	Bonnet hinge o/s & n/s @ \$23.00	\$	46.00	*SVC
1 pc	Bonnet grille	\$	385.00	/CRK
1 pc	Support panel	\$	645.00	?
1 pc	Front bumper	\$	531.00	/CRK
1 pc	Front bumper emblem	\$	44.00	/NEC
1 pc	Front bumper centre grille	\$	174.00	*SVC
1 pc	Front bumper lower stiffer	\$	134.00	?
1 pc	Front bumper tow hook cover	\$	14.00	/CRK
1 pc	Front bumper lip	\$	52.00	?
1 pc	Front bumper inner sponge	\$	110.00	?
1 pc	Front bumper reinforcement	\$	328.00	?
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	\$	32.00	} ?
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	\$	32.00	
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	\$	32.00	
2 pcs	n/s & o/s headlamp @ \$1028.00	\$	2,056.00	/SVC CRK
2 pcs	Front bumper o/s & n/s protector @ \$51.00	\$	102.00	?
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00	\$	132.00	?
1 pc	Air con condenser	\$	805.00	} ?
1 pc	Radiator	\$	669.00	
1 pc	Air duct	\$	210.00	
1 pc	Intercooler	\$	800.00	
1 pc	Blower assy	\$	596.00	/DEF
1 pc	Boot lid	\$	1,119.00	
1 pc	Boot lid lock	\$	99.00	/JAM
1 pc	Bootlid lock cable	\$	35.00	?
1 pc	Bootlid striker	\$	21.00	/DEF
1 pc	Bootlid emblem	\$	27.00	/NEC
1 pc	Bootlid CRDi	\$	29.00	/NEC
1 pc	Boot lid rubber weatherstrip	\$	96.00	/IN
1 pc	Boot lid lower garnish	\$	290.00	?
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	?
2 pcs	Rear license plate lamp @ \$30.00	\$	60.00	Blown
2 pcs	Bootlid hinge torsion bar @ \$33.00	\$	66.00	?
1 pc	Handle trunk lid hook	\$	5.00	?
1 pc	Bootlid inner trim	\$	190.00	?
1 pc	End panel	\$	250.00	?
1 pc	End panel inner garnish	\$	74.00	?

12-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	Rear n/s fender	\$	1,205.00	✓ BT
1 pc	Rear n/s fender inner shield	\$	120.00	?
1 pc	Rear windscreen moulding	\$	87.00	✓ NEL
1 pc	Rear bumper	\$	696.00	✓ CRK
1 pc	Rear o/s fender top chrome moulding	\$	97.00	? XSVL
1 pc	Rear n/s fender top chrome moulding	\$	97.00	? XSVL
1 pc	Rear bumper lower cover	\$	206.00	✓ CRK
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	?
1 pc	Rear bumper inner sponge	\$	114.00	?
1 pc	Rear bumper reinforcement	\$	607.00	?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	?
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	✓ CRK ?
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	✓ CRK
2 pcs	n/s & o/s tail lamp @\$421.00	\$	842.00	✓ CRK
2 pcs	n/s & o/s reflector @\$350.00	\$	700.00	✓ CRK
1 pc	n/s tail lamp panel	\$	215.00	?
1 pc	o/s tail lamp panel	\$	215.00	?
1 pc	Spare tyre clamp	\$	6.00	?
1 pc	Exhaust pipe	\$	1,009.00	?
1 pc	Exhaust pipe hanger	\$	40.00	?
1 pc	Floorboard panel	\$	625.00	?
1 pc	Floorboard panel trim	\$	205.00	?
		\$	18,936.00	
		Less 10%	\$	1,893.60
			\$	17,042.40

S/NETT

1 set	Rear bumper clips	\$	48.00	✓ NEL
1 set	End panel inner garnish clips	\$	30.00	?
1 set	Bootlid inner trim clips	\$	52.00	?
1 set	Bootlid lower garnish clips	\$	60.00	?
1 set	Bootlid stickers	\$	100.00	✓ NEL
1 set	Reverse sensor	\$	280.00	✓ MIS
1 pc	Rear bumper top protector	\$	80.00	✓ NEL
1 set	Floorboard compartment insulating paddings	\$	120.00	?
1 pc	Rear no. plate with casing	\$	50.00	X SVL
1 pc	Coolant 6L	\$	40.00	?

12-Dec-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1859 S

1 pc	Front no. plate with casing	\$	50.00	XSVL
1 pc	Front bumper clips	\$	48.00	/NHC
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	\$	12.00	/NHC
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	\$	6.00	/NHC
2 pcs	front n/s & o/s fender sticker @\$60.00	\$	120.00	/NHC
2 pcs	Rear n/s & o/s fender sticker @\$60.00	\$	120.00	/NHC
	Sundry	\$	50.00	XNN
	Towing Fee	\$	50.00	show receipt
	To check for wiring and to focus head lamps	\$	80.00	30
	To top up aircon gas	\$	120.00	?
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle and refit the rear windscreen	\$	120.00	100
	To dismantle / replace exhaust pipe	\$	120.00	?
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	80
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis	\$	3000.00	1,260
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear n/s taillamp panel, front bumper, bonnet, rear n/s & o/s chassis member, front o/s fender, front n/s fender, rear o/s fender, rear o/s taillamp panel	\$	3000.00	1,260
	To apply rustproofing on the repaired and replaced panels.	\$	300.00	150
		\$	25,398.40	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK
13/12/19 1745
LIS

8 DAYS.

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS.

request book value to calculate repair limit.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: