

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref : CC4/FCl19021998/R1ea3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 14-04-2020 Code: FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 2028Y	Veh. Inspected	YP 6573T	
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
	Claim No.	D19005789MFSH	Excess (\$)	0.00	
	Assign From	RACHEL WU	Assign Date	13/12/2019	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ ATEGO 1524	c.c	6374	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	WDB97007820117556	Colour	WHITE	
	Odometer	40737	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/09/2019	Inspection Date	24/12/2019	
	Survey held at	ASM AUTOMOTIVE SERVICES	PTE LTD		
	13 PIONEER SECTOR 1 SINGAPORE 628424				
5a.	Remarks				
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			