



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg

DATE : 09.12.2019

TO : MS First Capital Insurance Ltd
ATTN : Motor Claim Department
TEL. NO. : 6507-3848
EMAIL : motor_claims@first-insurance.com.sg

VEHICLE NO. : YP 6573 T
MODEL NO. : MERCEDES BENZ ATEGO
CHASSIS NO. : WDB97007820117556
ENGINE NO. : 902916C1127039
LTA REG DATE : 6/7/2017

CC : Sin Guan Lee Trading
ATTN : Ms. Joelyn

CLAIM TYPE : Third Party - SHC 2028 Y
D.O.A : 05.09.2019
CLAIM REF NO. : asm/AC19118/JL

Quotation for Accident Repair

S/N	SPARE PARTS	QUANTITY	UNIT PRICE	AMOUNT
1	Front bumper, LH <i>bro</i> ✓	1	\$ 450.00	\$ 450.00
2	Bumper bracket, LH <i>bro</i> ✓	1	\$ 70.00	\$ 70.00
3	Headlamp, LH <i>era</i> ✓	1	\$ 700.00	\$ 700.00
4	Step panel, LH <i>scat repair</i>	1	\$ 787.50	\$ 787.50
5	Side signal lamp, LH <i>bo</i> ✓	1	\$ 37.50	\$ 37.50
SUB-TOTAL :				\$ 2,045.00
LESS 20% :				\$ 409.00
BALANCE :				\$ 1,636.00

LABOUR CHARGES

1 To remove and replace damaged parts, check lamp wiring etc. (\$350 x 4 days)

875
\$ 1,400.00

TOTAL LABOUR :

\$ 1,400.00

GRAND TOTAL :

\$ 3,036.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Facul
Hy 90010068
3 days
P/P
24/12/19 01140
Reay before repair