

First Car - LKK 23/12/19



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLN 6431 J

*Not Authorized  
Return After Paint*

<b>Parts</b>	(a) Cost / List Price Items	\$	<u>1,894.10</u>
	Plus/Less 25%	\$	<u>473.53</u>
	<b>Total of Cost / List</b>	\$	<u><u>1,420.58</u></u>
	(b) Nett Price Items		_____
	Less		_____
	<b>Total of Nett Item</b>		_____
	(c) Special Nett Items	\$	<u>200.00</u>
<b>Total Parts Cost</b>		\$	<u><u>1,620.58</u></u>
<b>Labour</b>		\$	<u><u>2,140.00</u></u>
<b>Total</b>		\$	<u><u><u>3,760.58</u></u></u>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 23/12/19 at 11.50am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : Le Date: 23/12/19



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Spare Parts

Vehicle No. : SLN 6431 J  
 Make & Model : TOYOTA PRIUS  
 Chassis No : JTDKB3FUX03557933

Submit By : JENNY  
 Year Manufacture : 2017  
 Engine No. : \_\_\_\_\_

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>P<sub>2</sub></i>	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		?
3	Rear bumper clip	10	\$40.00		?
4	Rear bumper side retainer LH <i>P<sub>2</sub></i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>S<sub>2</sub></i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre <i>Red/G<sub>2</sub></i>	1	\$582.60		✓
8	Rear bumper lower garnish RH <i>S<sub>2</sub></i>	1	\$149.70		X
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : SLN 6431 J Submit By : Carmen Lim  
 Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$800.00	1501
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL)	\$800.00	2001
3	To Check wiring <i>nn</i>	\$50.00	X
4	To remove & refit reverse sensor	\$120.00	?
5	To remove & refit spare tyre, spare tyre board, carpet trim <i>nn</i> to assist work load.	\$150.00	X
6	To conduct water leakage tests to ensure proper air and <i>nn</i> sealing	\$120.00	X
7	To tuff coat. <i>nn</i>	\$100.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.