

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 17.12.19

TO : AXA MOTOR CLAIMS DEPTS

VEHICLE NO : SLF3026H

MODEL : HONDA VEZEL

DATE OF ACCIDENT : 12.12.19

TIME OF ACCIDENT : 07:50HRS

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR FENDER LH <i>Repld</i>	1	\$ 1,120.00	\$ 1,120.00
2	REAR FENDER COWLING LH <i>Repld</i>	1	\$ 150.20	\$ 150.20
3	REAR FENDER ARCED GARNISH LH <i>Repld</i>	1	\$ 184.70	\$ 184.70
4	REAR FENDER INNER TRIM LH <i>Repld</i>	1	\$ 399.10	\$ 399.10
5	REAR FENDER AIR VENT LH <i>Repld</i>	1	\$ 83.00	\$ 83.00
6	REAR MUDFLAP LH <i>Repld</i>	1	\$ 96.20	\$ 96.20
7	REAR BUMPER <i>Repld</i>	1	\$ 865.50	\$ 865.50
8	REAR BUMPER REFLECTOR LH <i>Repld</i>	1	\$ 151.10	\$ 151.10
9	REAR BUMPER SIDE LH <i>Repld</i>	1	\$ 230.00	\$ 230.00
10	REAR BUMPER SIDE RETAINER <i>Repld</i>	2	\$ 57.00	\$ 114.00
11	TAIL LAMP LH <i>Repld</i>	1	\$ 475.00	\$ 475.00
12	TAILGATE <i>Dented</i>	1	\$ 1,100.00	\$ 1,100.00
13	TAILGATE LOGO <i>Repld</i>	1	\$ 65.00	\$ 65.00
14	TAILGATE EMBLEM 'VEZEL' <i>Repld</i>	1	\$ 75.50	\$ 75.50
15	TAILGATE OUTER GARNISH <i>Repld</i>	1	\$ 220.00	\$ 220.00
16	TAILGATE SIDE LAMP LH <i>Repld</i>	1	\$ 240.00	\$ 240.00
17	TAILGATE STOPPER <i>Repld</i>	2	\$ 19.00	\$ 38.00
18	TAILGATE TOP LOCK <i>Repld</i>	1	\$ 180.00	\$ 180.00
19	TAILGATE LOWER LOCK <i>Repld</i>	1	\$ 24.70	\$ 24.70
20	TAILGATE INNER TRIM <i>Repld</i>	1	\$ 398.60	\$ 398.60
21	TAILGATE WEATHER STRIP <i>Repld</i>	1	\$ 168.40	\$ 168.40
22	TAILGATE WINDSCREEN MOULDING (SET) <i>Repld</i>	1	\$ 164.00	\$ 164.00
23	BUZZER <i>Repld</i>	1	\$ 109.00	\$ 109.00
24	REAR END PANEL <i>Dented</i>	1	\$ 530.00	\$ 530.00
25	REAR END PANEL TOP GARNISH <i>Repld</i>	1	\$ 146.30	\$ 146.30
26	REAR FLOOR PANEL BOTTOM GARNISH <i>Repld</i>	1	\$ 269.00	\$ 269.00
27	REAR FLOOR PANEL TOP BOARD <i>Repld</i>	1	\$ 300.40	\$ 300.40
28	REAR STORAGE BOX <i>Repld</i>	1	\$ 269.70	\$ 269.70

5792.50

4634

TOTAL PRICE \$ 8,167.40
LESS 20% \$ 1,633.48
SUB TOTAL PRICE \$ 6,533.92

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLF3026H
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 12.12.19
 TIME OF ACCIDENT : 07:50HRS

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR T NUMBER PLATE <i>Ne Nc</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>Xh</i>	1	\$ 80.00	\$ 80.00	30
3	TAILGATE OUTER GARNISH CLIP (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00	+
4	TAILGATE INNER TRIM BOARD CLIP (SET) <i>Ne</i>	1	\$ 80.00	\$ 80.00	30
5	TAILGATE WINDSCREEN SEALANT <i>2/100</i>	1	\$ 80.00	\$ 80.00	30
6	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
7	TAIL LAMP CLIP (SET) <i>Ne</i>	1	\$ 40.00	\$ 40.00	10
8	REAR FENDER SEALANT LH <i>Ne m</i>	1	\$ 150.00	\$ 150.00	+
9	REAR FENDER INNER TRIM CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	30
10	REAR FENDER COWLING CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER ARCED GARNISH CLIP LH (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	+
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>Ne</i>	1	\$ 50.00	\$ 50.00	20
13	REAR END PANEL INSULATION SEAL <i>Ne</i>	1	\$ 150.00	\$ 150.00	60
14	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	+
15	REVERSE CAMERA <i>Ne n</i>	1	\$ 480.00	\$ 480.00	+
16	REVERSE SENSOR (SET) <i>Ne n</i>	1	\$ 220.00	\$ 220.00	+
		280.	TOTAL	\$ 1,810.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800
3	TUFF COAT	\$ 250.00	60
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	60
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLF3026H**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 12.12.19
 TIME OF ACCIDENT : 07:50HRS

10	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
11	REMOVE AND REFIX REAR VIDEO CAMERA	\$ 80.00	✓ 50
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,270.00

2070

TOTAL PARTS COST : \$ 8,343.92
 TOTAL LABOUR COST : \$ 5,270.00
 TOTAL REPAIR COST : \$ 13,613.92

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian L
 h/s 18/12/19.

06 days.

total: 6944.

4/s: 5.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

ACKNOWLEDGED BY REPAIRER