



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003361
INV Date 22/04/2020
Reference CS/SMO19022006/Eqd3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SKA 326A
Insured Veh.
Claim No. CMTD1905642/AGC
Policy No.
Accident Date 29/11/2019
Inspection Date 16/12/2019

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO19022006/Eqd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 22-04-2020



Code : SMO

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKA 326A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1905642/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	13/12/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NOTE	c.c	1198
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JN1TAAE12Z0983121	Colour	PINK
Odometer	3346	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm
R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm
L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/11/2019	Inspection Date	16/12/2019
Survey held at	TAN CHONG MOTOR SALES PTE LTD 911 BUKIT TIMAH ROAD SINGAPORE 589623		

5a. Remarks

A)THE MARKET VALUE IS S\$60,000.00 (EST. AVERAGE)
 B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 326A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
4	CLIP @\$8.00 (SN)	NECESSARY	32.00	21.84
10	CLIP @\$1.30 (SN)	NECESSARY	13.00	8.90
10	CLIP @\$1.30 (SN)	NECESSARY	13.00	8.90
1	EXBLEM RAD GRIL (SN)	CRACKED	64.90	44.26
1	GRILLE-RADIATOR (SN)	TO REPAIR SEE LABOUR	204.80	-
1	GRILLE-RADIATOR (SN)	BROKEN	276.70	188.71
1	BRACKET-BUMPER (SN)	NOT NECESSARY	24.80	-
1	BRACKET-BUMPER RH (SN)	BROKEN	26.60	18.14
1	FACE-FR BUMPER (SN)	DENTED	394.30	268.91
1	RH HEADLAMP (ADDITIONAL)(SN)	BROKEN	365.48	365.48
1	SUNDRIES (SN)	NECESSARY	30.00	20.00
			1,445.58	945.14
	<u>LABOUR</u>			
	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS.		60.00	60.00
	R/INSTALL HEADLAMP.		48.00	48.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	NOT NECESSARY	120.00	-
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	-
	REPAIR FRONT UPPER BUMPER & FRONT RH SIDE FENDER RENEW FRONT BUMPER COVER.INCLUSIVE OF THE REPAIR OF GRILLE-RADIATOR.		570.00	285.00
	S/PAINT FRT BUMPER,FRT UPPER BUMPER & FRT RH SIDE FENDER.		555.00	277.50
	-		-	-
	-		-	-
	-		-	-
			1,453.00	670.50
GRAND TOTAL			2,898.58	1,615.64
RECOMMENDED COST OF REPAIRS				1,615.64

Report Ref No. CS/SMO19022006/Eqd3n2



Report Ref No. CS/SMO19022006/Eqd3n2

A black ink signature of Chen Tsue Yee, consisting of a stylized 'C' followed by 'T' and 'Y'.

CHEN TSUE YEE

Automotive Assessor

A black ink signature of Adrian Ling Wai Ping, featuring a stylized 'A' and 'L'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 326A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

