Payee 2: (Strike if N.A.)

Payee 3: (Strike if N.A.)

88

22

Name 2:

Name 3:



Insurance Company:

LKK Auto Consultants hence notify

CARZ AUTO SERVICES PTE LED ing:

UEN/ GST 201409437D. To display damaged part(s) during resurvey 61 WOODLANDS IND PARK E9 (E9 PREMIUM) 404-04 Singapore 757047 femalion

Email: alex@carzauto.com.sg Tel: 65 6493 1924 http://dax.ofe.6493 1928 without Prejudies' basis

No illegal modification(s) is allowed

 Supplementary therein) must be resurroyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Date:

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

Telephone:

Address:

Fax:

Make Model:

TOYOTA HIACE

FWD Singapore Pte Ltd

Date:

10/12/2019

Chassis No:

JTFHT02P700245079

Vehicle No.

GBH 8376 Y

Date/Time of Accident:

28/11/2019 17:30

4/5= 2,650 4 days

Materials Cost/ Spare Parts Cost

ITEMS	DESCRIPTION (LIS	MPLETED BY SERVI (T PARTS)	QTY	LIST PRICE S	DISCOUNT	FIN/	AL PRICE 5
1	SLIDING DOOR LH	100	1	\$ 1,615.4	0 25%	5	1,211.55
2	SLIDING DOOR HINGE LH	XIV	1	5 174.9	0 25%	\$	131.18
3	SLIDING DOOR LOCK LH	×5ve	1	\$ 509.4	0 25%	5	382.05
1	REAR FENDER LH	, 00	-1	5 1,162.6	5 25%	5	871.99
			LIST PAR	TS COST AFTI	R DISCOUNT	S	2,596.76

Labour Work / Panel Beating Related Works	
Job Scope	Quotation
TO REMOVE AND RENEW REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 600 800.0

Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 500 700.0

Labour Works

Job Scope		Quotation.		
TO TUFFCOAT AFFECTED AREA	5	40	150.00	
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	5	50	100.00	
TO REMOVE AND REPLACE SLIDING DOOR MECHANISM 50	5	80	100.00	
OTHER LABOUR COST	5		350.00	

Repair day - 4 days Lump Sum Repair After puit photo

GRAND TOTAL S 4,446.76

2,178.05 - 757. P = 2,083.54

3,323.54

20%

Sunpin @ 1 kkauto . rom-

8661 2624

2,658.87

Person Incharge: Ms Jesiyn Chua Job Title: Motor Claim

CARZ AUTO SERVICES PTE LTD

Mobile: 65 8322 7418 Email: jeslyn@carzauto.com.sg

Sun Pin (Llux) 17/12/2014

The worthout prejude

SUPPRICAL Page 1 of 2

Oi Sun Pin (LKK Auto)

From:

alex@carzauto.com.sg

Sent:

Tuesday, 7 January, 2020 9:19 AM

To:

Oi Sun Pin (LKK Auto)

Subject:

RE: GBH 8376 Y AFTER REPAIR PHOTO

Follow Up Flag:

Follow up

Flag Status:

Flagged

Hi Mr Oi Sun Pin

We are able to accepted your offer . Thanks

All Document who should we send too?

Please advice

Best Regards

Alex

----Original Message----

From: Oi Sun Pin (LKK Auto) < sunpin@lkkauto.com>

Sent: Tuesday, January 7, 2020 9:07 AM

To: alex@carzauto.com.sg

Subject: RE: GBH 8376 Y AFTER REPAIR PHOTO

Dear Alex.

Kindly refer the finalize amount \$2,650. Repair day 4 days, (L/S, before gst). If agree please update.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

----Original Message-----

From: alex@carzauto.com.sg [mailto:alex@carzauto.com.sg]

Sent: Monday, 23 December, 2019 1:46 PM

To: Oi Sun Pin (LKK Auto) Cc: jeslyn@carzauto.com.sg

Subject: GBH 8850 Y AFTER REPAIR PHOTO

Hi Mr Sun Pin

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Partie days	
Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	805G
Vehicle Details	
Vehicle No.:	GBH8376Y
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2826393
Chassis No.:	JTFHT02P700245079
Maximum Power Output:	*
Open Market Value:	\$28,136.00
Original Registration Date:	15 Oct 2018 / 8 yrs 10 miths / 106 miths
First Registration Date:	15 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1.407.00
Intended PARF Rebate Details	*41797700
PARF Eligibility:	No
PARF Eligibility Expiry Date:	*:
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	*****
COE Expiry Date:	14 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27.104.00
COE Rebate Amount:	\$23,908.00
Total Rebate Amount:	\$23,908.00
The information contained herein is correct as at 18 Dec 2019	ACCULATION

OK

5,566/12 = 458.71

458.37 × 106=48,58]

MV = 41,583





LKK Auto Consultants hence notify

CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D. To display damaged purits) during resurvey

61 WOODLANDS IND PARK E9 (E9 PREMIUM), 404-04 Singapore 757943 demailion

Tel: 65 6493 1924 hirofiast 65,6493 1928 Without Projudice basis Email: alex@carzauto.com.sg

. No illegal modification(s) is allowed

Пý

		Supplementary Interest on Insurpress Assu
Insurance Company:	FWD Singapore Pte Ltd	is subject to time approve from trade de compar
50.74		A SALES AND DESCRIPTION OF THE PARTY OF THE

Azknowledged by Repairer

Date:

6 Temasek Boulevard, #18-01 Suntee Tower Four, Singapore 038986

Telephone:

Address:

Fax:

Make/ Model:

TOYOTA HIACE

Date:

10/12/2019

Chassis No:

JTFHT02P700245079

Vehicle No:

GBH 8376 Y

Date/Time of Accident:

28/11/2019 17:30

	per consistence and a second s	MPLETED BY SERV			T HOLES C	PARTS	FINA	L PRICE \$
ITEMS	DESCRIPTION (LIS	T PARTS)	QTY	LIS	T PRICE \$	DISCOUNT	11110	
-	SLIDING DOOR LH	100	- 1	5	1,615.40	25%	S	1,211.55
-	SLIDING DOOR HINGE LH	XIVC	1	5	174.90	25%	5	131.18
7	SLIDING DOOR LOCK LH	×5ve	1	5	509.40	25%	\$	382.05
3	5V11051001422015	/ pp	1	S	1.162.65	25%	5	871.99
4	REAR FENDER LH		LICT DAD	TSC	OST AFTER	DISCOUNT	5	2,596.76

Labour Work / Panel Beating Related Works	Quantition
Job Scope	Quotation
TO REMOVE AND RENEW REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	s 600 800.00

Spray Painting Job Scope		Quotation
The state of the s	Job Scope	\$ 500 700.0
TO RESPRAY AFFECTED AREAS		

Labour Works

Job Scope		Que	otation
TO TUFFCOAT AFFECTED AREA	5	80	150.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	5	50	100.00
TO REMOVE AND REPLACE SLIDING DOOR MECHANISM 50) 5	100	100.00
OTHER LABOUR CO	T 5	K	350.00

GRAND TOTAL S 4,446.76

Repair day - 4 days Lump Sum Repair After puit photo

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua

Job Title: Motor Claim Mobile: 65.8322.7418

Email: jeslyn@carzauto.com.sg

Sun Pin (Llik)

17/12/2019

Sunpin @ 1 kkautu . rum 8661 2624

TP without prejudes

LKK Auto Consultants Pte Ltd (Co.Reg.No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

FWD Singapore Pte. Ltd. To:

6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Lionel Tan Attn:

Date: 23 Dec 2019

Preliminary Advice

Insured Vehicle No SLU9814G

TP Vehicle No

GBH8376Y

Accident Date

28/11/2019

Make

TOYOTA DYNA 150

Assignment Date

: 13/12/2019

Date of Inspection

: 17/12/2019

Est. Duration of Repair

4 days

Inspection At

: Carz Auto Services Pte Ltd - Woodlands (HQ)

NO 51, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047

Singapore 757047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ... N/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,446.76
Revised Amount	:S\$	3,363.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,363.54

:88 Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:5\$

Remarks

(y	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.

Nivitha (LKK Auto)

22010 (P67

10-39amo 13/12/11

p: Jesylyn v: Not In amage on 16/12/19

From:

venessa.chan@fwd.com

Sent:

Friday, 13 December 2019 9:52 AM

To:

'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'

Cc:

motorclaims.sg@fwd.com; lionel.tan@fwd.com

Subject:

Request Surveyor for pre-repair inspection Our Ref: GBH8376Y Your Ref: SLU9814G

Attachments:

PRI GBH8376Y.pdf

Dear Nivitha.

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards.

Venessa Chan

Administrative Assistant, Claims



FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

venessa.chan@fwd.com

www.fwd.com.sg



From: jeslyn@carzauto.com.sg [mailto:jeslyn@carzauto.com.sg]

Sent: Thursday, December 12, 2019 4:17 PM

To: Motor Claims SG - SG Common

Cc: alex@carzauto.com.sg

Subject: Request Surveyor for pre-repair inspection Our Ref: GBH8376Y Your Ref: SLU9814G

Hi Sir

Good Afternoon

Please arrange surveyor for pre-repair inspection.

Please conduct the survey at 61 Woodland Industrial Park E9 #04-04 (Premium 9) Singapore 757047.

Thank You.

With Regards, Jeslyn Chua HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OPPICE & ACCESSORIES WORKSHOP, CAR GROCOUNTS WOCKSHOP, SPRAY PAINTING WOCKSHOP, ACCOUNT REPORTS & SERVICE WOCKSHOP, ACCOUNT REPORTS & SERVICE WOCKSHOP,

TEL: 6100 3000 FAX: 6100 3001 MP: 1022 2226 1 KARI BUNTE AVE 6, WILLIS, (AUTOBANGISAT BURTE, UNGAPORE 457885)
1 KARI BUNTE AVE 6, WILLIS, (AUTOBANGISAT BURTE, UNGAPORE 417885)
1 KARI BUNTE AVE 6, WILLIS, (AUTOBANGISAN BURTE, UNGAPORE 417885)
1 KARI BUNTE AVE 6, WILLIA, (AUTOBANGISAN BURTE, UNGAPORE 417885)
15 WOODGLANDS SPUSTINIA, PARK ES, WIR 64, UNESAULUS ØF ES, UNGAPORE 73/04/2
2794 MACHINERISON BURDE, UNARE SPUSTI SERVICE SPUSTINIA ØF ES), UNGAPORE 73/04/2

PR:

SALESGICAREAUTO-COM-SG FACEBOOK-COMPCAREAUTOSERVICES HTTP://WWW.CAREAUTO-COM-SC

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Hsiao Tong (LKKAuto)

From:

Lionel Tan Tian Pei - SGUser < lionel.tan@fwd.com>

Sent:

Tuesday, 4 February 2020 9:47 AM

To:

Hsiao Tong (LKKAuto)

Cc:

Admin A

Subject:

RE: Your Ref: 1201900037225 *Our Ref: CC4/FWD19022010/Qpa3 [ACCIDENT

INVOLVING SLU 9814G(FWD) AND GBH 8376Y ON 28/11/2019]

Gd morning

You may proceed DS

Regards, Lionel

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Monday, February 3, 2020 3:50 PM

To: Lionel Tan Tian Pei - SGUser < lionel.tan@fwd.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your Ref: 1201900037225 *Our Ref: CC4/FWD19022010/Qpa3 [ACCIDENT INVOLVING SLU 9814G(FWD)

AND GBH 8376Y ON 28/11/2019]

Hi Lionel,

We refer to our below email.

Kindly assist to upload a copy of insured video in Merimen for our viewing and advise if we may proceed DS.

Thank you.

"Wishing you a Happy and Prosperous New Year"



Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Hsiao Tong (LKKAuto)

Sent: Thursday, 9 January 2020 2:03 PM

To: lionel.tan@fwd.com

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Your Ref: 1201900037225 *Our Ref: CC4/FWD19022010/Qpa3 [ACCIDENT INVOLVING SLU 9814G(FWD)

AND GBH 8376Y ON 28/11/2019]

Hi Lionel,

We refer to our below email.

Kindly assist to upload a copy of insured video in Merimen for our viewing and advise if we may proceed DS.

Thank you.

"Wishing you a Happy and Prosperous New Year"



Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 27 December 2019 7:52 AM

To: lionel.tan@fwd.com

Cc: Admin A <admin-a@lkkauto.com>

Subject: Your Ref: 1201900037225 *Our Ref: CC4/FWD19022010/Qpa3 [ACCIDENT INVOLVING SLU 9814G(FWD)

AND GBH 8376Y ON 28/11/2019]

Your Ref: 1201900037225

Our Ref: CC4/FWD19022010/Qpa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLU 9814G(FWD) AND GBH 8376Y ON 28/11/2019

We refer to the above matter.

Third party reported that our insured driver dashed out from parking lot and collided with third party vehicle.

Our insured reported that she was adjusting her cat into the lot. When she parked inside the lot, third party came from her right and hit onto her car front left portion.

Kindly assist to upload a copy of insured video in Merimen for our viewing and advise if we may proceed DS.

Thank you.

Best Wishes for Merry Christmas, and Happy New Year 2020

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

3 /	AUDIT '	TRAIL		By
la.	On	Audit	Remarks	
1	13 Dec 2019 16:41	Clm Dtl Modified	Claimant's Name: ->	[A] HOW MEI KWAN
2		Cim Veh Model Changed	(204479) TOYOTA DYNA 150 3.0 D (M).	[A] HOW MEI KWAN
3	13 Dec 2019 16:41	Clm Created	Reg No: GBH8376Y. Acct Date: 2019/11/28. Claim Type: TP. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Carz Auto Services Pte Ltd - Woodlands (HQ)	[A] HOW MEI KWAN
4	13 Dec 2019 16:41	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):; RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : RT Ap praisal Pte Ltd.	(A) HOW MEI KWAN
5		Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/12/24	[A] HOW MEI KWAN
6	13 Dec 2019 16:41	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	(A) HOW
7	13 Dec 2019 16:43	Label Added	(20005):Direct Settlement .	(A) HOW MEI KWAN
8	13 Dec 2019 16:43	Adjuster Assigned	[None] -> OI SUN PIN	[A] HOW MEI KWAN
9	13 Dec 2019 18:04	Clm Registration Modified	Pol No:->PNPV2018-00016544.	[I] Venessi Chan
10	13 Dec 2019 18:04	Clm Registration Modified	Pol No:PNPV2018-00016544->PNPV-2018-00016544.	[1] Venessi Chan
11	23 Dec 2019 16:06	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/12/24	[A] HOW MEI KWAN
12	14 Feb 2020 14:26	Adj Rpt Initiated		[A] JOANN LEE KHANG MIN
13	14 Feb 2020 14:26	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] JOANN LEE KHANG MIN
14	14 Feb 12020 14:26	Clm Dti Modified	JP) Reg. Date: -> 2018/10/15.	[A] JOANN LEE KHANG MIN
1!	14:26 14 Feb 2020 14:26	Clm Details Notified		[A] JOANN LEE KHANG MIN
16	19 Feb 2020 16:51	Adj Mandate Request	Cur.Req:3342.95:LIABILITY: 100%* QUANTUM: (a) CORW/GST: \$2,835.50 + (b)LOR: \$500.00 (5days x \$100) + (c) DISBURSEMENT: \$7.45 Total: a+b+c = \$3,342.95 *VEH MODEL: Toyota Hiace Turbo (2982c c). FOR YOUR APPROVAL/INSTRUCTION.	[A] CHEW HSIAO TONG

▼ Go 4 P Audit Type None ■ Date To Date From

ACTIVITY

No record

lerimen Bill	ing for this cas	e - Transactio	n History					
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref.1	Ref 2	Amount
2376802	13 Dec 2019 18:04:19	TP Case (Insurer)	Motor	FWD Singapore Pte. Ltd. (HQ)	FWD Singapore Pte. Ltd. (HQ)	GBH8376Y	LI YAN	xx.xx
2385319	23 Dec 2019 16:06:37	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBH8376Y	SLU9814G	11.77

Print Received Message

This mail is associated with:

*GBH8376Y (1201900037225) [SLU9814G] TP MOMENTS LOFT LOGISTICS PTE LTD Nov 28 2019 5:00PM [Li Yan] Carz Auto Services Pte Ltd - Woodlands

From To

FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 19/02/2020 18:37 PM.

LKK HQ

Subject

Alert - Adj Mandate Approved (S\$3342.95) - GBH8376Y - Claim Handler: Lionel Tan

Approved:3342.95.		

Hsiao Tong (LKKAuto)

From:

alex@carzauto.com.sq

Sent:

Monday, 24 February 2020 12:13 PM

To:

Hsiao Tong (LKKAuto); jeslyn@carzauto.com.sg

Subject:

RE: Request Offer for Vehicle Number: GBH8376Y // DOA: 28/11/2019 //LKK REF:

CC4/FWD19022010/Qpa3

HI Ms Hsiao Tong

We are able to accepted your offer @ \$3340/- All In

Please kindly submit to your insurer. Thanks

Best Regards

Alex

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Monday, February 24, 2020 12:05 PM

To: jeslyn@carzauto.com.sg Cc: alex@carzauto.com.sg

Subject: RE: Request Offer for Vehicle Number: GBH8376Y // DOA: 28/11/2019 //LKK REF: CC4/FWD19022010/Qpa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$3,340.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jeslyn@carzauto.com.sg <jeslyn@carzauto.com.sg>

Sent: Monday, 24 February 2020 11:54 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: alex@carzauto.com.sg

Subject: RE: Request Offer for Vehicle Number: GBH8376Y // DOA: 28/11/2019 //LKK REF: CC4/FWD19022010/Qpa3

Hi Ms Hsiao Tong

Good Afternoon

Any updated news? Please let us know as soon as possible.

Thank You.

With Regards, Jeslyn Chua HP: 8322 7418



From: jeslyn@carzauto.com.sg [mailto:jeslyn@carzauto.com.sg]

Sent: Friday, 14 February 2020 11:52 AM

To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com> Cc: 'alex@carzauto.com.sg' <alex@carzauto.com.sg>

Subject: RE: Request Offer for Vehicle Number: GBH8376Y // DOA: 28/11/2019 //LKK REF: CC4/FWD19022010/Qpa3

Hi Ms Hsiao Tong

Noted.

Thank You.

With Regards,

Jeslyn Chua HP: 8322 7418



CARZ AUTO SERVICES PTE LTD

MAIN OFFICE & ACCESSORIES WORKSHOP, CAR GRIGORIES WORKSHOP, SPRAF PAINTING WORKSHOP, ACCESSIVE REPAIR & SERVICE WORKSHOP, ACCESSIVE REPAIR & SERVICE WORKSHOP,

FAX: SHOP NOW HAT: SHOP NOW I KARI BURDT AVE S. 160-26, URUTOBANIPGARI BURDT, UNGAPORE 417885
I KARI BURDT AVE S. 60-35, LIKUTOBANIPGARI BURDT, UNGAPORE 417885
I KARI BURDT AVE S. 60-16. LIKUTOBANIPGARI BURDT, UNGAPORE 417885
I KARI BURDT AVE S. 60-16. LIKUTOBANIPGARI BURDT, UNGAPORE 417885
45 WOODCARDS INDUSTRIAL PARK ES, 60-60, (PREMILIA Ø ES), LINGAPORE 757647
UNGAPORHEPSON BORGE, (TRAFF UNGL. 159764) ESTATOON, UNGAPORADOR 757647

EMAIL:

SALESPICAREAUTO COM NO FACEBOOK COM/CAREAUTOSEPVICES

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Friday, 14 February 2020 11:48 AM

To: <u>jeslyn@carzauto.com.sg</u> Cc: <u>alex@carzauto.com.sg</u>

Subject: RE: Request Offer for Vehicle Number: GBH8376Y // DOA: 28/11/2019 //LKK REF: CC4/FWD19022010/Qpa3

Without Prejudice

Dear Sirs/Mdm,

Thank you for your email.

We will expedite the matter and send you the offer.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jeslyn@carzauto.com.sg <jeslyn@carzauto.com.sg>

Sent: Friday, 14 February 2020 9:21 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: alex@carzauto.com.sg

Subject: Request Offer for Vehicle Number: GBH8376Y

Hi Ms Hsiao Tong

Good Morning

Please chase insurance settle this with us as soon as possible or you may give us the officer in-charge contact number or email so that we can contact the officer.

Thank You.

With Regard Ms Jeslyn Chua

...CLAIM SUBFOLDER...(Pending for Survey Report) Oirect Settlement

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj 5	Submitted	Ins Auth'ed	Status		
Marin	02 Dec 2019 Edit Reg		13 Dec 2019 00:00 Edit Adj Rpt	100000000000000000000000000000000000000	S\$2,650.00 Edit Estimates		,650.00 sw Rpt		Pending for Surve Report Cancel Case		
21	Main	R	eference		iaim Det	ails		Documents		Show All	
CLAIM SU	BFOLDER DE	TAILS		lat a			[Created	by adjuster]			
Insured:	Li Yan,	D: S8983339F									
Main Claimant:	MOMENT	S LOFT LOGISTIC	S PTE LTD, Co.	Reg. Na.: 2	01829805	iG :					
Vehicle Reg No.:	GBH837	GBH8376Y				Loss:		9 17:00 - :59 and 13 Days Fro	m LTA Reg Da	ite (Man Yr))	
Claim Type	TP / 120	1900037225			Policy/Co			IPV-2018-00016544 (Comprehensive) overage: 19/12/2018 - 18/12/2019			
Vehicle Reg No. (Insured):	SLU9814G				Policy No (Claimar		5104649000-01				
					Excess:						
Repairers		Services Pte Lt 57047 Woodlands	d - Woodlands (H - Tel:	Q) NO 61, 1	WOODLAN	DS IN	IDUSTRIAL P	ARK E9, #04-04 E	9 PREMIUM S	INGAPORE	
Handling Insurer:	FWD Sing	papore Pte. Ltd.	(HQ) - Tel: 6727 5	700 [Han	dled by Li	ionel	Tan]				
Claimant's Insurer:	(4) (1) (4) (4) (4) (4)	THE COURSE OF THE PARTY OF THE	Co-operative Ltd (
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	256-3561	[Handled	by O	I SUN PIN	[Final Rpt	tue 24/12/2	[019]	
ASSOCIAT	ED MAIL RE	CEIVED						Vie	w All Corr	pose Case Ma	
 FWD_SG 	(19/02/2020): Alert - Adj Ma	ndate Approved (\$\$3342.95) - GBH8	376Y	- Claim Ha	ndler: Lionel Tar			
ALL ASSO	CIATED TAS	sks=				- 0	View Alt 1	Search Tasks C	reate New Tas	k Complet	
Due Dat	e Priority	Type Task	Group Subje	ct Hand	ller A	ssign	ned By	Completed On	Created	On Don	

Claim Documents

*GBH8376Y (1201900037225)

[SLU9814G]

TP

MOMENTS LOFT LOGISTICS PTE LTD

Nov 28 2019 5:00PM

[Li Yan]

Carz Auto Services Pte Ltd - Woodlands

Lett	ers/Corresponder	ices	1 per	page 🗸	82
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page 🔽	Ø
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	23/12/19 16:06	Adjuster Immediate Advice	6	Load HTM	
Pho	tos/Images		3 per	page 🔻	12
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	27/12/19 07:51	Odometer Reading	0	Load 3PG	2
2	27/12/19 07:51	Chassis Number	0	Load JPG	82
3	27/12/19 07:51	General View	0	Load JPG	8
4	27/12/19 07:51	General View	0	Load JPG	Ø
5	27/12/19 07:51	General View	0	Load JPG	12
6		General View	0	Load JPG	12
	27/12/19 07:51	THE CONTRACTOR OF THE CONTRACT	0	Load JPG	12
7	27/12/19 07:51	General View	0	Load 3PG	120
8	27/12/19 07:51	General View		MIN. 0.10.10.10.10.10.10.10.10.10.10.10.10.10	80
9	27/12/19 07:51	General View	0	Load 3PG	-
10	27/12/19 07:51	General View	0	Load JPG	82
11	27/12/19 07:51	General View	0	Load JPG	82
12	27/12/19 07:51	General View	0	Load JPG	2
13	27/12/19 07:51	General View	0	Load JPG	82
14	27/12/19 07:51	General View	0	Load JPG	R
15	27/12/19 07:51	General View	0	Load JPG	2
16	27/12/19 07:51	General View	0	Load JPG	2
17	27/12/19 07:51	General View	0	Load JPG	12
18	27/12/19 07:51	General View	6	Load JPG	V
19	27/12/19 07:51	General View	0	Load JPG	W
20	27/12/19 07:51	General View	0	Load JPG	V
24-11		General View	0	Load JPG	V
21	27/12/19 07:51	(280/2000)	0	Load JPG	82
22	27/12/19 07:51	General View		Load 3PG	2
23	27/12/19 07:51	General View	0		+
24	27/12/19 07:51	General View	0	Load JPG	N
25	27/12/19 07:51	General View	0	Load JPG	2
26	19/02/20 16:35	Reinspection Photo	0		8
27	19/02/20 16:35	Reinspection Photo	0		82
28	19/02/20 16:35	Reinspection Photo	0		8
29	19/02/20 16:35	Reinspection Photo	0	Load JPG	8
30	19/02/20 16:35	Reinspection Photo	0	Load JPG	2
Dos	umentation		1 per	page [v]	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	13/12/19 16:43	EMAIL - FWD TO OI DD 13.12.19	0	Load PDF	
2	13/12/19 16:43	NOTIFICATION FROM WORKSHOP	0	Load PDF	
3.	26/12/19 09:42	TP ESTIMATE - MARKED	0	-	-
4	14/02/20 14:38	WORKSHOP INVOICE	0	Load PDF	

Let	Letters/Correspondences		1 per s	page 🗸	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
		The second secon	0		
6	14/02/20 14:38	LOD	0	Load PDF	
7	05/03/20 10:05	AUTHORISATION TO ACT FORM	0	Load PDF	
В	05/03/20 10:05	Release Voucher	0	Load PDF	_
9	05/03/20 10:05	RENTAL RECEIPT	0	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	12.5	Thumbnail	Print
1	13/12/19 18:02	PRI - CARZ AUTO SERVICES PTE LTD	0	Load PDF	_
2	13/12/19 18:02	SLU9814G OI GIA	0	Load PDF	
3	13/12/19 18:02	GBH8376Y TP GIA	0	Load PDF	
4	29/01/20 14:12	Letter of Demand from Third Party	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

NOTE: TO BE COMP	LETED BY	SURVEYOR
------------------	----------	----------

TEAM			

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU9814	G (Insd vet	1)	Model:			TOYOTA HIACE 3.0 D TURBO 5 DR (M)			D
	GBH8376	Y (TP veh))			Ì				
Date of Accident:	28/11/201	9								
Global Sum Settler	nant I	X] Yes	_	I 1 No		1				
	nent : [V 1 162	: \$		58.03	1				
Repair Estimate			: \$,340.00	-				
Final Repair Cost			: \$	3	,340.00	1	day	/s at \$0	00.00	r day
Loss of Use			: \$			5	day		ou pe	uay
Rental (if any)			: \$			3	uay	5		
LTA / GIA Search F	ee		: \$			1				
Others:			: \$			-				
Final Cattlement Co	- /Clahal	Comi	: \$	2	340.00	1				
Final Settlement Si			11		YES	X 1	1 NO	2 //	Cindly i	ndicate
Is Third Party Wor below)	rksnop Giz	r Kegistere	ur	[]	ILS	1.	1	, 11	caracty i	ridicaro
A) For Non GIA F	Registered	Workshop	:	Agreed	Liabilit	y	_100_	(%	o)	
				BOLA A	pplical	ole: Ye	s/ No	BOLA :	Scenar	rio No:
B) For GIA Regis	tered Worl	kshop:		_						
BOLA Liability		_(%)		Assess	ed Liab	ility (*)			(%)	
* Assessed Lie	bility to be	filled only fo	or cha	in collisions	and fo	r case	s where	BOLA	does r	not apply
Remarks										
Payment Instructi	on: Payee'	s Breakdo	wn							
1) Carz Auto Se	rvices Pte L	td			: \$					3,340.0
2)					: \$					
3)					: \$					
JOANNE	LEE KHAN	G MIN		05 Ma 2020						
LKK Auto C	Consultants	Pte I td		Date						

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19022010/QPA3Q2

05/03/2020 Date:

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No:

PNPV-2018-00016544

Claimant

GBH8376Y Vehicle No:

Insured Vehicle No: SLU9814G

Date of Loss:

28/11/2019

Nature of Claim:

TP

Claim No: 1201900037225

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBH8376Y

Make & Model:

TOYOTA HIACE, 3.0 D TURBO 5 DR (M)

Engine No: Chassis No:

Odometer:

1KD2826393

75224 km

JTFHT02P700245079

Reg. Date: Colour:

15/10/2018 (Man. Year: 2018) Silver

Engine Capacity:

2982 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

195 R15

Rear Tyre Size:

195 R15

Front Tyre Size: Front Left Side:

Bridgestone 5 mm Bridgestone 5 mm

Rear Left Side: Rear Right Side: Bridgestone 5 mm Bridgestone 5 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,596.76	2,083.54	513.22	19.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,240.00	610.00	32.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,446.76	3,323.54	1,123.22	25.26
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	4,446.76	2,650.00	1,796.76	40.41
+ GST 7.00/7.00% (S\$)	311.27	185.50	125.77	40.41
Nett Amount (S\$)	4,758.03	2,835.50	1,922.53	40.41
+ Car Rental (5.0 x S\$1	00.00/day) (S\$)	500.00		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	tt Liability (S\$)	3,342.95		
Global Sum S	Settlement (S\$)	3,340.00		

INSPECTION

Date of Assignment:

13/12/2019

Date Inspected:

17/12/2019 Inspected At:

Carz Auto Services Pte Ltd -

Woodlands (HQ)

NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM

SINGAPORE 757047 Singapore 757047

Estimated Period of Repair:

4.0 days

Adjuster: OI SUN PIN Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2020)		
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for GBH8376Y)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

lo. Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*SLIDING DOOR LH	Dented	1,615.40 FL	*1,615.40 FL
1		*SLIDING DOOR HINGE LH	Serviceable	174.90 FL	*-FL
- 1		*SLIDING DOOR LOCK LH	Serviceable	509.40 FL	*-FL
3.1		*REAR FENDER LH	Dented	1,162.65 FL	*1,162.65 FL
F=Franchise part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)			3,462.35 865.59	2,778.05 694.51	
			Total Parts (S\$)	2,596.76	2,083.54

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND RENEW REAR DAMAGED PARTS REPLACE REALIGNED ALL AFECTED PARTS	New	800.00	600.00
2	TO RESPRAY AFFECTED AREAS	New	700.00	500.00
3	TO TUFFCOAT AFFECTED AREA	New	150.00	40.00
4	TO REMOVE/REFIX INTERIOR UPHOLSTERY	New	100.00	50.00
5	TO REMOVE AND REPLACE SLIDING DOOR MECHANISM	New	100.00	50.00
	Gross Labour	Cost (S\$)	1,850.00	1,240.00
	Report was unsubmitted durin)5 (5)	1,000.00	

< END OF ESTIMATES >