

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan

Date: 23 Dec 2019

Preliminary Advice

Insured Vehicle No : SLU9814G
TP Vehicle No : GBH8376Y
Make : TOYOTA DYNA 150
Date of Inspection : 17/12/2019
Inspection At : Carz Auto Services Pte Ltd - Woodlands (HQ)
NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047
Singapore 757047
Accident Date : 28/11/2019
Assignment Date : 13/12/2019
Est. Duration of Repair : 4 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...N/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,446.76
Revised Amount	:S\$	3,363.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,363.54

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.