

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



Car In

GST REG. NO : M2 - 0020081 - X

13 DEC 2019

**E S T I M A T E**

|                |                |                   |
|----------------|----------------|-------------------|
| Estimate No.   | : b1 53781     | Page No. : 1 of 6 |
| Date Estimated | : 13/12/2019   |                   |
| Prepared By    | : Chua Kee Sin |                   |

|                                                                                                |                                                        |
|------------------------------------------------------------------------------------------------|--------------------------------------------------------|
| - ESTIMATE REPAIR FOR -<br>See Chern Chong Joel<br>67 Sunset Way<br>#05-22<br>Singapore 597092 | - ACCOUNT - 40000<br>Cash Sales - Service<br>Singapore |
|------------------------------------------------------------------------------------------------|--------------------------------------------------------|

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| EL8965R   | WBA6V12040ED05521 | 30/10/2018 | 216i GT | 0       |

| DESCRIPTION                                                                                  | VALUE         |
|----------------------------------------------------------------------------------------------|---------------|
| Replace rear boot lid, rear bumper include remove attachment etc and repair on accident area | 1700 2,550.00 |
| Spray painting rear boot lid, rear bumper and tail pan                                       | 2399 2,666.00 |
| To remove and install boot compartment carpet and garnish to facilitate repairs.             | 230 271.00    |
| To carry out body cavity preservation.<br>(Per panel).                                       | 100 118.00    |
| To check electrical wiring systems and lightings at the rear section for proper function.    | 150 177.00    |
| To replace rear windscreen glass.                                                            | 574.00        |
| To conduct water leak tests.                                                                 | 75.00         |
| To supply and install rear windscreen solar film. (Certificate)                              | 531.00        |
| To Vacuum interior of broken glass debris                                                    | 120 150.00    |
| To supply rear emboss number plate.                                                          | 83.00         |
| Sundries.                                                                                    | ? 150.00      |
| Total Labour 1:                                                                              | 7,345.00      |

| DESCRIPTION             | QTY | PRIC     | VALUE    |
|-------------------------|-----|----------|----------|
| BOOTLID                 | 1   | 1,210.35 | 1,210.35 |
| LH TRUNK LID HINGE      | 1   | 79.75    | 79.75    |
| RH TRUNK LID HINGE      | 1   | 79.75    | 79.75    |
| RR BUMPER LH SIDE GUIDE | 1   | 61.35    | 61.35    |
| RR BUMPER RH SIDE GUIDE | 1   | 61.35    | 61.35    |
| REAR BUMPER CARRIER     | 1   | 460.40   | 460.40   |

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : **b1 53781**  
Date Estimated : **13/12/2019**  
Prepared By : **Chua Kee Sin**

Page No. : 2 of 6

| REGN. NO.      | CHASSIS NO.              | REGN. DATE        | MODEL          | MILEAGE  |
|----------------|--------------------------|-------------------|----------------|----------|
| <b>EL8965R</b> | <b>WBA6V12040ED05521</b> | <b>30/10/2018</b> | <b>216i GT</b> | <b>0</b> |

| DESCRIPTION                                 | QTY | PRIC     | VALUE    |
|---------------------------------------------|-----|----------|----------|
| SUPPORT ?                                   | 1   | 45.55    | 45.55    |
| RR BUMPER LH INNER SIDE GUIDE ?             | 1   | 61.35    | 61.35    |
| RR BUMPER RH INNER SIDE GUIDE ?             | 1   | 61.35    | 61.35    |
| LEFT PROTECT foil / MC                      | 1   | 11.20    | 11.20    |
| RIGHT PROTEC / MC                           | 1   | 11.20    | 11.20    |
| REAR BUMPER TOWING FLAP EYE PRIMED X        | 1   | 43.05    | 43.05    |
| REAR BUMPER PANEL PRIMED (LINES PDC / 00    | 1   | 1,045.45 | 1,045.45 |
| SET MOUNTS PDC SENSOR REAR / MC             | 1   | 60.70    | 60.70    |
| GROMMET / MC                                | 2   | 0.80     | 1.60     |
| PLAQUE 74MM / MC                            | 1   | 71.60    | 71.60    |
| STRIKER BOOT LID X                          | 1   | 59.80    | 59.80    |
| LOCK TRUNK LID X                            | 1   | 194.75   | 194.75   |
| ACTUATION UNIT X                            | 1   | 601.30   | 601.30   |
| LH MOUNTING TAILGATE SUPPORT BOTTOM X       | 1   | 27.25    | 27.25    |
| RH MOUNTING TAILGATE SUPPORT BOTTOM X       | 1   | 27.25    | 27.25    |
| SPINDLE DRIVE X                             | 2   | 355.65   | 711.30   |
| BOOT LID/TAILGATE PUSH BOTTON ICAM X        | 1   | 48.65    | 48.65    |
| BUMP STOP / MC                              | 10  | 3.75     | 37.50    |
| REAR WINDOW / BR                            | 1   | 657.60   | 657.60   |
| REAR BUMPER TRIM STRIP CHROM / BR           | 1   | 78.75    | 78.75    |
| HOOK AND LOOP FASTENER / MC                 | 10  | 2.85     | 28.50    |
| LOADING SILL COVER (ANTHRAZIT) X            | 1   | 79.55    | 79.55    |
| REAR BUMPER HEAT INSULATION X               | 1   | 63.50    | 63.50    |
| BOOTLID SEALING / MC                        | 1   | 143.85   | 143.85   |
| REAR LH REFLECTOR X                         | 1   | 38.85    | 38.85    |
| REAR RH REFLECTOR X                         | 1   | 38.85    | 38.85    |
| GROMMET / MC                                | 1   | 6.85     | 6.85     |
| REAR WINDOW WIPER MOTOR ?                   | 1   | 412.00   | 412.00   |
| REAR WINDOW WIPER ARM / CAT                 | 1   | 72.55    | 72.55    |
| REAR WIPER BLADE / CAT                      | 1   | 45.70    | 45.70    |
| WIPER ARM COVER / BR                        | 1   | 11.55    | 11.55    |
| SPRAY NOZZLE F RR WINDOW CLEANING X         | 1   | 26.95    | 26.95    |
| REAR LH LIGHT IN TRUNK LID X                | 1   | 262.15   | 262.15   |
| REAR RH LIGHT IN TRUNK LID X                | 1   | 262.15   | 262.15   |
| DECOUPING RING PDC TORQUE CONVERTER / MC    | 4   | 5.10     | 20.40    |
| ULTRASONIC SENSOR B53 SPARKLING BRO ?       | 4   | 370.00   | 1,480.00 |
| (DG) CLEANER R1 (100ML) / MC                | 1   | 26.15    | 26.15    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) / MC | 2   | 131.55   | 263.10   |
| (DG/SL) GLASS PRIMER 30ML (VP206) / MC      | 1   | 27.85    | 27.85    |

Total Parts : **9,120.65**

**Performance Motors Limited**

A Sime Darby Motors Company  
CO. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 53781  
Date Estimated : 13/12/2019  
Prepared By : Chua Kee Sin

Page No. : 3 of 6

| REGN. NO. | CHASSIS NO.       | REGN. DATE | MODEL   | MILEAGE |
|-----------|-------------------|------------|---------|---------|
| EL8965R   | WBA6V12040ED05521 | 30/10/2018 | 216i GT | 0       |

**LKK Auto Consultants** hence notify  
the **Repairer** of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Claims OD / 3rd Party / Uninsured losses / Direct Settlement**

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date&Time 16/12/19, 12.00pm Excess S\$ \_\_\_\_\_  
Surveyor's Name Steve CLKK Sign \_\_\_\_\_  
Surveyor's Tel \_\_\_\_\_ Authorised Yes / No \_\_\_\_\_  
Authorised Date \_\_\_\_\_ Time \_\_\_\_\_  
**RESURVEY PARTS PHOTO BY SURVEYOR** Yes / No **PML** Yes / No  
Surveyor's E-mail \_\_\_\_\_  
No. of Working Days Recommend \_\_\_\_\_

*with April*  
*P/P*  
*Ry Bel 91*  
*7 days*

|                    |   |                  |
|--------------------|---|------------------|
| Labour 1           | : | 7,345.00         |
| Parts              | : | 9,120.65         |
| Labour 2           | : | 0.00             |
| Excess             | : | 0.00             |
| Total GST @ 7%     | : | 1,152.60         |
| <b>Grand Total</b> | : | <b>17,618.25</b> |

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*