



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI19022030/Bha3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 29-04-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4027G	Veh. Inspected	SKQ 8320D	
Policy No.	D-19092580MFSH	Coverage (\$)	0.00	
Claim No.	D19007851MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	13/12/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	MR053REH104523483	Colour	BLACK	
Odometer	86136	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2019	Inspection Date	13/12/2019	
Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		