

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000195**

TO : MS FIRST CAPITAL INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

SKQ8320D
CHONG AH JOO
 50 BAYSHORE ROAD
 #30-03
 SINGAPORE 469977
 CONTACT NO : 96398162

DATE : 11-DEC-2019
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS
 1.6L CVT
 CHASSIS NO : MR053REH104523483
 ENGINE NO : 1ZRY136784
 SERVICE ADVISOR : GERINE
 PAGE : 1 OF 2


QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

- | | | | |
|---|----------------------------------|---------------|---------|
| 1 | FRONT DOOR LH | 1,231.70 | DD ✓ |
| 1 | REAR DOOR LH | 1,179.30 | RX |
| 1 | LOCKER PANEL LH | ✓ 494.75 | DD ✓ |
| 1 | FRONT DOOR WEATHER STRIP LH | ✓ 169.79 | TN ✓ |
| 1 | FRONT DOOR LOCK LH | ✓ 421.76 | JAM ✓ |
| 1 | FRONT DOOR CHECKER | 139.10 195.40 | ? BT ✓ |
| 1 | FRONT DOOR REGULATOR | ✓ 188.91 | JAM |
| 1 | FRONT DOOR REGULATOR MOTOR | 499.10 511.65 | JAM |
| 1 | FRONT FENDER LH | 858.64 | RX |
| 1 | FRONT DOOR OUTER CHROME MOULDING | 130.70 158.47 | BT ✓ |
| 1 | FRONT DOOR INNER TRIM | ✓ 799.60 | ? CRA ✓ |
| 1 | SIDE MIRROR LH | 901.69 | ? NDX |
| 1 | FRONT DOOR OUTER HANDLE | ✓ 167.41 | DL |

SPECIAL NETT

- | | | | |
|----|-----------------------------|--|--|
| 10 | FRONT DOOR INNER TRIM CLIPS | | |
| 1 | FRONT DOOR LH SEALANT | | |
| 1 | REAR DOOR LH SEALANT | | |

**Sub Total**

7,279.07 4211.12 0.00
 @ 25% 1052.78
 3158.34
 50.00 30.00 NEC ✓
 50.00 30.00 NEC ✓
 50.00 30.00 NEC ✓
 150.00 90.00 0.00

LABOUR

- | | | |
|---|--|-----------------|
| 1 | TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS | 1,000.00 800.00 |
| 1 | TO SPRAY PAINT ON AFFECTED AREAS | 1,000.00 800.00 |
| 1 | TO DISMANTLE, REPLACE AND/OR REPAIR FRONT LH DOOR COMPONENTS | 180.00 80.00 |
| 1 | TO DISMANTLE, REPLACE AND/OR REPAIR REAR LH DOOR COMPONENTS | 180.00 |

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000195**

TO : MS FIRST CAPITAL INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

SKQ8320D**CHONG AH JOO**

50 BAYSHORE ROAD

#30-03

SINGAPORE 469977

CONTACT NO : 96398162

DATE : 11-DEC-2019
 MAKE : TOYOTA
 MODEL : TOYOTA COROLLA ALTIS
 1.6L CVT
 CHASSIS NO : MR053REH104523483
 ENGINE NO : 1ZRY136784
 SERVICE ADVISOR : GERINE
 PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO APPLY UNDERCOATING FOR RUST PROOFING	200.00 120.00	
1	TO CHECK WIRING	150.00 80.00	
Sub Total		2,710.00	0.00

Survey 13.12.19

15 25 hrs

Tgim lin

97361577

Resurvey 23/12/19 Tgim lin

15 30 hrs

Resurvey days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts 3158.34

SN 90.00

Labour 1880.00

5128.34

@20% 1025.67

4102.67

4/5 4100/- Tgim
 26/12/19

SUB-TOTAL	10,139.07	0.00
GST - 7 %	709.73	0.00
TOTAL	10,848.80	0.00

ABWIN SERVICE PTE LTD

Prepared By

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**SUPPLEMENTARY: HQQ000210**

TO : MS FIRST CAPITAL INSURANCE LIMITED
ATTN : MOTOR CLAIM DEPARTMENT

SKQ8320D
CHONG AH JOO
50 BAYSHORE ROAD
#30-03
SINGAPORE 469977
CONTACT NO : 96398162

DATE : 23-DEC-2019
MAKE : TOYOTA
MODEL : TOYOTA COROLLA ALTIS
1.6L CVT
CHASSIS NO : MR053REH104523483
ENGINE NO : 1ZRY136784
SERVICE ADVISOR : GERINE
PAGE : 1 OF 1

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1 FRONT DOOR BODY WEATHER STRIP LH

~~323.70~~ TN ✓ RPT X

SUB-TOTAL	323.70	0.00
GST - 7 %	22.66	0.00
TOTAL	346.36	0.00

ABWIN SERVICE PTE LTD

Prepared By