

BW WORKSHOP SERVICES PTE LTD

291 KAKI BUKIT AVE 1 SHUN LI

INDUSTRIAL PARK

Singapore 416080

6289 8800

workshop_admin@bw.com.sg

GST Registration No. : 201504834E

Company Registration No. 201504834E

**Estimates**

TP1st Lap

Jasper

ESTIMATES NO. 1156**DATE 12/12/2019****ADDRESS**

MS FIRST CAPITAL

INSURANCE LTD

VIN NUMBER

SMM4782C / RU31322955

MAKE & MODELHONDA VEZEL HYBRID 1.5X
AUTO**MILEAGE**

ACTIVITY	QTY	RATE	AMOUNT
REAR TAILGATE @ \$1,200.00 <i>1100 Dented</i>	1	960.00	✓ 960.00 <i>880</i>
REAR TAILGATE INNER GARNISH @ \$390.00 <i>Ne m</i>	1	312.00	✗ 312.00
LOGO "VEZEL" @ \$65.00 <i>3 m</i>	1	52.00	✓ 52.00
LOGO "HYBRID" @ \$85.00	1	68.00	✓ 68.00
LOGO "HONDA" @ \$25.00 <i>Ne n</i>	1	20.00	✗ 20.00
REAR BUMPER - CENTER @ \$790.00 <i>Dented</i>	1	632.00	✓ 632.00
REAR BUMPER - SIDE - LH & RH @ \$260.00 <i>RH Rpt</i>	2	208.00	✗ 416.00
REAR BUMPER REFLECTOR - LH & RH @ \$160.00 <i>RH Rpt</i>	2	128.00	✗ 256.00
REAR END PANEL @ \$460.00 <i>Dented</i>	1	368.00	✓ 368.00
END PANEL INNER GARNISH @ \$120.00 <i>Ne m</i>	1	96.00	✗ 96.00
COMPARTMENT BOX - CENTER @ \$170.00 <i>Ne m</i>	1	136.00	✗ 136.00
COMPARTMENT BOX COVER - TOP @ \$450.00 <i>Ne m</i>	1	360.00	✗ 360.00
LOCK @ \$190.00 <i>Dented</i>	1	152.00	✓ 152.00
TAILGATE LAMP - LH & RH @ \$450.00 <i>Rt cut</i>	2	360.00	360.00
FENDER LAMP - LH & RH @ \$490.00 <i>Rt cut</i>	2	392.00	392.00

2904

Subtotal: 5,332.00

REAR WINDSCREEN MOULDING - S/N <i>Ne</i>	1	120.00	✓ 120.00
SEALANT - S/N <i>Ne</i>	1	40.00	✓ 40.00
REVERSE SENSOR - S/N <i>Dented</i>	1	180.00	✓ 180.00
REAR BUMPER CLIPS - S/N <i>Ne</i>	10	3.50	✓ 35.00

NETS & Cash only.

375

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

ACTIVITY	QTY	RATE	AMOUNT
----------	-----	------	--------

Subtotal: 375.00

TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	5	200.00	800 1,000.00
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	6	200.00	800 1,200.00
TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATIONS.	1	80.00	30 80.00
TO APPLY UNDERSEALING.	1	80.00	60 80.00
TO REMOVE AND REFIT TAILGATE'S FITTINGS.	1	80.00	80.00
TO REMOVE AND REFIT REVERSER SENSOR.	1	80.00	50 80.00
TO REMOVE AND REFIT REAR WINDSCREEN AND CONDUCT WATER LEAKING TEST.	1	120.00	120.00

1940

Subtotal: 2,640.00

SUBTOTAL	8,347.00
GST TOTAL	0.00
TOTAL	SGD 8,347.00

Accepted By

Accepted Date

Adrian King
P/P 16/12/15

06 Days

96893735.

Supplementary
324

total: 5543

(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7

BW WORKSHOP SERVICES PTE LTD
291 KAKI BUKIT AVE 1 SHUN LI
INDUSTRIAL PARK
Singapore 416080
6289 8800
workshop_admin@bw.com.sg
GST Registration No. : 201504834E
Company Registration No. 201504834E



Estimates

ADDRESS

MS FIRST CAPITAL
INSURANCE LTD

ESTIMATES NO. 1196

DATE 18/12/2019

VIN NUMBER

SMM4782C / RU31322955

MAKE & MODEL

HONDA VEZEL HYBRID 1.5X AUTO

ACTIVITY

SUPPLEMENTARY ITEMS

REAR UNDER COVER @ 190.00 *deland*

WHEEL ARCH @ \$215.00 *cracked*

QTY

RATE

AMOUNT

1

152.00

152.00 ✓

1

172.00

172.00 ✓

Please feel free to contact us again if you have any queries on our quotation.

We look forward to hearing from you soon.

SUBTOTAL

324.00

GST TOTAL

0.00

TOTAL

SGD 324.00

Accepted By

Accepted Date

324

NETS & Cash only.

Our Bank Details:-

Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

Account Number :356-305-177-7