

ASS. REC. BY:

REF: CS/CT1/902208/4A1-312

Special Instruction:

Supervisor: AdrianASSIGNMENT (Office)

From (Person):

Tan Kah Loong

of

CT1

Date/Time:

16.12.19 2.05p.m

Estimated Cost:

Bill to:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV/CS)

To Inspect Vehicle No:

SKU 4570D

Insured:

SKJ 9242B

at Workshop m/s

Kai Motor

Tel:

67474006

of

BIC 3007 Ubi Rd / #01-440

Policy No:

DMP(CS) 3024 9119000

Claim No:

SNM 19D205922

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

my

H.O.D. Endorsement:

Date/Time:

16.12.19 2.05p.m

Person Contacted:

KymVehicle: IN / OUT

Date/Time

Action/Instruction () EstimateSKU 4570D - NA / CT1 1904306 / RS R.O.D. - 11/12/2019SKJ 9142B - Xlump sum \$4000. (Red: 5522.48; 57%)

Adrian

ASSIGNMENT

SKU4570D

2015 July

To inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Date Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bill or Market Value: _____
 IDAC Accident Report: _____ Consistent? Yes or No
 GA / PR Sett: _____ Consistent? Yes or No
 Est. Repair: _____ days Res: Yes or No
 Loss Sum: _____ % 3 Val: Yes or No
 CA / REV / REP: / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Type: M / Cycle / Bus / Van / Lorry / Taxi / Private Motor /
 Truck / Trailer or
 Make: Toyota Altis CC 1598
 Colour: ~~Blue~~ Blue
 Sp. Reading: 73929. T. Mile: Insured / Std / Nil / NA
 Engine: _____
 C/N: MROS3REH104537536.
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / R/R / STD A/R or
 Tyre Size: F: 205/55R16.
 R: 205/55R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 06 mm P/Bal: 06 mm
 L/Bal: 06 mm L/Bal: 06 mm
 D.O.A: _____ 0.01 16/12/19
 Survey held at: K9i Motor
 Des. of Damages: Frt / Rear / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected (due to collision)

Date / Time	Action / Instruction
	TP China

RECEIVED 20 JAN 2020

MV:
PV:
Nett:

Date/Time File Post in: : Prelim Report
 20/1 Typist : Final Report
 Date/Time File Print out:

Days Of Repair: 5
 Resurvey No. of Trip: 1

Audit Fee: Site fee: 15
 Interview: 25
 2nd Report: _____

Survey Fee: _____
 Transport: _____
 Fuel: _____
 Other: _____
 Total: _____
 320

0 TP 4000+

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2019		16 Dec 2019 14:05 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	LIM GEOK MEE, ID: S1185462A		
Vehicle Reg. No.:	SKU4570D	Date of Loss:	11/12/2019 09:00 - :59
Claim Type:	TP / SNM19D205922C02	Policy/Cover Note No.:	DMPCSN30249119000
Vehicle Reg. No. (Insured):	SKJ9242B	Policy No. (Claimant):	2100422330-04
		Excess:	S\$1,050.00
Repairer:	KAI MOTOR TRADING (HQ) BLK 3007 UBI ROAD 1, #01-440, 408701 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) | [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 16 December, 2019 2:00 PM
To: kaimotor@gmail.com; assignments
Subject: RE: OUR REF: SNM19D205922/SKJ9242B/TKL - ACCIDENT INVOLVING VEHICLE Toyota Altis No SKU 4570 D & SKJ 9242 B on 11/12/2019 @09:25:00
Attachments: SAS report Toyota Altis No SKU 4570 D & SKJ 9142 B on 11122019 @092500....pdf; LTA e-Receipt - SKJ9242B.PDF

WITHOUT PREJUDICE

Dear Ms Kym,

We refer to your email below.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, December 16, 2019 1:54 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; kaimotor@gmail.com
Subject: OUR REF: SNM19D205922/SKJ9242B/TKL - ACCIDENT INVOLVING VEHICLE Toyota Altis No SKU 4570 D & SKJ 9242 B on 11/12/2019 @09:25:00

Dear Kah Leong,

Please conduct PRS for SKU4570D.

Note: officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Kai Motor [<mailto:kaimotor@gmail.com>]

Sent: Friday, December 13, 2019 4:40 PM

To: Claims Dept of CTI

Subject: ACCIDENT INVOLVING VEHICLE Toyota Altis No SKU 4570 D & SKJ 9142 B on 11/12/2019 @09:25:00

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1

#01-440, SINGAPORE 408701

TEL: 67474006 FAX: 67437591

E-mail : kaimotor@gmail.com

REG NO: 44223100L

GST REG NO : M90371531Y

Date : 12/12/2019

Attn: The Motor Claims Department

Your Insured veh no : SKJ 9142 B

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00

Spring Leaf Tower

Singapore 079909

Dear Sir / Madam

WITHOUT PREJUDICE

(By Email Only)

ACCIDENT INVOLVING VEHICLE Toyota Altis No SKU 4570 D & SKJ 9142 B on 11/12/2019 @09:25:00

We are writing on behalf of Lim Geok Mee the registered owner of SKU 4570 D which was involved on the above mentioned accident between SKJ 9142 B .

Investigation reveals that the motor vehicle number SKJ 9142 B was insured with you at the material time of the said accident.

As a result of the accident was caused solely and completely by the negligence of your insured vehicle number SKJ 9142 B . Therefore, our client is holding you liable for the repair costs and

other consequential loss which was sustained by him/her/them.

Kindly arrange your representative to survey our client's vehicle at **KAI MOTOR TRADING** Blk 3007, Ubi Road 1, #01-440, Singapore 408701 within two (2) days from the date hereof as to avoid further losses incur.

We enclosed hereby the GIA report of SKU 4570 D for your kind attention.

Failing which, our client have no alternative but to proceed with the necessary repairs and the bill will be forward to you for reimbursement.

Yours faithfully,

--
Have a nice day w thanks.

Ms Kym

Kai Motor Trading

Blk 3007 Ubi Rd 1 #01-440

Singapore 408701

Telephone: 6747 4006

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
 TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
 BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償·拖車·汽車修理及維修服務·打嗎呷·噴漆·
 Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 13/12/2019

Dence.

Irene: 63896192

Attn: The Motor Claims Department

Your Insured veh no : SKU 9142B SKY9242B

China Taiping Insurance (S) Pte Ltd

3 Anson oad

#16-00

Spring Leaf Tower

Singapore 079909

Dear Sir / Madam

WITHOUT PREJUDICE

(By Email Only)

MR053REH104537836

Kah leong: OFF,
<63896193>

LKK

Estimate Cost Repair Bill To Toyota Altis No SKU 4570 D & SKU 9142 B on 11/12/2019 @09:25:00

To Supply :-

1pc	Rear door RH	Dented		\$1,121.10 ✓
1pc	Rear door rubber	new		\$ 183.20 +
1pc	Rear door hinge top	new		\$ 90.50 +
1pc	Rear door hinge lower	new		\$ 90.50 +
1pc	Rear fender RH	Repair		\$ 979.80 +
1pc	Rear windscreen inner selar	new		\$ 63.30 +
1pc	Rear shock absorber RH	new		\$ 212.60 +
1pc	Rear shock absorber mounting	new		\$ 110.10 +
1pc	Rear wheel hup bearing	2nd		\$ 670.10 ✓
1pc	Rear AXLE assy	new Bent	4146.2	\$3,850.00 2355
1pc	Rear AXLE trailing arm	new	3109.65	\$ 312.10 +
1pc	Rear tyre rim	ut	SN: 400	\$ 500.00 400/sw
				\$8,283.30
		less	25%	\$2,070.83
				\$6,212.48

To dismantle & replace damage parts, panel beat where necessary.

\$1,200.00 500.

To putty, apply primer & spray paint on the affected portion.

\$1,250.00 600

labour charge to remove & refix windscreen

1550

\$ 120.00 +

To apply rust-proofing on repair, replace panel.

\$ ~~100.00~~ 60

To remove/renew undercarriage.

\$ ~~380.00~~ 280

To computer wheel alignment.

\$ 180.00 80

To check wiring functions.

\$ 80.00 30

\$9,522.48

Adrian Lij
 L/S 16/12/19.
 050amp

total: 5059.65

L/S: AK.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19022082/ATF3N2
Date: 21/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30249119000
Claimant Vehicle No: SKU4570D Insured Vehicle No: SKJ9242B
Date of Loss: 11/12/2019 Nature of Claim: TP Claim No: SNM19D205922C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU4570D**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZR527263
Reg. Date: 29/07/2015 (Man. Year: 2015) Chassis No: MR053REH104537536
Colour: Blue Odometer: 73929 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	6,212.47	3,509.65	2,702.82	43.51	
Miscellaneous Items	0.00	0.00	0.00		
Labour	3,310.00	1,550.00	1,760.00	53.17	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	9,522.47	5,059.65	4,462.82	46.87	
Approved Total (Overridden) (S\$)		4,000.00			
	(S\$)	9,522.47	4,000.00	5,522.47	57.99
+ GST 7.00/7.00% (S\$)	666.57	280.00	386.57	57.99	
Nett Amount (S\$)	10,189.04	4,280.00	5,909.04	57.99	

INSPECTION

Date of Assignment: 16/12/2019
Date Inspected: 16/12/2019 Inspected At: KAI MOTOR TRADING (HQ)
BLK 3007 UBI ROAD 1, #01-440
Singapore 408701
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2020)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKU4570D)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	1,121.10 FL	*1,121.10 FL
2	1		*REAR DOOR RUBBER	Not Necessary	183.20 FL	*- FL
3	1		*REAR DOOR HINGE TOP	Not Necessary	90.50 FL	*- FL
4	1		*REAR DOOR HINGE LOWER	Not Necessary	90.50 FL	*- FL
5	1		*REAR FENDER RH	Repair	979.80 FL	*- FL
6	1		*REAR WINDSCREEN INNER SELAR	Not Necessary	63.30 FL	*- FL
7	1		*REAR SHOCK ABSORBER RH	Not Necessary	212.60 FL	*- FL
8	1		*REAR SHOCK ABSORBER MOUNTING	Not Necessary	110.10 FL	*- FL
9	1		*REAR WHEEL HUP BEARING	Deformed	670.10 FL	*670.10 FL
10	1		*REAR AXLE ASSY	Bent	3,850.00 FL	*2,355.00 FL
11	1		*REAR AXLE TRAILING ARM	Not Necessary	312.10 FL	*- FL
12	1		*REAR TYRE RIM	Cut	450.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,133.30	4,546.20
- List Item Discount on L Items 25.00/25.00% (S\$)	1,920.83	1,036.55
Total Parts (S\$)	6,212.47	3,509.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGE PARTS,PANEL BEAT WHERE NECESSARY	New	1,200.00	500.00
2	TO PUTTY,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	1,250.00	600.00
3	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN	New	120.00	0.00
4	TO APPLY RUST-PROOFING ON REPAIR,REPLACE PANEL	New	100.00	60.00
5	TO REMOVE/RENEW UNDERCARRIAGE	New	380.00	280.00
6	TO COMPUTER WHEEL ALIGNMENT	New	180.00	80.00
7	TO CHECK WIRING FUNCTIONS	New	80.00	30.00
Gross Labour Cost (S\$)			3,310.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >