



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	Document No.	: SQT19005418	Page	1
Registration No	: SLA6325B	Date	: 13. Dec 2019	Customer No.	: WZI007
Chassis No	: MRHGM6660GP000466	Svc Advisor	: IVAN TEO BOON KIAT	Engine No	: L15Z12720058
Model	: CITY 1.5SV CVT 2016	Date Time	: 13. Dec 2019 1:51:24 PM	Surveyor Name	:
Owner's Name	: WONG YUEN KUAN JANE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 13/12/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: WONG YUAN KUAN JANE OWNER INSURER: LIBERTY INSURANCE ACC DATE: 13/12/2019 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA TP VEH: SHD4335S						
68500-T9A-T30ZZ	LID COMPTRUNK <i>X R</i>	1	500.20	25	375.15	26.26	401.41
75701-T9A-000	EMBLEM H <i>/ MC</i>	1	12.30	25	9.22	0.65	9.87
75722-T9A-T00	EMBLEMRR.CITY <i>/ MC</i>	1	12.70	25	9.52	0.67	10.19
75725-T9A-T00	EMBLEMRR.I-VTEC <i>/ MC</i>	1	13.30	25	9.97	0.70	10.67
91512-SR3-004	CLIP TUBULAR <i>/ MC</i>	2	2.40	25	3.60	0.25	3.85
74851-T2A-003	LOCK ASSYTRUNK <i>X NN</i>	1	101.10	25	75.82	5.31	81.13
74865-T9A-T01	WEATHERSTRIPTRUNK LID <i>X NN</i>	1	80.60	25	60.45	4.23	64.68
66100-T9A-T50ZZ	PANEL COMPRR. <i>/ DD</i>	1	364.50	25	273.37	19.14	292.51
84640-T9A-T01ZA	LINING ASSYRR.PANEL <i>/ CRU</i>	1	66.60	25	49.95	3.50	53.45
71501-T9A-T00ZZ	FACERR.BUMPER <i>/ DD</i>	1	463.70	25	347.77	24.34	372.11
33505-T9A-T01	REFLECTOR ASSYR.RR. <i>X NN</i>	1	16.60	25	12.45	0.87	13.32
33555-T9A-T01	REFLECTOR ASSYL.RR. <i>X NN</i>	1	16.60	25	12.45	0.87	13.32
71593-T9A-J00	SPACER R.RR.BUMPER SIDE <i>/ RR</i>	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE <i>/ RR</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>/ MC</i>	4	2.30	25	6.90	0.48	7.38
33500-T9A-T01	TAILLIGHT ASSYR. <i>X</i>	1	205.70	25	154.27	10.80	165.07
33550-T9A-T01	TAILLIGHT ASSYL. <i>X</i>	1	205.70	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSY,R.LID <i>X</i>	1	81.90	25	61.42	4.30	65.72
34155-T9A-T01	LIGHT ASSYL.LID <i>X</i>	1	81.90	25	61.42	4.30	65.72

Printed on 13/12/2019 2:12:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLA6325B
Chassis No : MRHGM6660GP000466
Model : CITY 1.5SV CVT 2016
Owner's Name : WONG YUEN KUAN JANE
Ins Policy No. :
Date of Accident : 13/12/2019

Document No. : SQT19005418 Page 2
Date : 13. Dec 2019
Customer No. : WZI007
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15Z12720058
Date | Time : 13. Dec 2019 1:51:24 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					2060.24	144.22	2,204.46
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BOJSE	BODY JOINT SEALANT END PANEL	1	150.00		120.00	10.50	160.50
BOBC	BODY UNDERSIDE COATING (N)	1	280.00		250.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	480.00		450.00	33.60	513.60
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	480.00		nn 480.00	33.60	513.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKRP02M	CUT OFF & RENEW RR PANELAND REPLACE DAMAGE PARTS	1	3920.00		1960.00	274.40	4194.40
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2250.00		2250.00	157.50	2407.50
Sum Labor					8580.00	600.60	9,180.60

Survey By

Date & Time

Excess

Status

Signature: **EKK Auto Consultants hence notify**

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Printed on 13/12/2019 by 21:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Total Amount 10,640.24 744.82 11,385.06

Total (Inclusive of GST) 11,385.06

WML MML
P/P
By Ref sy
13 days

Supa - floor M-4 days 2140
Paint - 1 pm 450



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: CU0117880 / INDIA
Chassis No: MRHGM6660GP000466
License No: SLA6325B
Mileage: 48369
Engine No: L15Z12720058

Document No: SVO19082806
Printed By: IVANTEO
Order Date: 23. December 2019
Order Time: 2:58:15 PM
Service Advisor: IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: WONG YUAN KUAN JANE OWNER INSURER: LIBERTY INSURANCE ACC DATE: 13/12/2019 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA TP VEH: SHD4335S						
04655-T9A-T00ZZ	PANEL SETRR.FLOOR / DD	1.	460.00	25.	345.00	24.15	369.15
65513-T9A-T00ZZ	STIFFENERRR.JACK UP / DD	1.	104.80	25.	78.60	5.50	84.10
72841-SH3-315	OILSHEET / MC	1.	41.70	25.	31.27	2.19	33.46
74940-SZW-003	BUZZER ASSYSMART / BR	1.	62.90	25.	47.17	3.30	50.47
BKRP02B	CUT & RENEW RR FLOOR PANEL. /	1	2,240.00		2,240.00	156.80	2,396.80
BP01R	SPRAY PAINTING ON FLOOR PANEL /	1	450.00		450.00	31.50	481.50

GST Amount is calculated from individual line(s)