



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711

Registration No : SLA6325B

Chassis No : MRHGM6660GP000466

Model : CITY 1.5SV CVT 2016

Owner's Name : WONG YUEN KUAN JANE

Ins Policy No. :

Date of Accident : 13/12/2019

Document No. : SQT19005418

Date : 13. Dec 2019

Customer No. : WZI007

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L15Z12720058

Date | Time : 13. Dec 2019 1:51:24 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

| Item            | Description                                                                                                                                                                                          | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: WONG YUAN KUAN JANE<br>OWNER INSURER: LIBERTY INSURANCE<br>ACC DATE: 13/12/2019<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: INDIA<br>TP VEH: SHD4335S |     |            |        |        |               |                  |
| 68500-T9A-T30ZZ | LID COMPTRUNK X R                                                                                                                                                                                    | 1   | 500.20     | 25     | 375.15 | 26.26         | 401.41           |
| 75701-T9A-000   | EMBLEM H / MC                                                                                                                                                                                        | 1   | 12.30      | 25     | 9.22   | 0.65          | 9.87             |
| 75722-T9A-T00   | EMBLEMRR.CITY / MC                                                                                                                                                                                   | 1   | 12.70      | 25     | 9.52   | 0.67          | 10.19            |
| 75725-T9A-T00   | EMBLEMRR.I-VTEC / MC                                                                                                                                                                                 | 1   | 13.30      | 25     | 9.97   | 0.70          | 10.67            |
| 91512-SR3-004   | CLIP TUBULAR / MC                                                                                                                                                                                    | 2   | 2.40       | 25     | 3.60   | 0.25          | 3.85             |
| 74851-T2A-003   | LOCK ASSYTRUNK X                                                                                                                                                                                     | 1   | 101.10     | 25     | 75.82  | 5.31          | 81.13            |
| 74865-T9A-T01   | WEATHERSTRIPTRUNK LID ?                                                                                                                                                                              | 1   | 80.60      | 25     | 60.45  | 4.23          | 64.68            |
| 66100-T9A-T50ZZ | PANEL COMPRR. / DD                                                                                                                                                                                   | 1   | 364.50     | 25     | 273.37 | 19.14         | 292.51           |
| 84640-T9A-T01ZA | LINING ASSYRR.PANEL / CRU                                                                                                                                                                            | 1   | 66.60      | 25     | 49.95  | 3.50          | 53.45            |
| 71501-T9A-T00ZZ | FACERR.BUMPER / DD                                                                                                                                                                                   | 1   | 463.70     | 25     | 347.77 | 24.34         | 372.11           |
| 33505-T9A-T01   | REFLECTOR ASSYR.RR. ?                                                                                                                                                                                | 1   | 16.60      | 25     | 12.45  | 0.87          | 13.32            |
| 33555-T9A-T01   | REFLECTOR ASSYL.RR. ?                                                                                                                                                                                | 1   | 16.60      | 25     | 12.45  | 0.87          | 13.32            |
| 71593-T9A-J00   | SPACER R.RR.BUMPER SIDE / RR                                                                                                                                                                         | 1   | 11.50      | 25     | 8.62   | 0.60          | 9.22             |
| 71598-T9A-J00   | SPACERL.RR.BUMPER SIDE / RR                                                                                                                                                                          | 1   | 11.50      | 25     | 8.62   | 0.60          | 9.22             |
| 91505-TM8-003   | CLIP,BUMPER / MC                                                                                                                                                                                     | 4   | 2.30       | 25     | 6.90   | 0.48          | 7.38             |
| 33500-T9A-T01   | TAILLIGHT ASSYR. ?                                                                                                                                                                                   | 1   | 205.70     | 25     | 154.27 | 10.80         | 165.07           |
| 33550-T9A-T01   | TAILLIGHT ASSYL. X                                                                                                                                                                                   | 1   | 205.70     | 25     | 154.27 | 10.80         | 165.07           |
| 34150-T9A-T01   | LIGHT ASSY,R.LID X                                                                                                                                                                                   | 1   | 81.90      | 25     | 61.42  | 4.30          | 65.72            |
| 34155-T9A-T01   | LIGHT ASSYL.LID X                                                                                                                                                                                    | 1   | 81.90      | 25     | 61.42  | 4.30          | 65.72            |

Printed on 13/12/2019 2:12:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711  
Registration No : SLA6325B  
Chassis No : MRHGM6660GP000466  
Model : CITY 1.5SV CVT 2016  
Owner's Name : WONG YUEN KUAN JANE  
Ins Policy No. :  
Date of Accident : 13/12/2019

Document No. : SQT19005418  
Date : 13. Dec 2019  
Customer No. : WZ1007  
Svc Advisor : IVAN TEO BOON KIAT  
Engine No : L15Z12720058  
Date | Time : 13. Dec 2019 1:51:24 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 2

| Item            | Description                                                           | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|-----------------|-----------------------------------------------------------------------|-----|------------|--------|---------|---------------|------------------|
| NMRS-4P-TM3040L | 4PCS ACT RR.SENSOR ?                                                  | 1   | 320.00     |        | 320.00  | 22.40         | 342.40           |
| BO-NUM-COMP-L   | NUMBER PLATE WITH CASING-L(N) X                                       | 1   | 45.00      |        | 45.00   | 3.15          | 48.15            |
| Sum Item        |                                                                       |     |            |        | 2060.24 | 144.22        | 2,204.46         |
| BOSUN           | SUNDRIES                                                              | 1   | 100.00     | 50     | 100.00  | 7.00          | 107.00           |
| BML02I          | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER                         | 1   | 180.00     |        | 180.00  | 12.60         | 192.60           |
| BMI03D          | REMOVE & INSTALL REAR COMPARTMENT LININGS                             | 1   | 560.00     |        | 560.00  | 39.20         | 599.20           |
| BOJSE           | BODY JOINT SEALANT END PANEL                                          | 1   | 150.00     | 120    | 150.00  | 10.50         | 160.50           |
| BOBC            | BODY UNDERSIDE COATING (N)                                            | 1   | 280.00     | 250    | 280.00  | 19.60         | 299.60           |
| BC012R          | RESET VEHICLE SMART ENTRY SYSTEM                                      | 1   | 480.00     | 450    | 480.00  | 33.60         | 513.60           |
| BC011R          | REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA                           | 1   | 480.00     |        | 480.00  | 33.60         | 513.60           |
| BA02R           | REMOVE & RENEW REVERSE SENSORS-4 PCS (N)                              | 1   | 180.00     |        | 180.00  | 12.60         | 192.60           |
| BKRP02M         | CUT OFF & RENEW RR PANELAND REPLACE DAMAGE PARTS<br>Body - R 560 x 35 | 1   | 3920.00    | 1960   | 3920.00 | 274.40        | 4194.40          |
| BP05R           | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)<br>5 x 450         | 1   | 2250.00    |        | 2250.00 | 157.50        | 2407.50          |
| Sum Labor       |                                                                       |     |            |        | 8580.00 | 600.60        | 9,180.60         |

Survey By

Steve (LKK)

Date & Time

23/12/19, 2-15pm

Excess

Status

Signature

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Amount 10,640.24 744.82 11,385.06

Total (Inclusive of GST) 11,385.06

Printed on 12/2019 by Repairs

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.