

ASS. REC. BY:

REF:

AIG/

h

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

6/26

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1

File pass to

L/S \$7,900.00

CRD: \$3,539.00 (31%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Furnish

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



Veh No: SGL 3351X Yr Regn: 09, 06

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Yaris c.c. 1497

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 109549 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR054HY 910 4018535

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 11/12/19

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 16/12/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8/17

The U/C / Chassis frame / Body Structure affected due to collision.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06111

Vehicle Insured : SGW8088R
Accident Date : 11-Dec-2019

Date : 13-Dec-2019

Our Ref : 219208 (AIG) / CHAN

PAGE : 1

TAN THUAN LIANG
BLK 95 BEDOK NORTH AVENUE 4
#08-1409
Singapore 460095

*Not Authorized
Lump Sum @ 7900
Recovery After Paint*

ESTIMATED COST OF REPAIR FOR TOYOTA YARIS E 1.5 SGL3351X

1 pc	Tail gate			R	769.00	✓	
1 pc	Tail glass inner seal			M	49.50	✓	
1 pc	Tail gate wiper motor			M	536.60	✓	
1 pc	Tail gate inner trim			M	373.60	✓	
1 pc	Tail gate "YARIS" emblem			M	38.70	✓	
1 pc	Tail gate logo			M	48.40	✓	
1 pc	Tail gate "E" plate			M	34.50	✓	
1 pc	Tail gate inner lock			M	315.10	✓	
1 pc	Tail gate rubber			M	291.10	✓	
1 pc	Tail gate actuator lock			M	203.90	✓	
2 pcs	Tail lamp	M	@ S\$323.40		646.80	✓	
2 pcs	Taillamp corner panel		@ S\$159.60	R	319.20	✓	X
2 pcs	Taillamp side clip		@ S\$ 6.80	M	13.60	✓	X
1 pc	Rear end panel			R	514.20	✓	
1 pc	End panel top garnish			M	185.90	✓	
1 pc	Rear bumper fascia			R	460.90	✓	
1 pc	Rear bumper license plate lamp			M	68.80	✓	
2 pcs	Rear bumper side retainer		@ S\$ 57.90	M	115.80	✓	
2 pcs	Rear bumper bracket		@ S\$164.20	R	328.40	✓	
1 pc	Rear exhaust silencer box			R	540.10	✓	X
1 pc	Front bumper fascia			M	465.40	✓	
1 pc	Front bumper reinforcement			R	372.10	✓	
1 pc	Front bumper logo			M	60.30	✓	
1 pc	Front bumper grille			M	174.80	✓	
1 pc	Front bumper sponge			M	93.70	✓	
2 pcs	Front bumper side retainer		@ S\$ 57.90	M	115.80	✓	
1 pc	Air con condenser			M	1,069.30	✓	
2 pcs	Headlamp	M	@ S\$471.20		942.40	✓	
					9,147.90		
Less 25% :					2,286.98		
					6,860.92		

*8217.10
2054.28
6162.82
6,860.92*

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGW8088R

Page : 2

1 pc Rear bumper lower spoiler
1 pc Tail gate glass sealant
1 pc Rear no.plate with box
1 pc Rear bumper reverse sensor(set
1 pc Front no.plate with box

Bu 260.00 sn ✓
na 60.00 sn 401.
nd 50.00 sn 451.
cm 300.00 sn 200.
nd 50.00 sn 451.

To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 1201

To remove roof lining, front and
rear seats, trim board and carpet

120.00 601

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

120.00 80 ✓
7 ✓

To apply undersealing

100.00 601

To remove and ^{Repair} renew exhaust
silencer box

60.00 ✓

To putty and spray replaced parts

1,400.00 12001

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,200.00 9001

Total : S\$10,750.92

Singapore Dollars Ten Thousand Seven Hundred
and Fifty and Cents Ninety Two Only

L/sum 2900.00 P 6162.82

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

S N L

708.75
590.00
2500.00
9961.57
1992.31
7969.26

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGW8088E (AIG)

Date : 19-12-2019

Accident Date : 11-12-2019

Our Ref : 219208 /CHAN

TAN THUAN LIANG

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR TOYOTA YARIS E 1.5 SGL3351X

2 PCS REAR FENDER INNER TRIM @ \$472.50

<i>CM</i>	\$945.00	✓
LESS 25%	<u>\$236.25</u>	
	<u>\$708.75</u>	

Singapore Dollars Seven Hundred Eight And Cents Seventy Five Only

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06111

Vehicle Insured : SGW8088R
Accident Date : 11-Dec-2019

Date : 13-Dec-2019

Our Ref : 219208 (AIG) / CHAN

PAGE : 1

TAN THUAN LIANG
BLK 95 BEDOK NORTH AVENUE 4
#08-1409
Singapore 460095

*Not Authorized
L/Samp &?
Recovery After Paint
8 days*

ESTIMATED COST OF REPAIR FOR TOYOTA YARIS E 1.5 SGL3351X

1 pc	Tail gate		769.00	✓
1 pc	Tail glass inner seal		49.50	✓
1 pc	Tail gate wiper motor		536.60	?
1 pc	Tail gate inner trim		373.60	?
1 pc	Tail gate "YARIS" emblem		38.70	✓
1 pc	Tail gate logo		48.40	✓
1 pc	Tail gate "E" plate		34.50	✓
1 pc	Tail gate inner lock		315.10	✓
1 pc	Tail gate rubber		291.10	?
1 pc	Tail gate actuator lock		203.90	?
2 pcs	Tail lamp	<i>mf m</i> @ S\$323.40	646.80	✓
2 pcs	Taillamp corner panel	@ S\$159.60	319.20	?
2 pcs	Taillamp side clip	@ S\$ 6.80	13.60	?
1 pc	Rear end panel		514.20	✓
1 pc	End panel top garnish		185.90	?
1 pc	Rear bumper fascia		460.90	✓
1 pc	Rear bumper license plate lamp		68.80	?
2 pcs	Rear bumper side retainer	@ S\$ 57.90	115.80	✓
2 pcs	Rear bumper bracket	@ S\$164.20	328.40	?
1 pc	Rear exhaust silencer box		540.10	?
1 pc	Front bumper fascia		465.40	✓
1 pc	Front bumper reinforcement		372.10	?
1 pc	Front bumper logo		60.30	✓
1 pc	Front bumper grille		174.80	✓
1 pc	Front bumper sponge		93.70	?
2 pcs	Front bumper side retainer	@ S\$ 57.90	115.80	✓
1 pc	Air con condenser		1,069.30	?
2 pcs	Headlamp	@ S\$471.20	942.40	?
			9,147.90	
Less 25% :			2,286.98	

6,860.92

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGW8088R

Page : 2

1 pc Rear bumper lower spoiler
1 pc Tail gate glass sealant
1 pc Rear no.plate with box
1 pc Rear bumper reverse sensor(set
1 pc Front no.plate with box

Bu	260.00	sn	✓
ru	60.00	sn	401n
nd	50.00	sn	451n
cm	300.00	sn	2001n
nd	50.00	sn	451n

To rewire damaged parts and refocus
headlamp beam.

20.00 ✓

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 120d

To remove roof lining, front and
rear seats, trim board and carpet

120.00 60d

To remove air con condenser, pipes
and drier, vacuum and to recharge
gas

120.00 ?

To apply undersealing

100.00 60d

To remove and renew exhaust
silencer box

60.00 ✓

To putty and spray replaced parts

1,400.00 120d

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,200.00 90d

Total : S\$10,750.92

Singapore Dollars Ten Thousand Seven Hundred
and Fifty and Cents Ninety Two Only

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Summer Lee (LKK Auto)

From: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Sent: Monday, 16 December, 2019 9:23 AM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt ATTACHED SGL3351X REPAIR ESTIMATE ,GIA REPORT FOR ARRAGE T.P. SURVEY CLAIMING SGW8088R ON 11-12-2019
Attachments: SGL3351X.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

(in)
Kenny 16/12/19 @ 10:36a
✓
Esr
-b5

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: kennychan@alanutd.com <kennychan@alanutd.com>
Sent: Monday, December 16, 2019 9:13 AM
To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Subject: [EXTERNAL] ATTACHED SGL3351X REPAIR ESTIMATE ,GIA REPORT FOR ARRAGE T.P. SURVEY CLAIMING SGW8088R ON 11-12-2019

This message is from an external sender; be cautious with links and attachments.

Dear Motor Claims Dept.

Morning ,please arrange surveyor to survey our client vehicle SGL3351X for t. p. claim your insured vehicle SGW8088R accident on 11-12-2019 thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686

Print Received Message

This mail is associated with :

***SGL3351X (6035111451SG)**
[SGW8088R]

TP
TAN THUAN LIANG
Dec 11 2019 5:00PM
[LEE SENG CHYE]
Alan's United Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 10/03/2020 14:35 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9754.00) - SGL3351X - Claim Handler: MdNoor, Norsiah

Approved:9754.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Dec 2019 Edit Reg		16 Dec 2019 00:00 Edit Adj Rpt	S\$7,900.00 Edit Estimates	S\$7,900.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	LEE SENG CHYE, ID: S17457808				
Main Claimant:	TAN THUAN LIANG, ID: S1487298A				
Vehicle Reg. No.:	SGL3351X	Date of Loss:	11/12/2019 17:00 - :59 [158 Months and 29 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 6035111451SG	Policy/Cover Note No.:	(Comprehensive)		
Vehicle Reg. No. (Insured):	SGW8088R	Policy No. (Claimant):	10768198		
		Excess:			
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com				
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/12/2019]				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (10/03/2020): Alert - Adj Mandate Approved (S\$9754.00) - SGL3351X - Claim Handler: MdNoor, Nor...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results:									

Claim Documents

*SGL3351X (6035111451SG)
[SGW8088R]
TP
TAN THUAN LIANG
Dec 11 2019 5:00PM
[LEE SENG CHYE]
Alan's United Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown														Edit				
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	29/01/20 15:12	Odometer Reading														Load JPG	☒			
2	29/01/20 15:12	Chassis Number														Load JPG	☒			
3	29/01/20 15:12	General View														Load JPG	☒			
4	29/01/20 15:12	General View														Load JPG	☒			
5	29/01/20 15:12	General View														Load JPG	☒			
6	29/01/20 15:12	General View														Load JPG	☒			
7	29/01/20 15:12	General View														Load JPG	☒			
8	29/01/20 15:12	General View														Load JPG	☒			
9	29/01/20 15:12	General View														Load JPG	☒			
10	29/01/20 15:12	General View														Load JPG	☒			
11	29/01/20 15:12	General View														Load JPG	☒			
12	29/01/20 15:12	General View														Load JPG	☒			
13	29/01/20 15:12	General View														Load JPG	☒			
14	29/01/20 15:12	General View														Load JPG	☒			
15	29/01/20 15:12	General View														Load JPG	☒			
16	29/01/20 15:12	General View														Load JPG	☒			
17	29/01/20 15:12	General View														Load JPG	☒			
18	29/01/20 15:12	General View														Load JPG	☒			
19	29/01/20 15:12	General View														Load JPG	☒			
20	29/01/20 15:12	General View														Load JPG	☒			
21	29/01/20 15:12	General View														Load JPG	☒			
22	29/01/20 15:12	General View														Load JPG	☒			
23	29/01/20 15:12	General View														Load JPG	☒			
24	29/01/20 15:12	General View														Load JPG	☒			
25	29/01/20 15:12	General View														Load JPG	☒			
26	29/01/20 15:12	General View														Load JPG	☒			
27	29/01/20 15:12	General View														Load JPG	☒			
28	29/01/20 15:12	General View														Load JPG	☒			
29	29/01/20 15:12	General View														Load JPG	☒			
30	29/01/20 15:12	General View														Load JPG	☒			
31	29/01/20 15:12	General View														Load JPG	☒			
32	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
33	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
34	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
35	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
36	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
37	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
38	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
39	29/01/20 15:13	Reinspection Photo														Load JPG	☒			
40	29/01/20 15:13	Reinspection Photo														Load JPG	☒			

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	29/01/20 15:13	Reinspection Photo		Load JPG	☒
42	29/01/20 15:13	Reinspection Photo		Load JPG	☒
43	29/01/20 15:13	Reinspection Photo		Load JPG	☒
44	29/01/20 15:13	Reinspection Photo		Load JPG	☒
45	29/01/20 15:13	Reinspection Photo		Load JPG	☒
46	29/01/20 15:13	Reinspection Photo		Load JPG	☒
47	29/01/20 15:13	Reinspection Photo		Load JPG	☒
48	29/01/20 15:13	After Repair Photo		Load JPG	☒
49	29/01/20 15:13	After Repair Photo		Load JPG	☒
50	29/01/20 15:13	After Repair Photo		Load JPG	☒
51	29/01/20 15:13	After Repair Photo		Load JPG	☒
52	29/01/20 15:13	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/12/19 14:29	EMAIL FROM AIG DD 16122019		Load PDF	
2	16/12/19 14:29	TP EST & GIA REPORT		Load PDF	
3	17/12/19 17:20	TP ESTIMATE- MARKED		Load PDF	
4	29/01/20 15:10	TP ESTIMATE - FINALIZED		Load PDF	
5	29/01/20 15:36	EMAIL TO OI		Load PDF	
6	29/01/20 15:36	LETTER TO OI		Load PDF	
7	04/02/20 15:11	RENTAL RECEIPT		Load PDF	
8	04/02/20 15:11	MEDICAL FEE		Load PDF	
9	04/02/20 15:11	LOD		Load PDF	
10	04/02/20 15:11	GIA SEARCH		Load PDF	
11	14/03/20 10:19	ATA FOR MEDICAL BILLS ONLY		Load PDF	
12	14/03/20 10:19	EMAIL FROM TP		Load PDF	
13	17/03/20 09:14	WORKSHOP INVOICE		Load PDF	
14	17/03/20 09:14	AUTHORISATION TO ACT FORM		Load PDF	
15	17/03/20 09:14	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	17/12/19 09:31	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SGW8088R (Insd veh)	Model:	TOYOTA YARIS 1.5 E (A)
	SGL3351X (TP veh)		
Date of Accident:	11/12/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	12,261.86
Final Repair Cost	:	\$	9,750.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	12 days
LTA / GIA Search Fee	:	\$	
Others: Medical Fee	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	9,750.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability <u>100</u> (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): <u>0</u> (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Alan's United Auto Pte Ltd	:	\$ 9,750.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022085/KHS3Q2

Date: 17/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SGL3351X

Insured Vehicle No : SGW8088R

Date of Loss: 11/12/2019

Nature of Claim: TP

Claim No: 6035111451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGL3351X

Make & Model: TOYOTA YARIS, 1.5 E (A)

Engine No: 1NZX476411

Reg. Date: 12/09/2006 (Man. Year: 2006)

Chassis No: MR054HY9104018535

Colour: Metallic Grey

Odometer: 109599 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size:

185/60R15

Front Left Side: Michelin 9 mm

Rear Left Side:

Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side:

Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,289.68	7,388.80	900.88	10.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	2,500.00	670.00	21.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,459.68	9,888.80	1,570.88	13.71
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	11,459.68	7,900.00	3,559.68	31.06
+ GST 7.00/7.00% (S\$)	802.18	553.00	249.18	31.06
Nett Amount (S\$)	12,261.86	8,453.00	3,808.86	31.06
+ Medical Costs (S\$)		99.00		
+ Car Rental (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,754.00		
Global Sum Settlement (S\$)		9,750.00		

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 16/12/2019 Inspected At:

Alan's United Auto Pte Ltd (HQ)

Blk 7 Sin Ming Industrial Estate, #01-

76

Singapore 575642

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	769.00 FL	*769.00 FL
2	1		*TAIL GATE INNER SEAL	Necessary	49.50 FL	*49.50 FL
3	1		*TAIL GATE WIPER MOTOR	Jammed	536.60 FL	*536.60 FL
4	1		*TAIL GATE INNER TRIM	Mtg Cracked	373.60 FL	*373.60 FL
5	1		*TAIL GATE YARIS EMBLEM	Necessary	38.70 FL	*38.70 FL
6	1		*TAIL GATE LOGO	Necessary	48.40 FL	*48.40 FL
7	1		*TAIL GATE E PLATE	Necessary	34.50 FL	*34.50 FL
8	1		*TAIL GATE INNER LOCK	Jammed	315.10 FL	*315.10 FL
9	1		*TAIL GATE RUBBER (50%)	Distorted / Dented	218.33 FS	*145.55 FS
10	1		*TAIL GATE ACTUATOR LOCK	Dented	203.90 FL	*203.90 FL
11	2		*TAIL LAMP	Mtg Cracked	646.80 FL	*646.80 FL
12	2		*TAILLAMP CORNER PANEL	Repair	319.20 FL	*- FL
13	2		*TAILLAMP SIDE CLIP	Not Necessary	13.60 FL	*- FL
14	1		*REAR END PANEL	Bent	514.20 FL	*514.20 FL
15	1		*END PANEL TOP GARNISH	Dented	185.90 FL	*185.90 FL
16	1		*REAR BUMPER FASCIA	Bent	460.90 FL	*460.90 FL
17	1		*REAR BUMPER LICENSE PLATE LAMP	Cracked	68.80 FL	*68.80 FL
18	2		*REAR BUMPER SIDE RETAINER	Distorted	115.80 FL	*115.80 FL
19	2		*REAR BUMPER BRACKET	Bent	328.40 FL	*328.40 FL
20	1		*REAR EXHAUST SILENCER BOX	Repair	540.10 FL	*- FL
21	1		*FRONT BUMPER FASCIA	Cracked	465.40 FL	*465.40 FL
22	1		*FRONT BUMPER REINFORCEMENT	Bent	372.10 FL	*372.10 FL
23	1		*FRONT BUMPER LOGO	Missing	60.30 FL	*60.30 FL
24	1		*FRONT BUMPER GRILLE	Dented	174.80 FL	*174.80 FL
25	1		*FRONT BUMPER SPONGE	Cracked	93.70 FL	*93.70 FL
26	1		*FRONT BUMPER SIDE RETAINER	N/S Distorted	115.80 FL	*57.90 FL
27	1		*AIR CON CONDENSER	Bent / Punctured	1,069.30 FL	*1,069.30 FL
28	2		*HEADLAMP	Mtg Cracked	942.40 FL	*942.40 FL
29	1		*REAR BUMPER LOWER SPOILER	Buckled	260.00 FS	*260.00 FS
30	1		*TAIL GATE GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
31	1		*REAR NO.PLATE WITH BOX	Dented	50.00 FS	*45.00 FS
32	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	300.00 FS	*200.00 FS
33	1		*FRONT NO.PLATE WITH BOX	Dented	50.00 FS	*45.00 FS
34	2		*REAR FENDER INNER TRIM	Cracked	945.00 FL	*945.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,740.13	9,606.55
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,450.45	2,217.75
Total Parts (\$\$)	8,289.68	7,388.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	20.00	20.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
3	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
4	TO REMOVE AIR CON CONDENSER ,PIPES AND DRIER ,VACUUM AND TO RECHARGE GAS	New	120.00	80.00
5	TO APPLY UNDERSEALING	New	100.00	60.00
6	TO REMOVE AND REPON EXHAUST SILENCER BOX	New	60.00	60.00
7	TO PUTTY AND SPRAY REPLACED PARTS	New	1,400.00	1,200.00
8	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	1,200.00	900.00
Gross Labour Cost (S\$)			3,170.00	2,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >