

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06111

Vehicle Insured : SGW8088R
Accident Date : 11-Dec-2019

Date : 13-Dec-2019

Our Ref : 219208 (AIG) / CHAN

TAN THUAN LIANG
BLK 95 BEDOK NORTH AVENUE 4
#08-1409
Singapore 460095

PAGE : 1

Not Authorized
61 Simp 879006
Repair After Paint

ESTIMATED COST OF REPAIR FOR TOYOTA YARIS E 1.5 SGL3351X

1 pc Tail gate		Ry 769.00	✓
1 pc Tail glass inner seal		nu 49.50	✓
1 pc Tail gate wiper motor		nu 536.60	✓
1 pc Tail gate inner trim		ngcm 373.60	✓
1 pc Tail gate "YARIS" emblem		nu 38.70	✓
1 pc Tail gate logo		nu 48.40	✓
1 pc Tail gate "E" plate		nu 34.50	✓
1 pc Tail gate inner lock		nu 315.10	✓
1 pc Tail gate rubber		nu 291.10	✓
1 pc Tail gate actuator lock		nu 203.90	✓
2 pcs Tail lamp	ngcm @ S\$323.40	646.80	✓
2 pcs Taillamp corner panel	@ S\$159.60	R 319.20	✓
2 pcs Taillamp side clip	@ S\$ 6.80	nu 13.60	✓
1 pc Rear end panel		R 514.20	✓
1 pc End panel top garnish		nu 185.90	✓
1 pc Rear bumper fascia		R 460.90	✓
1 pc Rear bumper license plate lamp		cm 68.80	✓
2 pcs Rear bumper side retainer	@ S\$ 57.90	nu 115.80	✓
2 pcs Rear bumper bracket	@ S\$164.20	R 328.40	✓
1 pc Rear exhaust silencer box		R 540.10	✓
1 pc Front bumper fascia		cm 465.40	✓
1 pc Front bumper reinforcement		R 372.10	✓
1 pc Front bumper logo		nu 60.30	✓
1 pc Front bumper grille		nu 174.80	✓
1 pc Front bumper sponge		cm 93.70	✓
2 pcs Front bumper side retainer	@ S\$ 57.90	nu 115.80	✓
1 pc Air con condenser		R 1,069.30	✓
2 pcs Headlamp	ngcm @ S\$471.20	942.40	✓
		9,147.90	
Less 25% :		2,286.98	
		6,860.92	

8 days

145.555N

8217.10
2054.28
6162.82
6,860.92

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : SGW8088R

- 1 pc Rear bumper lower spoiler
- 1 pc Tail gate glass sealant
- 1 pc Rear no.plate with box
- 1 pc Rear bumper reverse sensor(set
- 1 pc Front no.plate with box

Buy 260.00 sn ✓
rm 60.00 sn *4051*
nd 50.00 sn *4551*
cm 300.00 sn *2001*
nd 50.00 sn *4551*

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To remove & refix rear windscreen glass and conduct water leak test.

150.00 *1201*

To remove roof lining, front and rear seats, trim board and carpet

120.00 *601*

To remove air con condenser, pipes and drier, vacuum and to recharge gas

120.00 *80* ✓
7 ✓

100.00 *601*

To apply undersealing

To remove and ^{Repair} renew exhaust silencer box

60.00 ✓

1,400.00 *12001*

To putty and spray replaced parts

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

1,200.00 *9001*

Total : S\$10,750.92

Singapore Dollars Ten Thousand Seven Hundred and Fifty and Cents Ninety Two Only

L/sum 7900.00

P 6162.82

708.75

590.00

2500.00

9961.57

1992.31

7969.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SGW8088E (AIG)

Accident Date : 11-12-2019

Date : 19-12-2019

Our Ref : 219208 /CHAN

TAN THUAN LIANG

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR TOYOTA YARIS E 1.5 SGL3351X

2 PCS REAR FENDER INNER TRIM @ \$472.50

<i>CM</i>	\$945.00	✓
LESS 25%	<u>\$236.25</u>	
	<u>\$708.75</u>	

Singapore Dollars Seven Hundred Eight And Cents Seventy Five Only