

**CITY CAB PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHA 807P

DATE 12/12/2019 15:12

MAKE :

MODEL : HYUNDAI IONIQ

CHINA-JU  
CP/P

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X M			\$ 459.40
	Rear Bumper Centre Moulding Assy cut			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy X M			\$ 155.00
	Rear Bumper Stay X M			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) X M		\$ 33.10	\$ 66.20
	Rear Bumper Cover Clips X M			\$ 22.00
	<b>SUB TOTAL</b>			<b>\$ 1,291.95</b>
	<b>LESS 20%</b>			<b>\$ 258.39</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,033.56</b>
	Rear No.Plates SEE			\$ 25.00
	Rear No.Plates Trim Cover cut			\$ 30.00
	Rear Bumper Reverse Sensor X M			\$ 135.70
	Rear Bumper Rubber Mat X M			\$ 50.00
				<b>\$ 240.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	<b>TOTAL LABOUR</b>			<b>\$ 730.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,004.26</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Nett  
Nett  
Nett  
Nett

\$320  
X M  
X M  
X M

RAM (LKK)  
12/12/19 1600hrs  
Paralunam@lkkauto.com  
88622178  
P/P  
@repairdegs  
aft repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.