

ASSIGNMENT

Surveyor:

ADRIAN

DOI: 16/12/2019

Date / Time: 13/12/2019

Registered in Merimen: 16/12/2019

Pre-assign / CCU / FTE

Insured Vehicle No. : SGV 1616TClaim No. : 7585211939SGName of Insured : SIOW OI LIN

Policy No. : _____

Insured Tel No. : _____ HP: +65-98389982

Make / Model : _____

Excess Sec II :S\$

D.O.A: 13/12/2019

Place of Accident : _____

Is driver the owner? (YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____

(V/L: YES / NO)

Insured Liability : _____

Final ? Yes / No

SKZ 3588J



INSRS:

WSP: IMPERIUM
Tel: AUTOMOTIVE

Liability : _____

RMKS: _____



INSRS:

WSP: _____
Tel: _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____
Tel: _____

Liability : _____

RMKS: _____



INSRS:

WSP: _____
Tel: _____

Liability : _____

RMKS: _____

Date/Time		STAGE	DATE / PIC
	SGV 1616T - CC3/AIG18007655/Aqbn2; DOA: 18.04.18	Non-Reporting ltr (1st):	
	SKZ 3588J - X	Non-Reporting ltr (2nd):	
19/12/19 -	OINR. To send out first letter. File pass to Su Li.	Non-Reporting ltr (Final):	
9/1/2020 -	✓ OI GIA Rec'd	Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☐
		Release Voucher:	☐
		Final Repair Bill:	☐
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA :	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☐
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____		Confirm by: _____
FINALIZATION	Date/Time: _____ Confirm with: _____	Confirm by: _____
Repair Cost: S\$ _____	(_____ days) Reduction: _____ %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: _____ Confirm with: _____	Email ☐ Call ☐
Final Liability: % <u>100</u>	(Agreed / Assessed) BOLA S/N No. : <u>27</u>	If NO or B 28, Ass. Lia : _____
Repair Cost: S\$ _____		
Loss of Rental (LOR): S\$ _____		

no 93/Ad

ASSIGNMENT

Form No. _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / MV / MV

Transport Vehicle No. _____

at Workshop No. _____

of _____

Insured _____

Policy No. _____

Class No. _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh. _____

(Policy Condition)

Remark: The V- had commenced its repair at the time of inspection.

N/S	O/S

Est. Repairs: 6 days Fee: Yes or No

Lim Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Vehicle No. SK2388J. Date 2016 Jan.

Type ☒ M/Cycle / Bus / Van / Lorry / Taxi / Private Motor /

Truck / Trailer or _____

Make Toyota Wish. Ax 1798

Colour Silver. AX Insured / Std / Nil / NA

Sp Reading 76229. T/Rails: Insured / Std / Nil / NA

Eng No. JTJG420W 40J003505

C/Nr _____

Gen. Cond. ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size F: 195/65R15

R: 195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal 06 mm L/Bal 06 mm

Rear R/Bal 06 mm L/Bal 06 mm

D.O.A. 16/12/19.

Survey held at Imperium Automobile.

Des. of Damages Frt / ☒ R/R / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	TP AIG.
	4, - \$5000 (Red \$9135.55 / 51)
	MV:
	PV:
	Nett:

Draw/Time File For: ☐ : Prel. Report

By: ☐ : Final Report

Draw/Time File For: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Other: _____

Draw/Time File For: _____

Draw/Time File For: _____

Draw/Time File For: _____

Draw/Time File For: _____

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800
Tel: 9748 9940 Fax: 6346 7213

Vehicle No: SKZ 3588J

Model: Toyota Wish

TPA16

Jia Le

T706620W40J003505

QTY

List Price:

Prices \$

1	Rear tailgate <i>Dented</i>	
2	Rear tailgate hinge- RH/LH @ 65.20	<i>3 new</i>
2	Rear tailgate damper- RH/LH @ 210.91	<i>new</i>
2	Rear tailgate lamp - RH/LH @ 484.65	<i>new</i>
1	Rear tailgate stopper <i>new</i>	
1	Rear tailgate rubber <i>new</i>	
1	Rear tailgate lock <i>Dented</i>	
1	Rear tailgate lock catch <i>new</i>	
1	Rear tailgate inner pull handle <i>new</i>	
1	Rear tailgate inner trim <i>cracked</i>	
1	Rear tailgate wiper blade	
1	Rear tailgate wiper arm	<i>new</i>
1	Rear tailgate wiper motor	
1	Rear tailgate emblem LOGO	
1	Rear tailgate emblem "Elegance"	<i>new</i>
1	Rear tailgate emblem "Valve MATIC"	
2	Rear number plate lamp @ 48.65	<i>new</i>
1	Rear tailgate opening control switch <i>new cracked</i>	
1	Rear tailgate outer chrome moulding <i>new</i>	
2	Rear taillamp- RH/LH @ 572.60	<i>new</i>
4	Rear taillamp side holder clip @ 7.80	<i>new</i>
2	Rear taillamp panel housing- RH/LH @ 195.00	<i>new</i>
1	Rear bumper <i>Dented</i>	
4	Rear bumper clip @ 4.50	<i>new</i>
2	Rear bumper reflector- RH/LH @ 68.55	<i>new</i>
2	Rear bumper bracket- RH/LH @ 68.50	<i>Dented</i>
2	Rear bumper side retainer- RH/LH @ 64.43	<i>new</i>
1	Rear end panel <i>Dented</i>	
1	Rear end panel garnish <i>Dented</i>	
1	Rear spare wheel carrier <i>Dented</i>	
1	Rear floor panel <i>new</i>	
1	Rear floor cardboard holder garnish <i>new</i>	
1	Rear floor panel cardboard <i>Dented</i>	
2	Rear floor panel side board- RH/LH @ 155.10	<i>new</i>
2	Rear fender air vent- RH/LH @ 148.50	<i>new</i>
2	Rear fender inner trim- RH/LH @ 607.62	<i>new</i>

1557.45

130.40

421.82

969.30

12.90

285.53

497.27

46.50

42.50

485.51

48.10

70.50

615.10

68.50

58.70

47.20

97.30

165.20

255.10

1145.20

31.20

390.00

735.98

18.00

137.10

137.10

128.86

575.10

248.97

335.10

618.70

216.50

265.70

310.10

297.00

1215.24

12680.73

Special Nett Items:

1 set	Rear windscreen sealant	240	80.00	60
1 set	Rear Reverse Camera	240	400.00	4
1 set	Rear number plate with casing	240	50.00	4
1 set	Rear inner trim clip	240	65.00	30
1 set	Rear bumper reverse sensor	240	280.00	20
Subtotal			875.00	

Labour Charges:

Panel beating, cut, weld, remove and replacing above parts	1500.00	900
To respray painting and etc	1500.00	900
To checking rear wiring	50.00	30
To remove, refix rear windscreen	200.00	120
To transfer rear tailgate parts	120.00	80
To remove, refix cushion and inner trim	180.00	60
To refix & replace reverse sensor	200.00	50
Subtotal	3750.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL**\$ 14135.55**

Adrian L
 2/5 16/12/19
 0624/5

total 6253.23.

2/5 5K

5K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19022093/Ada3

10 JANUARY 2020

SIOW OI LIN
73 CHISELHURST GROVE
SINGAPORE 558656

Dear Sir/Madam,

ACCIDENT INVOLVING SGV 1616T & SKZ 3588J ALONG/AT CLEMENTI RD/COMMONWEALTH WEST AVE ON 13/12/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SKZ 3588J against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head to rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: JiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

m93/Ad.

PRE-REPAIR INSPECTION REQUEST – SKZ3588J vs SGV1616T (OI) on D.O.A.: 12/12/2019

From: Hor, Yinrul
 To: assignments@ikkauto.com; Admin A (admin-a@ikkauto.com)
 Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariasa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
 Sent: Friday, 13 December, 2019 4:25:01 PM
 Attachments: Pre SKZ3588J.pdf; Pre SKZ3588J.pdf

Sur: Adm

Hi,

Please refer to the enclosed request from JusEquity Law Corporation.
 Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
 Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 FNO, Adjunct
 Singapore AUTO Claims

Tel: 8001206556 | Ext: 1002206
 Email: hor@aiq.com | www.aiq.sg

P. Zul
 T: 123 16-12-15
 V: h
 E. ✓

From: zul<zul@juseq.com.sg>
 Sent: Friday, December 13, 2019 4:08 PM
 To: Hor, Yinrul <Yinrul.Hor@aiq.com>
 Cc: 'Alfred Ng' <alfred_ng@juseq.com.sg>
 Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGV1616T AND SKZ3588J ON 13/12/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

We refer to your email today,

Our client is agreeable to appoint the following surveyor as our single joint expert.

Adrian Ling (LKK Auto Consultants Pte Ltd)

Please be informed that our client's vehicle is available for inspection at the understated workshop:-

IMPERIUM AUTOMOTIVE
 25 Kaki Bukit Road 4 #01 – 49
 Synergy@KB
 Singapore 417800
 Tel: 9748 9940 Fax: 6346 7213

Regards,

Zul
 JusEquity Law Corporation
 133 New Bridge Road #10-03
 Chinatown Point
 Singapore 058413
 Tel: 6536 9339
 Fax: 6536 5368
 E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Hor, Yinrul [mailto:Yinrul.Hor@aiq.com]
 Sent: Friday, 13 December, 2019 3:33 PM
 To: zul@juseq.com; alfred_ng@juseq.com
 Cc: Fong, Andy-SY <Andy.SY.Fong@aiq.com>; Fan, Winnie-LW <Winnie-LW.Fan@aiq.com>; Abu Kassim, Noor Mariasa <NoorMariasa.AbuKassim@aiq.com>; Azlan, Syazairdina <Syazairdina.Azlan@aiq.com>; Chan, Yoke Shi <yokeshi.chan@aiq.com>; Lim, Sheng Yang <shengyang.lim@aiq.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aiq.com>; Parthiban, Theerthan <Theerthan.Parthiban@aiq.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aiq.com>
 Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGV1616T AND SKZ3588J ON 13/12/2019



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o

anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです・閲覧には添付ファイルを開いてください・

[Click here](#) by 2019-12-20 01:33 CST to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual or entity named in the message. If you have received this email in error or simply delete it.

Secured by Freeform Encryption, Copyright © 2008-2017 Freeform, Inc. All rights reserved.

From: Yinnul Hor@sig.com
To: zul@juseq.com.sg, alfred_ng@juseq.com.sg
Cc: Andy-SY Fang@sig.com, Winnie-LW Fan@sig.com, NoorMarissa.AliuKassim@sig.com, Syazairdina Azlan@sig.com, yokeeshi.chen@sig.com, ShengYang Lim@sig.com, Aashweenjaekaur.Mithooosingh@sig.com, Theerthan Parthiban
Subject: aigenrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGV1616T AND SKZ3588J ON 13/12/2019
Date: Fri, 13 Dec 2019 07:33:26 +0000
Without Prejudice

Your Reference : JEQ/SKZ3588J/IMP (zl)
Our Reference : SGV1616T

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Raul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yit Rui (Viviane)
AIG
FNOL Adjuster 1
Singapore AUTO Claims

Tel: 8001296588 / Ext: 1002288
Yinnul.Hor@sig.com / www.sig.sg

From: zul <zul@juseq.com.sg>
Sent: Friday, December 13, 2019 3:23 PM
To: Hor, Yinnul <Yinnul.Hor@sig.com>
Cc: 'Alfred Ng' <alfred_ng@juseq.com.sg>
Subject: [EXTERNAL] ACCIDENT INVOLVING SKZ3588J AND SGV1616T ON 13.12.2019 O ref: JEQ/SKZ3588J/IMP (zl)

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Please refer to our notice of accident.

Regards,

Zul

JusEquity Law Corporation
133 New Bridge Road #10-03
Chinatown Point
Singapore 059413
Tel: 6536 9339
Fax: 6536 5368
E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail. Delete this message and you should not disseminate, distribute or copy any information contained herein.

View Received Message

This mail is associated with :

***SK23588J (75852119395G)**
[SGV1616T]

TP
OSCARS LEASING PRIVATE LIMITED
Dec 13 2019 11:00AM
[SLOW OI LIN]
Imperium Automotive - Kaki Bukit

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 17/12/2019 15:41 PM.
To LKK_HQ
CC YinruL.Hor@aig.com; Divyashni.Subramaniam@aig.com; NoorMariesa.AbuKassim@aig.com
Subject NO OI GIA REPORT

HL

Kindly be informed OI has not reported yet. OI details as below :

Name : SLOW OI LIN
Address : 73 CHISELHURST GROVE SINGAPORE 558656
Phone No. : 98389982

Thanks
Mariesa

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19022093/Ada3

19 December, 2019

SIOW OI LIN
73 CHISELHURST GROVE
SINGAPORE 558656

Dear Sirs,

**ACCIDENT INVOLVING SGV 1616T AND SKZ 3588J ON 13/12/2019 ALONG/
AT CLEMENTI ROAD**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Carlor Chan
Claims
Tel : 6841 5792
Fax: 6741 4108
Email : Jiale@lkkauto.com

*c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Dec 2019 Edit Reg		13 Dec 2019 00:00 Edit Adj Rpt	\$55,000.00 Edit Estimates	\$55,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SIOW OI LIN , ID: S0095048C, Tel: +6598389982								
Main Claimant:	OSCARS LEASING PRIVATE LIMITED , Co. Reg. No.: 201431292N								
Vehicle Reg. No.:	SKZ3588J	Date of Loss:	13/12/2019 11:00 - :59 [46 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5672081098SG	Policy/Cover Note No.:	2100437985 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGV1616T	Policy No. (Claimant):	5109910175						
		Excess:							
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (17/12/2019): NO OI GIA REPORT - AIG_SG (17/12/2019): Confirm DOA									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ3588J (5672081098SG)
[SGV1616T]
TP
OSCARS LEASING PRIVATE LIMITED
Dec 13 2019 11:00AM
[SIOW OI LIN]
Imperium Automotive - Kaki Bukit

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 11:42	General View	 Load JPG	☒
2	17/01/20 11:42	General View	 Load JPG	☒
3	17/01/20 11:42	General View	 Load JPG	☒
4	17/01/20 11:42	General View	 Load JPG	☒
5	17/01/20 11:42	General View	 Load JPG	☒
6	17/01/20 11:42	General View	 Load JPG	☒
7	17/01/20 11:42	General View	 Load JPG	☒
8	17/01/20 11:42	General View	 Load JPG	☒
9	17/01/20 11:42	General View	 Load JPG	☒
10	17/01/20 11:42	General View	 Load JPG	☒
11	17/01/20 11:42	General View	 Load JPG	☒
12	17/01/20 11:42	General View	 Load JPG	☒
13	17/01/20 11:42	General View	 Load JPG	☒
14	17/01/20 11:42	General View	 Load JPG	☒
15	17/01/20 11:42	General View	 Load JPG	☒
16	17/01/20 11:42	General View	 Load JPG	☒
17	17/01/20 11:42	General View	 Load JPG	☒
18	17/01/20 11:42	General View	 Load JPG	☒
19	17/01/20 11:42	General View	 Load JPG	☒
20	17/01/20 11:42	General View	 Load JPG	☒
21	17/01/20 11:42	General View	 Load JPG	☒
22	17/01/20 11:42	General View	 Load JPG	☒
23	17/01/20 11:42	General View	 Load JPG	☒
24	17/01/20 11:42	General View	 Load JPG	☒
25	17/01/20 11:42	General View	 Load JPG	☒
26	17/01/20 11:42	General View	 Load JPG	☒
27	17/01/20 11:42	General View	 Load JPG	☒
28	17/01/20 11:42	General View	 Load JPG	☒
29	17/01/20 11:42	General View	 Load JPG	☒
30	17/01/20 11:42	General View	 Load JPG	☒
31	17/01/20 11:42	General View	 Load JPG	☒
32	17/01/20 11:42	General View	 Load JPG	☒
33	17/01/20 11:42	Reinspection Photo	 Load JPG	☒
34	17/01/20 11:42	Reinspection Photo	 Load JPG	☒
35	17/01/20 11:42	Reinspection Photo	 Load JPG	☒
36	17/01/20 11:42			

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	17/01/20 11:42	Reinspection Photo		Load JPG	☒
45	17/01/20 11:42	Reinspection Photo		Load JPG	☒
46	17/01/20 11:42	Reinspection Photo		Load JPG	☒
47	17/01/20 11:42	Reinspection Photo		Load JPG	☒
48	17/01/20 11:42	Reinspection Photo		Load JPG	☒
49	17/01/20 11:42	Reinspection Photo		Load JPG	☒
50	17/01/20 11:42	Reinspection Photo		Load JPG	☒
51	17/01/20 11:42	Reinspection Photo		Load JPG	☒
52	17/01/20 11:42	Reinspection Photo		Load JPG	☒
53	17/01/20 11:42	Reinspection Photo		Load JPG	☒
54	17/01/20 11:42	Reinspection Photo		Load JPG	☒
55	17/01/20 11:42	Reinspection Photo		Load JPG	☒
56	17/01/20 11:42	Reinspection Photo		Load JPG	☒
57	17/01/20 11:42	Reinspection Photo		Load JPG	☒
58	17/01/20 11:42	Reinspection Photo		Load JPG	☒
59	17/01/20 11:42	Reinspection Photo		Load JPG	☒
60	17/01/20 11:42	Reinspection Photo		Load JPG	☒
61	17/01/20 11:42	Reinspection Photo		Load JPG	☒
62	17/01/20 11:42	Reinspection Photo		Load JPG	☒
63	17/01/20 11:42	Reinspection Photo		Load JPG	☒
64	17/01/20 11:42	Reinspection Photo		Load JPG	☒
65	17/01/20 11:42	Reinspection Photo		Load JPG	☒
66	17/01/20 11:42	Reinspection Photo		Load JPG	☒
67	17/01/20 11:42	Reinspection Photo		Load JPG	☒
68	17/01/20 11:42	Reinspection Photo		Load JPG	☒
69	17/01/20 11:42	Reinspection Photo		Load JPG	☒
70	17/01/20 11:42	Reinspection Photo		Load JPG	☒
71	17/01/20 11:42	Reinspection Photo		Load JPG	☒
72	17/01/20 11:42	Reinspection Photo		Load JPG	☒
73	17/01/20 11:42	Reinspection Photo		Load JPG	☒
74	17/01/20 11:42	Reinspection Photo		Load JPG	☒
75	17/01/20 11:42	Reinspection Photo		Load JPG	☒
76	17/01/20 11:42	Reinspection Photo		Load JPG	☒
77	17/01/20 11:42	Reinspection Photo		Load JPG	☒
78	17/01/20 11:42	Reinspection Photo		Load JPG	☒
79	17/01/20 11:42	Reinspection Photo		Load JPG	☒
80	17/01/20 11:42	Reinspection Photo		Load JPG	☒
81	17/01/20 11:42	Reinspection Photo		Load JPG	☒
82	17/01				

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/12/19 15:11	ACKNOWLEDGEMENT EMAIL TO AIG DD 16.12.19		Load PDF	
2	16/12/19 15:11	EMAIL FROM AIG DD 13.12.19		Load PDF	
3	16/12/19 15:11	NOTIFICATION FROM WORKSHOP +TP GIA REPORT		Load PDF	
4	18/12/19 15:40	TP GIA REPORT		Load PDF	
5	19/12/19 09:03	Non reporting letter		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	09/01/20 08:59	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022093/ADA3Q2

Date: 13/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100437985
 Claimant: SKZ3588J Insured Vehicle No: SGV1616T
 Vehicle No: SKZ3588J Nature of Claim: TP Claim No: 5672081098SG
 Date of Loss: 13/12/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ3588J
 Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1690154
 Reg. Date: 20/01/2016 (Man. Year: 2015) Chassis No: JTDGG20W40J003505
 Colour: Silver Odometer: 76229 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Firestone 6 mm Rear Left Side: Firestone 6 mm
 Front Right Side: Firestone 6 mm Rear Right Side: Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,385.55	4,113.23	6,272.32	60.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,140.00	1,610.00	42.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,135.55	6,253.23	7,882.32	55.76
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	14,135.55	5,000.00	9,135.55	64.63
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/12/2019
 Date Inspected: 16/12/2019 Inspected At: Imperium Automotive - Kaki Bukit (HQ)
 25 Kaki Bukit Road 4, #01-49
 Synergy@KB
 Singapore 417800
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,557.45 FL	*1,175.90 FL
2	2		*REAR TAILGATE HINGE -RH/LH	Not Necessary	130.40 FL	*- FL
3	2		*REAR TAILGATE DAMPER-RH/LH	Not Necessary	421.82 FL	*- FL
4	2		*REAR TAILGATE LAMP -RH/LH	Not Necessary	969.30 FL	*- FL
5	1		*REAR TAILGATE STOPPER	Not Necessary	12.90 FL	*- FL
6	1		*REAR TAILGATE RUBBER	Cut	285.53 FL	*285.53 FL
7	1		*REAR TAILGATE LOCK	Damaged	497.27 FL	*497.27 FL
8	1		*REAR TAILGATE LOCK CATCH	Not Necessary	46.50 FL	*- FL
9	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	42.50 FL	*- FL
10	1		*REAR TAILGATE INNER TRIM	Cracked	485.51 FL	*485.51 FL
11	1		*REAR TAILGATE WIPER BLADE	Not Necessary	48.10 FL	*- FL
12	1		*REAR TAILGATE WIPER ARM	Not Necessary	70.50 FL	*- FL
13	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	615.10 FL	*- FL
14	1		*REAR TAILGATE EMBLEM LOGO	Necessary	68.50 FL	*68.50 FL
15	1		*REAR TAILGATE EMBLEM ELEGANCE	Necessary	58.70 FL	*58.70 FL
16	1		*REAR TAILGATE EMBLEM VALVE MATIC	Necessary	47.20 FL	*47.20 FL
17	2		*REAR NUMBER PLATE LAMP	Not Necessary	97.30 FL	*- FL
18	1		*REAR TAILGATE OPENING CONTROL SWITCH	Cracked	165.20 FL	*165.20 FL
19	1		*REAR TAILGATE OUTER CHROME MOULDING	Not Necessary	255.10 FL	*- FL
20	2		*REAR TAILLAMP -RH/LH	Not Necessary	1,145.20 FL	*- FL
21	4		*REAR TAILLAMP SIDE HOLDER CLIP	Not Necessary	31.20 FL	*- FL
22	2		*REAR TAILLAMP PANEL HOUSING -RH/LH	Not Necessary	390.00 FL	*- FL
23	1		*REAR BUMPER	Deformed	735.98 FL	*605.00 FL
24	4		*REAR BUMPER CLIP	Necessary	18.00 FL	*18.00 FL
25	2		*REAR BUMPER REFLECTOR -RH/LH	Not Necessary	137.10 FL	*- FL
26	2		*REAR BUMPER BRACKET -RH/LH	Dented	137.10 FL	*137.10 FL
27	2		*REAR BUMPER SIDE RETAINER -RH/LH	Necessary	128.86 FL	*128.86 FL
28	1		*REAR END PANEL	Dented	575.10 FL	*575.10 FL
29	1		*REAR END PANEL GARNISH	Deformed	248.97 FL	*248.97 FL
30	1		*REAR SPARE WHEEL CARRIER	Damaged	335.10 FL	*335.10 FL
31	1		*REAR FLOOR PANEL	Repair	618.70 FL	*- FL
32	1		*REAR FLOOR CARDBOARD HOLDER GARNISH	Not Necessary	216.50 FL	*- FL
33	1		*REAR FLOOR PANEL CARDBOARD	Deformed	265.70 FL	*265.70 FL
34	2		*REAR FLOOR PANEL SIDE BOARD -RH/LH	Not Necessary	310.10 FL	*- FL
35	2		*REAR FENDER AIR VENT -RH/LH	Not Necessary	297.00 FL	*- FL
36	2		*REAR FENDER INNER TRIM -RH/LH	Not Necessary	1,215.24 FL	*- FL
37	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
38	1		*SET REAR REVERSE CAMERA	Not Necessary	400.00 FS	*- FS
39	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR INNER TRIM CLIP	Necessary	65.00 FS	*30.00 FS
41	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	13,555.73	5,387.64
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,170.18	1,274.41
Total Parts (\$\$)	10,385.55	4,113.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,CUT,WELD ,REMOVE AND REPLACING ABOVE PARTS	New	1,500.00	900.00
2	TO RESPRAY PAINTING AND ETC	New	1,500.00	900.00
3	TO CHECKING REAR WIRING	New	50.00	30.00
4	TO REMOVE,REFIX REAR WINDSCREEN	New	200.00	120.00
5	TO TRANSFER REAR TAILGATE PARTS	New	120.00	80.00
6	TO REMOVE,REFIX CUSHION AND INNER TRIM	New	180.00	60.00
7	TO REFIX & REPLACE REVERSE SENSOR	New	200.00	50.00
Gross Labour Cost (S\$)			3,750.00	2,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >