



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107508

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 01/11/2021
Reference CC6/FCI19022095/Qea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. TBG 2721
Insured Veh. SHA 2968U
Claim No. D19007069MFSH
Policy No. D-18088936MFSH
Accident Date 01/11/2019
Inspection Date 13/12/2019

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC6/FCI19022095/Qea3q2 Date: 01/11/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2968U	Veh. Inspected	TBG 2721
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D19007069MFSH	Excess (\$)	0.00
Assign From	VIC	Assign Date	13/12/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA FZ150I	c.c	149
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	PMYKG0250A0011395	Colour	RED
Odometer	679889 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	90/80-17	CORSA	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80-17	CORSA	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/11/2019	Inspection Date	13/12/2019
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. TBG 2721

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	BENT	120.00	120.00
1	SET HANDLE BAR GRIP	SERVICEABLE	40.00	-
1	HANDLE BAR TOP BRACKET	BENT	45.00	45.00
2	HANDLE BAR BALANCER @\$12.00	SCRATCHED	24.00	24.00
1	CLUTCH LEVER	BROKEN	22.00	22.00
1	CLUTCH CABLE	SERVICEABLE	45.00	-
1	BRAKE LEVER	SCRATCHED	22.00	22.00
1	BRAKE CABLE	SERVICEABLE	45.00	-
2	MIRROR ASSY @\$65.00	BROKEN	130.00	130.00
1	SPEEDOMETER UNIT	CRUMPLED	280.00	280.00
1	SPEEDOMETER UNIT BRACKET	BENT	35.00	35.00
1	HEADLAMP	CRUMPLED	160.00	160.00
1	HEADLAMP STAY	CRACKED	35.00	35.00
1	HEADLAMP STAY COWLING	SERVICEABLE	65.00	-
2	SIGNAL LAMPS @\$25.00	CRACKED	50.00	50.00
2	SIGNAL LAMP SIDE GARNISH @\$65.00	CRACKED	130.00	130.00
1	HORN	BENT	25.00	25.00
1	FRONT VISOR	MISSING	45.00	45.00
1	FRONT MUDGUARD	CRUMPLED	45.00	45.00
2	FRONT FORK @\$180.0	BENT	360.00	360.00
1	FRONT FORK CENTRE BRACKET	BENT	45.00	45.00
1	FRONT FORK TOP BRACKET	BENT	45.00	45.00
1	FRONT FORK CENTRE SHAFT	BENT	50.00	50.00
1	FRONT RIM	BENT	220.00	220.00
1	RADIATOR	BENT	350.00	250.00
2	FRONT FAIRING @\$220.00	N/S CRACKED	440.00	220.00
1	FUEL TANK	DENTED	380.00	380.00
1	REAR L/H SIGNAL LAMP	CRACKED	35.00	35.00
1	FOOTREST L/H	SCRATCHED	25.00	25.00
1	REAR SHIFT GEAR LEVER	SCRATCHED	45.00	45.00
1	REAR FOOTREST L/H	SERVICEABLE	25.00	-

Report Ref No. CC6/FCI19022095/Qea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR L/H FAIRING	CRACKED	120.00	120.00
1	REAR RIM	SERVICEABLE	220.00	-
1	SET STICKER	NECESSARY	60.00	60.00
	LESS 10% DISCOUNT		-378.30	-302.30
			3,404.70	2,720.70
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (SN)	NOT NECESSARY	150.00	-
			150.00	-
	<u>LABOUR</u>			
	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC.		500.00	300.00
	TO APPLY UNDERSEAL.	NOT NECESSARY	50.00	-
	TO RESPRAY AFFECTED PART.		350.00	150.00
	TO UNDERGO WHEEL ALIGNMENT .		60.00	30.00
	TRANSPORTATION CHARGES-TOWING.		40.00	40.00
	TO CHECK WIRING .		30.00	20.00
			1,030.00	540.00
	GRAND TOTAL		4,584.70	3,260.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00

Report Ref No. CC6/FCI19022095/Qea3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. TBG 2721

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. TBG 2721

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

