

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Our Ref: EST418/19/TP

Your Ref: TP claim against SHA2968U

5-Dec-19

## MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

### Attn: Motor Claims Department

Dear Sir/Ms,

### Re: Estimated cost of repair to Yamaha FZ150i no: TBG2721

Date of accident: 01-11-2019

#### Parts supply:

1 pc Handle bar	✓ BT	SS\$	120.00
1 set Handle bar grip	X SVC		40.00
1 pc Handle bar top bracket	X SVC		45.00
2 pcs Handle bar balancer @\$12.00	✓ SCH		24.00
1 pc Clutch lever	✓ BR		22.00
1 pc Clutch cable	X SVC		45.00
1 pc Brake lever	✓ SCH		22.00
1 pc Brake cable	X SVC		45.00
2 pcs Mirror assy @\$65.00	✓ BR		130.00
1 pc Speedometer unit	✓ CRU.		280.00
1 pc Speedometer unit bracket	✓ BT		35.00
1 pc Headlamp	✓ CRU.		160.00
1 pc Headlamp stay	✓ CRA		35.00
1 pc Headlamp stay cowling	X		65.00
2 pcs Signal lamps @\$25.00	✓ CRA		50.00
2 pcs Signal lamp side garnish @\$65.00	✓ CRA		130.00
1 pc Horn	✓ BT		25.00
1 pc Front visor	✓ MIS		45.00
1 pc Front mudguard	✓ CRU.		45.00
2 pcs Front fork @\$180.00	✓ BT		360.00
1 pc Front fork centre bracket	? - photo		45.00
1 pc Front fork top bracket	? - photo		45.00
1 pc Front fork centre shaft	? - photo		50.00
1 pc Front rim	✓ BT		220.00
1 pc Radiator	? - photo		350.00
2 pcs Front fairing @\$220.00	LH ✓ CRA		440.00
1 pc Fuel tank	✓ PR		380.00
1 pc Rear L/h signal lamp	✓ CRA		35.00
1 pc Footrest L/h	✓ SCH		25.00
1 pc Rear shift gear lever	✓ SCH		45.00
1 pc Rear footrest L/h	X SVC		25.00
1 pc Rear L/h fairing	✓ CRA		120.00
1 pc Rear rim	X SVC		220.00
1 set Sticker	✓ NEC.		60.00
			3,783.00

## ESTIMATE

# 振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883  
Tel: 6747-4810 Fax: 6745-5018  
cmmotors@singnet.com.sg

**Re: Estimated cost of repair to Yamaha FZ150i no: TBG2721**

Date of accident: 01-11-2019

Parts supply:

Balance b/f:

S\$	3,783.00
Less 10%:	<u>(378.30)</u>
	3,404.70

S/Nett Items

1 pc Front tyre (S/Nett) ?

150.00

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

500.00 300

To apply underseal

50.00 X

To respray affected part.

350.00 150

To undergo wheel alignment

60.00 30

Transportation charges - Towing.

40.00 / Nec.

To check wirings.

30.00 20

S\$ 4,206.40

Repair day - 4 days

Sun Pin (Uke)

13/12/2019.

TP without prejudice.

8661 2627.

Sunpin@lkkauto.com

Lump Sum

After paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Log Card.

Road tax

Insurance Cert

Driving license.

IC

WP